

HYDROGEOLOGICAL ASSESSMENT
OF THE
CLOSED COBOCONK LANDFILL

Report Prepared for:
Waste Management Branch

Report prepared by:
Gartner Lee Limited

October 1989
REPRINTED
March 1990



Copyright: Queen's Printer for Ontario, 1989
This publication may be reproduced for non-commercial purposes
with appropriate attribution.

DISCLAIMER

This report was prepared for the Ontario Ministry of the Environment as part of a ministry-funded project. The views and ideas expressed in this report are those of the author and do not necessarily reflect the views and policies of the Ministry of the Environment, nor does mention of trade names or commercial products constitute endorsement or recommendation for use.

**TABLE OF CONTENTS**

	<u>PAGE</u>
EXECUTIVE SUMMARY	i
1.0 INTRODUCTION	1
2.0 BACKGROUND AND LANDFILL HISTORY	3
3.0 PHYSICAL SETTING	6
4.0 GEOLOGY	13
5.0 WATER BUDGET	15
6.0 GROUND WATER USE	17
7.0 GROUND WATER FLOW	19
8.0 WATER QUALITY IN GROUND WATER MONITORS	25
9.0 WATER QUALITY IN RESIDENTIAL WELLS	29
11.0 SURFACE WATER QUALITY	33
12.0 LANDFILL GAS	35
13.0 CONCLUSIONS	37
14.0 RECOMMENDATIONS	39
15.0 SELECTED REFERENCES	40

LIST OF FIGURES

FIGURE 1 SITE LOCATION PLAN	4
FIGURE 2 1969 AERIAL PHOTOGRAPH	7
FIGURE 3 1978 AERIAL PHOTOGRAPH	8
FIGURE 4 1987 AERIAL PHOTOGRAPH	9
FIGURE 5 CROSS-SECTIONS A-A' AND B-B'	11
FIGURE 6 SITE PLAN	12
FIGURE 7 MEAN MONTHLY PRECIPITATION	16
FIGURE 8 ACTUAL WATER BALANCE	16
FIGURE 9 WATER TABLE ELEVATIONS, AUGUST 25, 1988	20
FIGURE 10 WATER TABLE ELEVATIONS, NOVEMBER 11, 1988	21



LIST OF TABLES

	<u>PAGE</u>
TABLE 1 WATER BALANCE CALCULATION	16
TABLE 2 SUMMARY OF HYDRAULIC CONDUCTIVITIES OF THE LIMESTONE BEDROCK BASED ON SLUG TEST RESULTS	24
TABLE 3 SUMMARY OF WATER QUALITY IN GROUND WATER MONITORS	26
TABLE 4 DRINKING WATER OBJECTIVES EXCEEDANCES	28
TABLE 5 SUMMARY OF WATER QUALITY IN RESIDENTIAL WELLS	30
TABLE 6 SUMMARY OF SURFACE WATER QUALITY	34

APPENDICES

APPENDIX I	-	MOE FILE INFORMATION
APPENDIX II	-	MOE COMPUTERIZED WATER WELL RECORDS
	-	MOE ORIGINAL WATER WELL RECORDS
	-	GLL WATER WELL RECONNAISSANCE SURVEY FORMS
APPENDIX III	-	BOREHOLE LOGS
	-	HAND AUGER BOREHOLE LOGS
	-	MONITOR DETAILS SUMMARY
	-	SLUG TEST ANALYSIS PLOTS
APPENDIX IV	-	ROUTINE WATER CHEMISTRY ANALYSES - AUGUST 1988 SAMPLES
		ROUTINE WATER CHEMISTRY ANALYSES - NOVEMBER 1988 SAMPLES
		VOLATILE ORGANIC ANALYSES OF LEACHATE (MONITOR 4-I)
		PHENOL ANALYSES OF LEACHATE (MONITORS 2-II, 3-II, 4-I)
		HEAVY METAL ANALYSES OF LEACHATE (MONITOR 4-I)



EXECUTIVE SUMMARY

The closed Coboconk Landfill is a small (0.5 hectare) landfill which was owned by the Township of Sommerville and was closed in 1974. The landfill was operated for most of its life as an open-face dump. Refuse was dumped off a bedrock scarp onto a lower area and burning of refuse was carried out on a regular basis.

The site is located on a flat lying, poorly drained, limestone plain. The refuse was placed directly on top of fractured limestone bedrock which forms the most important water supply aquifer for residents in the area. The nearest surface water courses to the landfill are the Gull River, 500 m to the west and a drainage ditch in the bottom of the Cedarhurst Quarry, 400 m to the north.

The results of this hydrogeological investigation indicate that landfill leachate presently has negligible impact on ground water quality in the limestone aquifer. The leachate tested in the study has exceptionally low concentrations compared to other Ontario landfills. This is probably due to the small size of the landfill, the age of the waste, and the fact that most of the refuse was burned. Dilution of leachate with clean ground water flowing beneath the landfill is also occurring. There are no detectable impacts on local residential wells related to leachate effects. The reasons for this are probably the dilute nature of the leachate, and additional dilution and attenuation along the ground water flow path. Based on our understanding of the landfill history and ground water flow system there is no reason to expect that leachate impacts will become worse in the future.

No leachate impacts on surface water quality were detected in this study. No methane gas concentrations were detected in the landfill and off-site methane gas migration appears highly unlikely based on our understanding of the hydrogeological setting.



Based on the findings of this hydrogeological assessment we have recommended that no remedial measures are required to contain or control leachate or methane gas at this site. Furthermore, there is no apparent need for monitoring of ground water, surface water or methane gas.



1.0 INTRODUCTION

Gartner Lee Limited (GLL) was retained by the Ontario Ministry of the Environment (MOE) (P.O. #A-05690) in August 1988 to carry out a hydrogeological assessment of the closed Coboconk Landfill.

As outlined in the MOE Request for Proposals, this hydrogeological assessment represents part of Phase III of a MOE program designed to investigate and monitor all active and closed waste disposal sites in the Province. The aim of this program is to ensure that all pertinent information regarding waste disposal sites is available for the definition of both existing impacts and the potential for future impacts on humans or the environment. Once existing or potential impacts have been identified, remedial options can be investigated and implemented where necessary.

The program has been subdivided into four separate phases:

- PHASE I: the creation and continual updating and verification of an inventory listing all active and closed waste disposal sites in the Province;
- PHASE II: preliminary file and field investigations to classify and establish a priority for further investigation;
- PHASE III: investigations and monitoring to assess site hydrogeology as well as surface and ground water contamination potential at selected sites;
- PHASE IV: investigations of remedial options at sites identified during Phase III.

The impact assessments and identification of the contamination problems related to landfills involves both surface and ground water investigations. An accurate definition



of site hydrogeology is necessary due to the Ministry's concern for the potential for hidden problems which may be affecting ground water resources.

The Phase III study described herein forms the basis for determining whether or not detailed investigations of remedial options are required at this site during Phase IV of the program.

The purpose of this Phase III study on the closed Coboconk Landfill is to define any impacts of risks the site may pose to human health and safety or the environment and to recommend any remedial measures or additional work necessary to remove or minimize such impacts or risks.

The four main objectives of this Phase III investigation are as follows:

- a) to assess any existing or potential future landfill leachate impacts on ground water and the local aquifers;
- b) to assess any existing or potential future landfill leachate impacts on surface water;
- c) to assess any existing or potential future landfill gas impacts;
- d) to determine the need for site improvements such as remedial measures or monitoring.



2.0 BACKGROUND AND LANDFILL HISTORY

The closed Coboconk Landfill is located on parts of Lots 35 and 36 of Concession Fronting on River, Township of Somerville, Victoria County, Ontario. The site is about 0.4 km southeast of the Village of Coboconk as shown on Figure 1. The area of refuse disposal is about 0.5 hectares.

Information on the history of this site was obtained from a review of MOE files. Photocopies of pertinent documents are included in Appendix I for reference.

The landfill site was owned and operated by the Township of Somerville. The date when landfilling commenced is not known but review of historical aerial photographs indicate that the site was well established in 1969. The site received a Provisional Certificate of Approval for a Waste Disposal Site (No. 321603) in November 1971. The site was closed in August 1974 due to an unsuitable hydrogeological setting and a lack of available cover material on-site.

The property on which the landfill is located was sold to a Mr. G. Mitchell in 1986 and was resold to Mr. R. Boyce in 1987. We understand that both Mr. Mitchell and Mr. Boyce were aware of the waste disposal site prior to purchasing the property.

The landfill received wastes from Somerville Township, the Village of Coboconk, and Bexley Township. It serviced a population of about 1,000 to 1,300 people and is reported to have received about 2.5 tons/day of wastes.

The composition of the wastes are estimated to be as follows:

- 60% domestic
- 25% commercial
- 5% industrial
- 4% agricultural
- 6% other




Figure 1
SITE LOCATION MAP

SCALE 1:50,000

GLL PROJECT 88-237





On some of the earlier documents the 5% industrial listed above is broken into 3% industrial and 2% hazardous wastes. However, a January 1987 letter from the Peterborough District MOE office revised this classification as shown above based on information received from the Township Reeve.

The landfill was operated as an open face dump for most of its life. Refuse was dumped off the north face of a 3 m high bedrock scarp into a lower area and filling probably proceeded in a northerly manner. Refuse was burned on a regular basis. Covering of refuse was reportedly carried out every two weeks, however lack cover material on-site probably made this task very difficult. Refuse is still visible along the north face.



3.0 PHYSICAL SETTING

The closed Coboconk Landfill is located in a rural, uplands area about 0.4 km southeast of the Village of Coboconk.

The area is described as a limestone plain by Chapman and Putnam, (1972). The main topographic relief in the area is the Gull River Valley which has cut about 20 m into the limestone plain. The Gull River is located about 0.5 km west of the landfill at its' closest point and flows in a southerly direction from Shadow Lake to Balsam Lake.

The Cedarhurst Limestone Quarry, which is located 0.3 km north of the landfill, also provides about 15 m of topographic relief. There is a drainage ditch in the bottom of the quarry which flows westward towards the river.

No flowing streams were observed during site visits on the landfill property. The area is poorly drained and bogs and swamps are present nearby.

Historical aerial photographs of the site from 1969, 1978 and 1987 were stereoscopically interpreted to provide a terrain analysis of the area. These aerial photographs are presented in Figures 2, 3 and 4.

Figure 2 illustrates that the landfill was well established in 1969. Quarries are apparent to the north and west of the site and bogs or swamps are present to the south and east. A bedrock scarp is also apparent just west of the landfill. No vegetation is established on the landfill.

Figure 3 shows the site in 1978, four years after it closed. Some vegetation is established on the landfill but most of the area appears largely unchanged from 1969. Both quarries are unchanged which suggests they were largely inactive during this period.

Figure 4 shows the site in 1987, thirteen years after closure. The landfill is covered with shrubs, trees and grasses. The access road into the site is partially overgrown. A new



Figure 2

Closed Coboconk Waste Disposal Site

1969 Aerial Photograph

Scale 1:5,000 approx.

Project 88-237






Figure 3
Closed Coboconk Waste Disposal Site
1978 Aerial Photograph

Scale 1:5,000 approx.

Project 88-237



Gartner
Lee




Figure 4

Closed Coboconk Waste Disposal Site

1987 Aerial Photograph

Scale 1:5,000 approx.

Project 88-237




Gartner
Lee




house has been built on 7th Line Road about 180 m northwest of the landfill. Cedarhurst Quarry to the north has expanded and a large area of land has been cleared presumably for additional quarrying in the future. The quarry to the west remains unchanged from conditions in 1969.


Figure 5 presents two cross-sections which illustrate how the landfill is related to the major topographic features in the area. Section A-A' runs east-west and Section B-B' runs north-south as shown on the site plan, Figure 6. Section A-A' shows how the land surface and the inferred water table slope eastward to the Gull River. Section B-B' illustrates how the grades in the Cedarhurst Limestone Quarry relate to the landfill and locally affect the water table elevation. The bedrock scarp at the south end of the landfill is also apparent on Section B-B'.



EAST







Legend

- PROPERTY BOUNDARY
- ESTIMATED EXTENT OF REFUSE
- BH3 GLL BOREHOLE AND GROUND WATER MONITOR LOCATION
- H7(5011) DOMESTIC WELL SAMPLING LOCATION WITH MOE WELL RECORD NO. IN BRACKETS
- RI SURFACE WATER SAMPLING LOCATION
- AH5 HAND AUGER BOREHOLE AND COMBUSTIBLE GAS TESTING LOCATION
- AL CROSS-SECTION LINE

AERIAL PHOTOGRAPHY - 1978

SCALE 1:2000 approx

SITE PLAN

Figure
6

CLOSED COBOCONK LANDFILL
HYDROGEOLOGICAL ASSESSMENT
for the
Ministry of the Environment

GILL PROJECT #A-277



Cartier
Log



4.0 GEOLOGY

According to geological mapping (Liberty, 1969) the bedrock at this site consists of the Middle Ordovician Black River Group. Near surface the Bobcaygeon Formation lower member occurs. This is a grey fine grained argillaceous limestone. Below this occurs the lithographic limestones of the Gull River Formation. The contact between these two horizontally bedded limestone formations reportedly occurs at surface just west of the site.

Excellent vertical exposures of the bedrock are provided in the quarry north of the site and in the Highway 35 roadcut northwest of the site. Horizontal and vertical fractures are present in the rock as well as the horizontal bedding planes. Numerous flat lying limestone outcrops are visible at the landfill site, particularly on the south and west sides.

Quaternary geological mapping by Finamore and Bajc (1983) indicates that the area of the landfill is mapped as bedrock-drift complex. This is a discontinuous veneer of glacial drift which in places is sufficiently thick to subdue bedrock topography. This drift is very thin at the landfill site.

Seven boreholes were drilled at the site between August 15th and 19th, 1988, using a track mounted CME 55 drill rig. Boreholes were advanced using casing, NQ coring bit and/or tri-cone depending on the nature of the borehole. At three locations (BH1, BH2, BH3) two boreholes were drilled in order to permit installation of both deep ($\pm 10\text{m}$) ground water monitors (1-I, 2-I, 3-I) and shallow ($\pm 5\text{m}$) ground water monitors (1-II, 2-II, 3-II). The deep boreholes were cored and the shallow monitors were tri-coned. Water was trucked from the Gull River for drilling purposes. Only one borehole was drilled and one ground water monitor was installed at location BH4. The cored samples were geologically logged by GLL's supervising geologist. Geologic borehole logs are presented in Appendix III. Borehole locations are shown on Figure 6.

Limestone bedrock was encountered at surface in boreholes 1 and 2. Borehole 3 encountered 0.3 m of sandy silt topsoil above the limestone bedrock. Borehole 4



Limestone bedrock was encountered at surface in boreholes 1 and 2. Borehole 3 encountered 0.3 m of sandy silt topsoil above the limestone bedrock. Borehole 4 encountered 3.5 m of refuse and fill above the bedrock. All boreholes were terminated in limestone bedrock.



5.0 WATER BUDGET

Long term meteorological data for Coboconk meteorological station have been reviewed to prepare a water budget for this site.

The mean annual precipitation at Coboconk is 909 mm per year, based on 11 years of meteorological data from 1970 to 1980. There is some variation, from year to year, in the total annual precipitation (standard deviation of 108 mm about the mean value). The distribution of the precipitation varies from month to month, as shown on Figure 7, for a normal year.

A water balance has been prepared using the method described in Thornthwaite and Mather (1957), as shown on Table 1. The mean annual evapotranspiration is estimated to be 537 mm, based on an assumed soil moisture storage of 100 mm. The mean annual water surplus is calculated to be 372 mm.

The distribution of the surplus water on a monthly basis through a normal year is shown on Figure 8. It shows that a significant surplus of 440 mm occurs during the autumn, winter and spring months and a deficit of 68 mm occurs during the summer.

The water surplus comprises both the surface runoff and infiltration components of the water balance. Due to the relatively flat topography and presence of fractured limestone near surface at this site it seems likely that most of the water surplus infiltrates.

TABLE 1

WATER BALANCE CALCULATIONS
FOR
COBOCONK, ONTARIO
UNDER AVERAGE CONDITIONS

MONTH	MEAN TEMP. °C	MEAN PRECIPI- TATION mm	ACTUAL EVAPO- TRANSPIRATION mm	ACTUAL WATER BALANCE mm
JAN	-9.2	73.7	0	74
FEB	-8.6	62.5	0	63
MAR	-2.9	68.9	0	69
APR	5.3	73.4	29	44
MAY	11.9	67.6	77	-9
JUN	17.0	86.4	107	-21
JUL	19.4	79.6	107	-27
AUG	18.4	85.6	97	-11
SEP	14.3	77.6	75	2
OCT	8.3	65.4	39	26
NOV	1.7	92.8	6	86
DEC	-6.3	75.9	0	76
YEAR		909	537	372

FIGURE 7





FIGURE 8





6.0 GROUND WATER USE

The following tasks were completed in order to assess ground water use in the vicinity of the closed Coboconk Landfill:

- a) MOE Water Well Log Computer Printouts for the area were reviewed and plotted (see Appendix II).
- b) Copies of the original MOE water well logs for Concession RFC lots 33, 34, 35 and 36 were obtained, reviewed and plotted (see Appendix II).
- c) The Victoria County Official Plan Volume 1 Physical Base report was reviewed.
- d) A water well survey involving resident interviews at eight homes near the landfill was carried out in August, 1988 (see Appendix II).

The water wells (H1 to H8) included in the survey are plotted on Figure 6. MOE well numbers are also provided where possible. There is some uncertainty regarding the locations of some of the wells recorded by the MOE due to the poor quality of the well location maps provided by the drillers.

The Victoria County Official Plan indicates that the Village of Coboconk uses individual wells for water supply. Sewage works consist of holding tanks and septic tank disposal systems. According to this report about 84% of the wells in this area are completed in bedrock and the rest in overburden. The limestone bedrock is geologically mapped as the Bobcaygeon and Gull River Formations and is by far the most important aquifer. Most wells obtain good yields and the limestone aquifer is an important water supply resource for future development in Coboconk and the surrounding area.

This assessment was confirmed during a detailed review of the thirteen original water well records for Concession RFC Lots 33, 34, 35 and 36. All the wells are completed in the limestone bedrock except for one shallow overburden well. Well depths range from



6 to 35 m with an average depth of 20 m. Reported static water levels range from 1 to 17 m with an average level of 7 m. Specific capacities vary between .01 and 0.5 L/s/m with an average of about 0.17 L/s/m, which confirms that yields are adequate for residential purposes.

Three of the residents which were interviewed reported problems with their wells. Well H7 was partially depleted of water about four years ago apparently due to ground water interference effects from expansion of the Cedarhurst Quarry. A new well will reportedly be drilled soon. Well H8 apparently has been flooded in the past by spring runoff. Well H6 was apparently contaminated with petroleum from a leaking tank at the Texaco Station on Highway 35. Water was brought in for the resident's use for three years, during which time the well was pumped out and apparently rehabilitated.



7.0 GROUND WATER FLOW

Ground water levels were measured in the on-site monitors on five occasions in August and on one occasion in November 1988. These results and geodetic water level elevations calculated from survey information are presented in Appendix III.

The water table measured in the monitors at the site generally occurred between 2 and 7 m below grade in August, depending upon location. The summer of 1988 was exceptionally hot and dry which probably accounts for the deep water levels at monitor locations 2, 3 and 4 in August. The water table in November, after a period of heavy rain, was between 0 and 3.5 m below grade, depending upon location.

Water level rises in the order of 0.8 to 5.5 m occurred in the various monitors between August and November. The smallest changes occurred at borehole 1. Highly permeable fractures are present in the upper 2 m of borehole 1 as evidenced by excessive water losses during coring of the bedrock at this location. These permeable fractures probably control water levels at borehole 1 within a narrow range by rapidly draining off any excess infiltration.

Water levels in all the other monitors at borehole locations 2, 3 and 4 rose by 3.5 m or more between August and November 1988. The magnitude of these water level rises is due to the relatively low fracture porosity of the limestone bedrock. For instance, if the effective fracture porosity was 1% then a 10 mm infiltration event transferred to the water table could cause a 1 m rise in ground water levels.

Figures 9 and 10 present water table elevation maps for August 25 and November 11, 1988 based on water level elevations in on-site ground water monitors. A surveyed water level elevation in the Cedarhurst Quarry drainage ditch and an estimated water level for the Gull River (estimated from 1:50,000 topographic map) are also provided on Figures 9 and 10 to illustrate how ground water elevations at the landfill site relate to the regional ground water flow system.



Legend

- PROPERTY BOUNDARY
- ▨ ESTIMATED EXTENT OF REFUSE
- 276.61 WATER TABLE ELEVATION (mASL) MEASURED AUG. 25, 1988
- ➔ INFERRED GROUND WATER FLOW DIRECTION

AERIAL PHOTOGRAPHY - 1978


SCALE 1:2000


WATER TABLE
ELEVATIONS
(Aug. 25, 1988)

Figure
9

CLOSED COBOCONK LANDFILL
HYDROGEOLOGICAL ASSESSMENT
for the
Ministry of the Environment

GLL PROJECT 88-237





Legend

-  PROPERTY BOUNDARY
-  ESTIMATED EXTENT OF REFUSE
-  276.61 WATER TABLE ELEVATION (mASL) MEASURED NOV. 11, 1988
-  INFERRED GROUND WATER FLOW DIRECTION

AERIAL PHOTOGRAPHY - 1978


SCALE 1:2000

WATER TABLE
ELEVATIONS
(Nov. 11, 1988)

Figure
10

CLOSED COBOCOOK LANDFILL
HYDROGEOLOGICAL ASSESSMENT
for the
Ministry of the Environment

2000-01-01





Ground water flow was to the north-northwest on both dates, in spite of the large seasonal changes in water levels. Flow to the north-northwest suggests that ground water flow below the landfill is influenced by the dewatering effect of the Cedarhurst Quarry as well as by the Gull River which is probably a regional ground water discharge zone.

Lateral hydraulic gradients generally range between 0.03 and 0.08 with the higher lateral gradients occurring in August. Lateral hydraulic gradients in November were less than half of what they were in August. In addition the lateral gradients appear to be slightly steeper at the south end of the site near the bedrock scarp and tend to flatten out on the flat limestone plain north of the landfill.

Vertical hydraulic gradients at this site are generally downward indicating recharge conditions, as would be expected in this uplands area. In August the vertical hydraulic gradients were between 0.02 and 0.18 downward. In November they were reduced to an average of about 0.01 downward.

All the on-site ground water monitors were slug tested to assess the in-situ hydraulic conductivity of the fractured limestone bedrock. The test results were plotted and analyzed using the methods of Hvorslev (1952). The test plots and calculations are presented in Appendix III. The hydraulic conductivity results are summarized below in Table 2.

The measured hydraulic conductivity of the limestone bedrock ranged from 9×10^{-9} to 1×10^{-5} m/s with a geometric mean value of 3×10^{-7} m/s and a median value of 2×10^{-7} m/s. Hydraulic conductivity values vary over three orders of magnitude due to the presence or absence of fracture as well as variations in fracture aperture and continuity. The primary hydraulic conductivity of the unfractured limestone matrix at this site is probably less than 1×10^{-8} m/s.

It is difficult to estimate average ground water flow velocities in fractured bedrock due to the large variability in hydraulic conductivities from place to place. However, based

Closed Coboconk Landfill 88-237

Table 2 Summary for Hydraulic Conductivity of the
Limestone Bedrock Based on Slug Test Results

Monitor	Depth of Screen (m)	Hydraulic Conductivity (m/s)
1-I	8.3 - 9.8	1×10^{-5}
1-II	3.1 - 6.1	1×10^{-7}
2-I	7.5 - 9.0	8×10^{-6}
2-II	1.6 - 4.6	9×10^{-9}
3-I	7.2 - 8.7	1×10^{-8}
3-II	1.3 - 4.3	2×10^{-7}
4-I	5.8 - 8.8	6×10^{-7}



on an average hydraulic gradient of 0.055, the geometric mean hydraulic conductivity of 3×10^{-7} m/s and estimated fracture porosity for the limestone of 1%, an average ground water flow rate of about 50 m/yr can be calculated using Darcy's Law. Based on this flow rate, average ground water travel times from the landfill to Gull River (0.5 km) or to the Cedarhurst Quarry (0.4 km) would be in the order of ten years. Since the landfill closed over fourteen years ago there is no reason to expect that leachate impacts will become more severe in the future.



8.0 WATER QUALITY IN GROUND WATER MONITORS

The on-site ground water monitors were developed by removing three well-bore volumes of water prior to sampling. Well development and sampling were carried out using Terraqua hand pumps and polyethylene tubing dedicated to each monitoring well. The samples were collected in August 1988. There was insufficient water in shallow monitors 2-II and 3-II in August so these monitors were developed and sampled in November 1988 after the water table had risen in response to infiltration from a period of wet weather. Monitor 4-I was sampled in August and again in November to provide a preliminary assessment of ground water quality seasonal variations.

The chemical analysis results are presented in Appendix IV and are summarized on Table 3.

Monitors 1-I and 1-II are located upgradient of the landfill and thus are representative of background ground water quality. Monitors 2-I, 2-II, 3-I and 3-II are located downgradient of the landfill where some leachate impacts on ground water quality would be expected. Monitor 4-I was installed directly below the refuse and should have water quality which is representative of the leachate source.

Review of Table 3 indicates the chemical concentrations in the leachate monitor, 4-I, and in the downgradient monitors, 2-I, 2-II, 3-I and 3-II, are generally not much higher than the background concentrations in monitors 1-I and 1-II. Water quality in all the monitors is relatively good compared to typical landfill sites. The leachate is exceptionally dilute. For instance the maximum chloride concentration measured on-site is 11 mg/L. The drinking water objective is 250 mg/L and it is not uncommon to get chloride concentrations of 1000 mg/L or more in leachate from typical Ontario landfills.

The leachate sample from monitor 4-I was also tested for a scan of volatile organic compounds (U.S. EPA Method 624), phenols and heavy metals. No volatile organic compounds were detected at concentrations above the method detection limits.

PROJECT NO: 88-237 CLOSED COBOCONK LANDFILL

TABLE 3: Summary of Water Quality in Ground Water Monitors
Results in mg/L unless otherwise noted.

MONITOR	1-I	1-I(BH6)	1-II	2-I	2-II	3-I	3-II	4-I	4-I	Municipal Tap (BH5)
DATE	Aug-88	Aug-88	Aug-88	Aug-88	Nov-88	Aug-88	Nov-88	Aug-88	Nov-88	Aug-88
PARAMETERS										
Total Dissolved Solids	314	215	290	297	396	315	769	323	576	158
Conductivity (umho/cm)	625	430	575	560	522	660	1098	640	766	300
Calcium	113	75	99	64	64	86	137	88	117	36
Magnesium	3.8	3.6	7.8	14	5.7	12	14	21	10	8.3
Sodium	0.9	0.6	0.9	20	25	7.6	25	4	3.3	8.8
Potassium	0.6	0.4	3.5	3.7	2.1	6.3	23	3.4	11	1.2
Chloride	2	2	3	11	3	11	10	4	1	25
Alkalinity (CaCO3)	290	195	250	175	199	190	294	280	321	85
Sulphate	15	11	21	70	49	70	176	26	33	26
Iron (dissolved)	0.07	0.04	0.02	0.03	0.03	0.06	0.03	0.05	0.02	0.02
Manganese (dissolved)	0.06	0.06	0.04	0.04	0.03	0.03	0.04	0.04	0.06	0.01
Ammonia (N)	<.05	<.05	<.05	0.4	<.05	0.25	<.05	0.23	0.09	0.19
Nitrate + Nitrite (N)	<.05	<.05	<.05	0.86	0.22	0.56	4.6	0.11	0.74	0.24
Total Organic Carbon	4.1	3.5	2.9	4.1	2.0	5.4	5.6	2.6	2.0	2.6
Phenols	<.002	<.002	<.002	0.006	<.002	0.003	<.002	0.003	<.002	0.003

1-I(BH6) - 'Blind' Replicate Sample
Toronto Tap (BH5) - 'Blind' QA Sample



Similarly the leachate heavy metal concentrations were generally below detection limits or were typical of background levels in ground water. Phenol concentrations slightly exceeded the drinking water limit in the August leachate sample and several downgradient monitors, however, phenols were not detected in the November samples from monitors 2-II, 3-II and 4-I.

The dilute nature of the leachate and the lack of significant ground water quality degradation can probably be attributed to the following:

- (a) the landfill is very small,
- (b) landfill closed over fourteen years ago,
- (c) the most of the refuse was burned, and
- (d) the landfill does not have an impermeable cover and infiltrating precipitation has probably flushed out most of the soluble contaminants years ago.

Ground water quality data from monitoring wells and residential wells were compared to the Ontario Drinking Water Objectives. The results of this comparison are presented in Table 4. None of the health-related objectives were exceeded in any of the monitoring wells. Only four of the aesthetic consideration objectives were exceeded and only in a few of the monitoring wells.

Replicate samples were collected in August from monitor 1-I, residential well H6 and surface water station R2. The replicate samples were submitted to the laboratory with false names (BH6, H9 and R3) for quality assurance purposes. The results of the residential well (H6/H9) and surface water (R2/R3) replicates correlate reasonably and are generally within the accepted range for laboratory accuracy. The replicate samples from ground water monitor 1-I do not correlate as well but this is more likely related to sampling than to laboratory analysis. The residential well and surface water replicate samples were collected at the same time. However, it was necessary to allow water levels in monitor 1-I to recover for several hours prior to collecting the second sample.

PROJECT NO: 88-237 CLOSED COBOCONK LANDFILL

TABLE 4: Drinking Water Objectives Exceedances

Parameter	MOE Drinking Water Objectives	Residential Wells in Exceedance (concentrations in mg/L)	Monitoring Wells in Exceedance (concentrations in mg/L)
Chloride	250	H6 (360)	
Total Dissolved Solids	500	H1 (877), H3 (606), H4 (590), H6 (999)	3-II (769), 4-I (576 Nov)
Total Organic Carbon	5.0	H7 (5.9)	3-I (5.4), 3-II (5.6)
Iron*	0.3	H1 (.31), H5 (.36), H6 (.64), H7 (1.0)	
Manganese*	0.05	H3 (.16), H6 (.46), H7 (.11)	1-I (.06), 4-I (.06 Nov)
Phenols	0.002	H3 (.006), H5 (.003), H6 (.003) H7 (.003), Toronto Tap (BH5) (.003)	2-I (.006), 3-I (.003), 4-I (.003 Avg)

* total metal concentrations were considered for residential wells and dissolved metal concentrations were considered in monitoring wells due to the presence of suspended silt and clay particles.



9.0 WATER QUALITY IN RESIDENTIAL WELLS

Water samples were collected from eight residential wells in the vicinity of the landfill in August 1988. Residential well sampling locations are shown on Figure 6. The taps were allowed to run for several minutes prior to sampling, while the residents were being interviewed about their wells (see Appendix II).

The chemical analysis results are presented in Appendix IV and are summarized in Table 5. Table 4 (see section 8.0) presents the results of a comparison of the data with Ontario Drinking Water Objectives. No health-related objectives were exceeded.

Four of the residential wells (H1, H3, H4 and H6) which are located along Highway 35, have above background levels of conductivity ($>1,000$ umho-cm) sodium (>50 mg/L) and chloride (>50 mg/L), and exceed the objective for total dissolved solids (T.D.S.). This is probably due to application of de-icing salt to the highway, parking lots and driveways. Well H6 also exceeded the objective for chloride of 250 mg/L.

Four wells exceeded the limits for total iron and three exceeded the total manganese limit. These aesthetic limits are established primarily to prevent staining of plumbing fixtures and the levels of iron and manganese found could be caused by natural background water quality. One well (H7), also slightly the aesthetic objective for total organic carbon, and four wells (H3, H5, H6 and H7) exceeded the aesthetic objective for phenols as did the quality assurance blank sample of municipal tap water.

Three wells H3, H4 and H8 have above-background nitrate concentrations (2.2 to 5.2 mg/L) although the drinking water objective of 10 mg/L was not exceeded. This suggest minor ground water quality degradation from septic systems, which is common where fractured bedrock occurs near surface as it does in this area.

Three of the residents interviewed reported water quality problems with their wells. Well H6 was reportedly contaminated with petroleum product from a spill at the nearby Texaco station several years ago. Apparently the resident had to import water for three years. During this time the well was pumped out and rehabilitated, and since then the

PROJECT NO: 88-237 CLOSED COBOCONK LANDFILL

TABLE 5: Summary of Water Quality in Residential Wells
Results in mg/L unless otherwise noted.

Residential Well	H1	H2	H3	H4	H5	H6	H6(H9)	H7	H8	Municipal Tap (BH#5)
Date	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88	Aug-88
Parameters										
Total Dissolved Solids	877	300	606	590	380	999	985	422	387	158
Conductivity (µmho/cm)	1480	593	1240	1128	760	1960	1990	770	760	300
Calcium	138	88	129	134	94	200	197	112	111	36
Magnesium	24	11	13	8.3	20	9.8	9.7	13	6.6	8.3
Sodium	120	7.3	84	58	14	170	160	22	16	8.8
Potassium	5.0	1.9	3.4	1.9	4.1	3.7	3.7	3.0	2.4	1.2
Chloride	54	8	140	95	22	360	350	41	20	25
Alkalinity (CaCO3)	210	240	280	230	250	350	360	250	230	85
Sulphate	400	33	49	140	67	35	34	75	65	26
Iron (total)	0.31	0.05	0.19	0.03	0.36	0.64	0.64	1.0	0.03	0.03
Manganese (total)	0.05	0.01	0.16	0.01	0.05	0.46	0.45	0.11	0.01	<.01
Ammonia (N)	0.35	<.05	<.05	<.05	0.19	0.93	0.95	0.14	<.05	0.19
Nitrate + Nitrite (N)	<.05	0.13	2.9	2.2	0.17	0.69	0.73	<.05	5.2	0.24
Total Organic Carbon	1.7	2.6	3.9	2.8	4.1	4.5	4.5	5.9	3.3	2.6
Phenols	<.002	<.002	0.006	<.002	0.003	0.003	<.002	0.003	<.002	0.003

H6 (H9) - 'Blind' Replicate Sample
Toronto Tap (BH#5) - 'Blind' QA Sample



resident has resumed use of the well. The owner of well H8 reported that flooding of the well during spring run-off was a problem in the past. The owner of well H7 reported sulphur problems and water level depletion which she attributed to the dewatering effect of the nearby Cedarhurst Quarry.

Based on the available data it seems unlikely that leachate from the closed Coboconk Landfill will ever have a detectable impact on the residential wells in the area. While it is hydraulically possible for leachate to reach some of the residential wells the leachate would likely have negligible impact because:

- (a) The leachate chemistry at this landfill is so dilute that concentrations of most parameters are not as high in leachate as they are in water from local residential wells.
- (b) Dilution and attenuation of leachate would occur along the 200 m long flow path to the nearest residential wells.
- (c) The effects of dilute leachate impact would be masked by potential impacts of local contaminant sources such as septic systems and road salt contamination which are located nearer the residential wells



10.0 SURFACE WATER FLOW

No streams or flowing surface water were observed on the landfill property during site visits in August and November 1988, although some ponded surface water was present in November.

The ditch which drains the Cedarhurst Quarry, north of the landfill property, was flowing in August, 1988 after an exceptionally dry summer. This observation confirms that this drainage ditch is fed by ground water discharge.

The Gull River is the area's major drainage channel and is located about 500 m from the landfill. Stream flow data for the Gull River is available from the gauging station (No. 02HF002) at Norland, 8 km north of Coboconk. Mean annual discharge at this station was $30.4 \text{ m}^3/\text{s}$ for the period 1963 to 1986. The highest daily discharge for the period of record was $80.4 \text{ m}^3/\text{s}$ which occurred on April 2, 1976. The lowest daily discharge was $1.37 \text{ m}^3/\text{s}$ which occurred on December 22, 1964.



11.0 SURFACE WATER QUALITY

Samples of surface water from the Gull River (R2, R3, R4) and the Cedarhurst Quarry drainage ditch (Q1) were collected in August, 1988. A sample of ponded surface water (SWA) was collected near the west side of the landfill in November, 1988. Chemical analysis results of these samples are provided in Appendix IV and are summarized in Table 6.

Water quality in the Gull River is good. Due to the large flow volumes in this river, it would be impossible to ever detect any leachate impacts attributable to the closed Coboconk Landfill.

The water used for coring the boreholes at the landfill was obtained from the Gull River at location R2.

The water quality in the quarry ditch is much more mineralized than the Gull River water due to ground water discharge from the limestone bedrock. Concentrations of conductivity, calcium, magnesium, sodium, alkalinity and sulphate are up to an order of magnitude higher than in the Gull River.

Water quality in ponded surface water near the west flank of the landfill also contained elevated levels of conductivity, calcium, and alkalinity which are not typical of runoff from recent precipitation. However, the chloride concentration for SWA was <1 mg/L which is not typical of leachate contamination. SWA is located near monitors 2-I and 2-II. The water table was observed to be at surface in these monitors in November 1988 which suggests that the mineralized water quality in the SWA sample may be related to localized ground water discharges from the fractured limestone outcrops in this area at the base of the bedrock scarp.

PROJECT NO: 88-237 CLOSED COBOCONK LANDFILL

TABLE 6: Summary of Surface Water Quality
Results in mg/L unless otherwise noted.

Station	Q1	R2	R2(R3)	R4	SWA	Municipal Tap (BH#5)
Date	Aug-88	Aug-88	Aug-88	Aug-88	Nov-88	Aug-88
Parameters						
Total Dissolved Solids	384	40	40	35	500	158
Conductivity (µmho/cm)	740	73	76	65	570	300
Calcium	82	9	9	8	104	36
Magnesium	18	1.8	1.7	1.7	3.0	8.3
Sodium	15	1.5	1.8	1.3	10	8.8
Potassium	3.7	0.7	0.6	0.5	4.0	1.2
Chloride	19	3	3	3	<1	25
Alkalinity (CaCO3)	140	19	21	16	294	85
Sulphate	150	11	10	10	18	26
Iron (total)	0.07	0.07	0.30	0.04	0.03	0.03
Manganese (total)	0.01	0.02	0.05	0.01	0.04	0.01
Ammonia (N)	0.1	0.05	<.05	<.05	<.05	0.19
Nitrate + Nitrite (N)	2.5	<.05	<.05	<.05	<.05	0.24
Total Organic Carbon	4.7	4.6	4.2	4.1	3.7	2.6
Phenols	<.002	<.002	<.002	<.002	-	0.003

R2 (R3) - 'Blind' Replicate Sample
Toronto Tap (BH #5) - 'Blind' QA Sample



12.0 LANDFILL GAS

Methane and carbon dioxide are the principal gases generated at a landfill site. Carbon dioxide is heavier than air and is not explosive. Methane is a combustible gas which is explosive in concentrations of 5 to 15% mixed with air. Methane is lighter than air and tends to migrate upward.

Lateral off-site gas migration problems generally occur when frozen ground surfaces or low permeability landfill covers prevent upward venting of gas to the atmosphere. When this occurs, gas pressure builds up in the landfill and the gas begins to migrate laterally towards areas of low pressure, such as underground spaces like basements. Winter operation of furnaces in basements of nearby buildings can actually cause a negative pressure sink that induces gas flow towards it. A layer of unsaturated, permeable soil or rock that is horizontally continuous is generally required for significant gas movement to occur. Methane cannot move through saturated soils or rock (e.g., below the water table) and only moves very slowly through low permeability materials.

Six hand auger boreholes were drilled into the top of the landfill to permit gas sampling and testing in August, 1988. Hand auger borehole locations are shown on Figure 6 and geologic logs are presented in Appendix III.

Methane gas concentrations were measured in each hand auger borehole using a portable gas sniffer which detects combustible gases as a percentage of total atmosphere. No combustible gas concentrations were detected in any of the hand auger boreholes. Similarly, there was no evidence of vegetation damage caused by methane gas concentrations.

The lack of methane gas is consistent with what we know about this landfill. The refuse was burned regularly which would have consumed and oxidized most of the organic matter in the refuse which is the major source of methane production in most municipal landfills. In addition, the landfill surface final cover consists of a thin layer of silty sands with exposed refuse along the northern slope, thus any methane produced would easily



vent to the atmosphere. The site has been closed for over fourteen years so gas generation rates would probably be significantly less than when the site was in operation.

The limestone bedrock occurs from 0 to 0.5 m below grade at this site. Consequently all the refuse was emplaced above grade and there is little likelihood for lateral, subsurface gas migration. In addition, the effective porosity and permeability of the limestone is relatively low, which further restricts subsurface gas movement.

In summary, methane gas impacts from the Closed Coboconk Landfill on adjacent properties and residences is highly unlikely.



13.0 CONCLUSIONS

The following conclusions are drawn based on the results of this hydrogeological assessment and review of previous investigations:

1. The limestone bedrock aquifer which outcrops in the vicinity of the landfill is the main water supply for the residents of this area. Ground water flow beneath the landfill is to the north-northwest towards several residences which are located about 200 m from the landfill. However, the results of this study indicate that the landfill has almost negligible impact on ground water quality in the bedrock aquifer because the leachate is exceptionally dilute. This is probably due to the following factors:
 - (a) the landfill is very small (0.5 hectares),
 - (b) the landfill was closed over fourteen years ago and time has reduced the strength of the leachate,
 - (c) the refuse was burned regularly which reduced the organic content of the leachate, and
 - (d) the leachate is diluted by clean ground water flowing below the site in the limestone bedrock.

There are no detectable water quality impacts on local residential wells attributable to the landfill because of the dilute nature of the leachate and additional dilution and attenuation along the 200 m ground water flow path. Based on our understanding of the landfill history and ground water flow system, any leachate impacts on the bedrock aquifer would have been at a maximum in the 1970s. There is no reason to expect that leachate impacts will become worse in the future.

2. The nearest flowing surface water courses to the landfill are the Gull River, 500 m to the west, and a drainage ditch in the bottom of the Cedarhurst Quarry,



400 m to the north. No leachate impacts were detected on water quality in either of these two streams and none are expected in the future.

3. No methane gas was detected in six hand auger holes drilled into the landfill. There is very little potential for significant off-site methane gas migration in this hydrogeological setting and gas impacts on adjacent residences either now or in the future are highly unlikely.



14.0 RECOMMENDATIONS

Based on the conclusions of this hydrogeological assessment the following recommendations are submitted for consideration:

1. No remedial measures are required at this site to contain or control leachate or methane gas. Improvements to the landfill final cover including covering the exposed refuse along the north face was previously recommended by the MOE in the early 1970s. This would have been a good idea in the 1970s, however, completion of this work in 1989 would undoubtedly involve the destruction of mature trees and vegetation which now cover the site. Since the site is far removed from public view and most of the contaminants in the landfill have already been leached out, it is our opinion that remedial actions to improve the landfill cover would have little beneficial effect at this time.
2. On-site monitoring of ground water and surface water quality, and methane gas is not warranted because the existing impacts are negligible at present and are expected to decrease in the future. Monitoring of residential wells as a landfill-related program is also unwarranted because water quality in the residential wells is far more likely to be affected by nearby septic systems, road salting and other closer contaminants sources than by the landfill. This surficial bedrock aquifer is susceptible to contamination and perhaps the residents should be informed of existing MOE and local Health Department services regarding domestic water well quality.
3. The construction of new residences and water supply wells closer to the landfill than the existing residential wells is probably not advisable without a more detailed investigation of leachate pathways in the limestone aquifer.



15.0 SELECTED REFERENCES

- Chapman, L.J., and Putnam, D.F. 1972:
The Physiography of Southern Ontario; University of Toronto Press,
Toronto, Ontario, 386 p.
- Finamore, P.F., and Bajc, A.F. 1983:
Quaternary Geology of the Fenelon Falls Area, Southern Ontario;
Ontario Geological Survey, Preliminary Map P.2596.
- Hvorslev, M.J. 1951:
Time Lag and Soil Permeability in Ground water Observations. U.S.
Army Corps Engineers. Waterways Exp. Sta. Bull. 36, Vicksburg, Miss.
- Liberty, B.A. 1963:
Geology of Tweed, Kaladar and Bannockburn Map-Areas, Ontario.
Geological Survey of Canada Paper 63 - 14, 15 p.
- Ontario Ministry of the Environment. 1984:
Water Management. Goals, Policies, Objectives and Implementation
Procedures of the Ministry of the Environment. 70 p.
- Thornthwaite, C.W., and Mather, J.R. 1957:
Instructions and Tables for Computing Potential Evapotranspiration and
the Water Balance. Drexel Institute of Technology, Centerton, New
Jersey, 311 p.
- Victoria County Planning Department. 1975:
Victoria County Official Plan, Background Studies, Volume 1 Physical
Base. 293 p.

APPENDIX I

MOE FILE INFORMATION



APPLICATION FOR A CERTIFICATE OF APPROVAL FOR A WASTE DISPOSAL SITE

TO: THE DEPARTMENT OF ENERGY AND RESOURCES MANAGEMENT
880 Bay Street,
Toronto, Ontario

To be submitted through Regional
Waste Management Engineer

(1) Under the Waste Management Act, 1970 and the regulations, this applica-

tion is made by Township of Souerville
Hammond, Ont.

Owner of Facility

Address

(2) for the Renewal of a Certificate of Approval for a

Delete item inapplicable

Type of Disposal

Garbage Dump Site

(3) located Dist. lots 35 & 36 First Range

Full particulars of Location

Souerville Township

(4) A Certificate of Approval No. 321603 for this
Provisional Certificate
site was issued Mar. 17 19 71

Delete item inapplicable

(5) No change in use, operation, or ownership of the site has occurred since
the date of the original application.

Dated this Oct. 27 day of October 19 71

Miss Byrne
Signature of Applicant



(6) The following changes in use, operation or ownership (have occurred
since the date of the original application) (are proposed)

Delete item inapplicable

If necessary, provide additional
details on separate sheets and attach
to application.

have kept burned & buried
every two weeks
Continued on Attached Sheets ☐

(7) The site will be operated in accordance with The Waste Management Act,
1970 and the regulations by George Pease

Name of Operator

Address

Colbrook, Ont.

The required supporting information to the application is appended hereto.

(8) Notice of this application has been published in the.....

.....on.....and

.....19..... and a copy of the notice is attached.

(9) A certificate that the site does not contravene any of the by-laws of the
municipality is attached.

To be completed if applicant is other
than a municipality

See notes on sections 1 to 9 on back
of last copy (pink) which is to be
retained by Applicant.

HALIBURTON, KAWARTHA, PINE RIDGE DISTRICT HEALTH UNIT

Charlotte M. Horner, B.A., M.D., D.P.H. - Medical Officer of Health

Inspection Report
General Sanitation

Date Received Date of Inspection Feb. 12, 1971
Address of Premises: Part of Lots 35 & 36, Front Range - Somerville Twp.
Type of Premises: Refuse Disposal Site.
Tenant P.O. Address
Owner: Twp. of Somerville P.O. Address: Kinmount
Complainant P.O. Address
Reason for Inspection: Routine

REPORT This site is an open face dump serving the Village of Coboconk (Pop. 800) and surrounding area. Residents of Bexley Twp. also use this dump.

Observations: The dump face measures about 75' x 150'. There is little or no soil cover over rock in this general area and it is suspected that this is the case at the dump site although snow cover made it difficult to determine. Supposedly the dump is heavily infested with rats according to the clerk of Bexley Twp., although none were observed during the inspection. The dump is accessible year round. The nearest dwelling is situated about $\frac{1}{4}$ mile away on the corner of the township road and the access road. The nearest watercourse is the Gull River about 1 mile away.

Comment: Mainly because of the lack of soil cover over rock and the difficulty encountered in drawing in fill to cover the refuse, the site is unsatisfactory.

Recommendation: Provisional certificate be issued with a time for expiry.

INSPECTOR

M. D. Dawson

M. D. Dawson, C.P.H.I. (C)

(OVER)

RECOMMENDATION OF REGIONAL ENGINEER

NOTE: This form shall be submitted by the Regional Engineer to Head Office along with the application form and all supporting information.

(1) DATE APPLICATION RECEIVED: January 18, 1971 File: A. 3216

(2) APPLICANT: Township of Somerville

(3) ISSUE: Certificate of Approval ☐

Provisional Certificate of Approval ☒

(4) TIME: Provisional Certificate to Expire in 1 months from date of issue.

(5) CONDITIONS OF ISSUE:

1) SUPPORTING INFORMATION FORM TO BE COMPLETED BY THE
MUNICIPALITY & FORWARDED TO THIS OFFICE BY EXPIRY
DATE.

(6) DO NOT ISSUE: REFUSE APPLICATION ☐

REVOKE (Cert. No.) ☐

(7) REASONS FOR (6)

(8) DEFER: CIRCULATE TO:

FOR:

(9) DATE: FEB 17/71 SIGNED: [Signature]

Regional Engineer



Department of Energy and Resources Management
Waste Management Branch

APPLICATION FOR A CERTIFICATE OF APPROVAL
FOR A WASTE DISPOSAL SITE

DEPT. OF ENERGY AND RESOURCES
MANAGEMENT
JAN 10 1970

TO: THE DEPARTMENT OF ENERGY AND RESOURCES MANAGEMENT
830 Bay Street,
Toronto, Ontario

To be submitted through Regional
Waste Management Engineer

(1) Under the Waste Management Act, 1970 and the regulations, this applica-
tion is made by Township of Simcoeville

Kirkfield Ontario

Owner of Facility

Address

Delete item inapplicable

Type of Disposal

Full particulars of Location

(2) for the Renewal of a Certificate of Approval for a
Issue

LANDFILL
Site

(3) located Part of lots 25 & 36 Front Range
Simcoeville Township

(4) A Certificate of Approval No. _____ for this
Provisional Certificate site was issued _____ 19____

Delete item inapplicable

(5) No change in use, operation, or ownership of the site has occurred since
the date of the original application.

Dated this 18th day of Nov 1970

M. S. Gallettman
Signature of Applicant

(6) The following changes in use, operation or ownership (have occurred
since the date of the original application) (are proposed).

Delete item inapplicable

If necessary, provide additional
details on separate sheets and attach
to application.

have kept burning ^{put time} & buried
about every 2 weeks

Continued on Attached Sheets ☐

(7) The site will be operated in accordance with The Waste Management Act,
1970 and the regulations by Jacob Gill

Name of Operator

Address

The required supporting information to the application is appended hereto.

(8) Notice of this application has been published in the _____
on _____ and
_____ 19____ and a copy of the notice is attached.

(9) A certificate that the site does not contravene any of the by-laws of the
municipality is attached.

To be completed if applicant is other
than a municipality

See notes on sections 1 to 9 on back
of last copy (pink) which is to be
retained by _____

TO AN
APPLICATION FOR APPROVAL
OF A
LANDFILL DISPOSAL SITE

1. Wastes to be Disposed of Comprise

Domestic	60 %
Commercial	25 %
Industrial Waste	3 %
Hauled Liquid Industrial Waste	%
Agricultural Waste	4 %
Hazardous Waste	2 %
Hauled Sewage	%
* Other	6 %
100%	

* Describe

Total 2 1/2 Tons/Day

Population Served 1000

3. Distance to Nearest Watercourse Ft.
Distance to Source of Potable Water Ft.
Distance to Dwelling Ft.
Distance to Public Road 1000 Ft.
Distance to Cemetery 5180 Ft.

Total Area of Site 9 Acres

Anticipated Life 2 Years

General Description of Site

Rosky & 2' of dirt on top

5. Proposed Future Land Use

no good for anything

7. The Following Documents are Attached

2. Origin and Composition of Principal Components of Waste (other than domestic and commercial)

nil

4. Maximum Depth of Excavation Below Surface

nil Ft

Maximum Height of Fill

15 Ft

Above Surface

Type(s) of Material Encountered From Surface

clay bottom 2 Ft

Depth of Watertable Below Surface 4 Ft
on March 1 (Date)

6. Operating Equipment

2-1/2 ton capacity Bulldozer shovel

Hours of Operation 20 hours per month

FOR DEPARTMENTAL USE

8. Authorities Consulted:

Health Unit	☐ Objection	☐ No Objection
O.W.R.C.	☐ Objection	☐ No Objection
A.M.B.	☐ Objection	☐ No Objection
Municipality	☐ Objection	☐ No Objection
Conservation Authority	☐ Objection	☐ No Objection

Other See Health Unit report dated 11/18/67

Commercial	%
Industrial Waste	3.....%
Hauled Liquid Industrial Waste	%
Agricultural Waste	4.....%
Hazardous Waste	2.....%
Hauled Sewage	%
* Other	6.....%
	<u>100%</u>

Describe.....

Total..... 2 1/2 Tons/Day

Population Served..... 1000

Distance to Nearest Watercourse Ft.
 Distance to Source of Potable Water Ft.
 Distance to Dwelling Ft.
 Distance to Public Road 1000 Ft.
 Distance to Cemetery 5000 Ft.

Total Area of Site 9 Acres
 Anticipated Life 2 Years

General Description of Site

Rocky & 2' of dirt on top

4. Maximum Depth of Excavation Below Surface nil Ft.
 Maximum Height of Fill Above Surface 15 Ft.
 Type(s) of Material Encountered From Surface

dry loam 2 Ft.
 Ft.
 Ft.
 Depth of Watertable Below Surface 4 Ft.
 on Nov. 1 (Date).

5. Proposed Future Land Use

no good for anything

6. Operating Equipment

20 hrs per month
bulldozer shovel
 Hours of Operation..... 20 hrs per month

The Following Documents are Attached

FOR DEPARTMENTAL USE

8. Authorities Consulted:

Health Unit	☐ Objection	☐ No Objection
O.W.R.C.	☐ Objection	☐ No Objection
A.M.B.	☐ Objection	☐ No Objection
Municipality	☐ Objection	☐ No Objection
Conservation Authority	☐ Objection	☐ No Objection

Other (SEE HEALTH UNIT INSPECTION REPORT)

Inspection Record Forms Attached

Prepared by

Marion Station

Regional Engineer's Report Attached ☐

RECOMMENDATION

SEE FORM 2-11

DATED March 3/71

SIGNED Marion Station

DATED Nov. 8/71

SIGNED [Signature]

WASTE MANAGEMENT BRANCH

RECOMMENDATION OF REGIONAL ENGINEER

NOTE: This form shall be submitted by the Regional Engineer to Head Office along with the application form and all supporting information.

(1) DATE APPLICATION RECEIVED: October 29, 1971 File: A. 321603

(2) APPLICANT: Township of Somerville
Pt. Lots 35, 36 Front Range

(3) ISSUE: Certificate of Approval

☐

Provisional Certificate of Approval

☒

(4) TIME: Provisional Certificate to Expire in 8 months from date of issue.

(5) CONDITIONS OF ISSUE:

- 1) ALL OPEN FACES TO BE PROPERLY GRADED, COMPACTED, & COVERED WITH AT LEAST TWO (2) FT. OF FILL
- 2) COMPLETE COVERAGE OF ALL REFUSE TO BE CARRIED OUT AT LEAST WEEKLY
- 3) RAT CONTROL PROGRAM TO BE INITIATED
- 4) SITE TO BE ATTENDED DURING ALL OPEN HOURS & ADEQUATE GATES, FENCING, & SIGNS TO BE INSTALLED.

(6) DO NOT ISSUE:

REFUSE APPLICATION

☐

REVOKE (Cert. No.)

☐

(7) REASONS FOR (6)

.....

.....

.....

.....

(8) DEFER: CIRCULATE TO:

FOR:



DEPARTMENT OF ENERGY AND RESOURCES MANAGEMENT
WASTE MANAGEMENT BRANCH

TELEPHONE
XXXXXX

XXXXXXXXXXXX
1 ST. CLAIR AVE. W.
TORONTO

FILE REF. NO.: A.321603

WASTE DISPOSAL SITE
SOMERVILLE TOWNSHIP
LOTS 35 & 36, FRONT RANGE

Report by: P. E. Davidson, P. Eng.,
Regional Engineer,
Midwestern Region,
797 Princess Street,
Kingston, Ontario.

September 7, 1971.

R E P O R T

Report by: Mr. P. E. Davidson, P. Eng.,
Waste Management Engineer,
Midwestern Region,
Waste Management Branch,
Department of the Environment,
797 Princess Street,
Kingston, Ontario.

File No. A.321603

September 7, 1971.

GENERAL:

This site was inspected by the writer on September 1, 1971. It is one of three disposal sites serving the Township, population of which is 1310. (In the main, this site serves Cobococonk and surrounding area)

DETAIL:

The site is located approximately 1 mile south-east of Cobococonk, $\frac{1}{4}$ mile east of Highway 35. It is located 250 yds. south of the east-west township road and the same distance from the nearest dwelling which is located at the entrance to the site. The soil type in the vicinity is Dummer loam (shallow phase) over bedrock. There does not appear to be sufficient soil on-site to support a landfill operation. The closest watercourse is the Gull River which is approximately one mile away to the north-west. The site is apparently open at all hours although it was attended when inspected. Although covering has occurred recently on the top, the 12 foot high open sides have not been covered. There are no gates, signs, or fences and some open burning of refuse does take place.

CONCLUSIONS:

- 1) The operation of this site is not in accordance with Ontario Regulation 375/70.
- 2) The location of this site may be found to be unacceptable by the Township when the additional costs of trucking in fill are appreciated.

RECOMMENDATIONS:

- 1) All open faces should be properly graded, compacted, and covered with at least two (2) ft. of fill.
- 2) Complete coverage of all refuse to be carried out at least weekly.
- 3) Site to be attended during all open hours.
- 4) Adequate gates, fencing and signs to be installed.
- 5) Rat control program to be initiated.


P. E. Davidson, P. Eng.

PED/lup



Ontario

Ministry of the
Environment

Waste Management Branch,
880 Bay Street, 3rd Floor,
Toronto, Ontario,
M5S 1Z8.

SITE RESUME

Date: April 27/73

Applicant: Township of Somerville File No. 321603

Location: Pt. lots 35 & 36, Front Range, Somerville Twp.

Common Name (if applicable) Coboconk

Municipalities Served: Somerville Twp.

Population Served 1000 Type of Site Landfill

No. of Inspections: 2 Date of Last Inspection: Mar. 12/73

Upgrading proceeding under an Approved Program: Yes No

Applicant's Attitude: Retarding the Efforts of Branch Adequate

Current Status of Site:

Location:

Acceptable.

Operations:

Operation inadequate.



MINISTRY OF THE ENVIRONMENT

Waste Management Branch,
797 Princess Street,
Kingston, Ontario.
K7L 1G1.

Telephone Area Code 613
546-3297

March 19, 1973.

File No. A.321601
A.321602
A.321603 ✓

Mrs. V. G. Byrne, Clerk,
Township of Somerville,
Kinmount, Ontario.

Re: Waste Disposal Sites
Lot 13, Conc. IV
Lot 1, Conc. XI
Part Lots 35 & 36, Front Range
Somerville Township

Dear Mrs. Byrne:

Routine inspections of these sites were conducted by staff of this Branch on March 12, 1973. The following inspection reports may act as a guide to Council regarding further site maintenance which is required. Please accept these comments as constructive criticism as we consider the action to date by Somerville Township Council to be very positive.

(1) Lot 13, Conc. IV
No. A.321601

This is a small site situated on shallow soil. The site is posted as being closed but no fence or gate has been established to limit access. The cover material applied at the time of closing did not completely cover all refuse. Complete covering of all refuse must be undertaken at the site. Some use of the site since its closing has resulted in a littering problem.

Recommendations:

1. Completely cover refuse with clean fill.
2. Establish a fence to control access to the site.
3. Maintain a litter control program at this site.

- (2) Lot 1, Conc. XI
No. A.321602
(Kinmount)

The site was closed on June 30, 1972. All efforts regarding closing off have been well executed except the total covering of all refuse on site. The dumping area has been compacted and covered but the side face of the dump is still open. Broken glass and rusted steel remain exposed causing a potential hazard to persons entering the site.

Recommendation:

1. Completely cover refuse with clean fill.
- (3) Part Lots 35 & 36, Front Range
A.321603
(Coboconk)

This is the largest of the three sites closed by Somerville Township in 1972. The 12 foot high banks of refuse extend approximately 400 feet along the north and west sides of the site. No successful attempt has been made by the township to properly grade and cover the open sides of the landfill. This requirement for closing off the site was first transmitted to Council in Mr. P. Davidson's report dated September 7, 1971.

The access road has been fenced and a sign noting the new site location has been erected.

Recommendations:

1. That the open garbage face should be reduced to a grade of one foot vertical drop over 3 feet horizontal run.
2. That this 1:3 slope should be compacted and covered with at least two feet of clean fill.

I would be pleased to meet with members of Council to discuss the work required to properly and adequately close the above noted site.

Yours very truly,

F. J. Iliffe

F. J. Iliffe, P. Eng.,
Regional Engineer,
Midwestern Region.

H. Avey/mp

[Handwritten signature]



Department of Energy and Resources Management

PROVISIONAL CERTIFICATE OF APPROVAL FOR A WASTE DISPOSAL SITE


Certificate No. 321603

Under The Waste Management Act, 1970 and the regulations and subject to the limitations thereof, this Provisional Certificate of Approval is issued to.....

.....Township of Somerville,.....

.....Kilmount,.....

.....Ontario.....



for the.....Landfill.....

Site

located.....Part of lots 35 and 36, Front Range, Township of Somerville.....

subject to the following conditions.....

1....That all faces including the working face are properly graded, compacted.....
.....and covered with at least two (2) feet of fill.....

2....That all refuse is covered at least once each week.....

3....That a rodent extermination and control program is initiated immediately.....

4....That the site is supervised during all open hours and that adequate.....
.....gates, fencing and signs are installed.....

This Provisional Certificate expires on the.....15th.....day of.....July.....
19.72....

Dated this.....9th.....day of.....November.....19.71..



Ministry
of the
Environment

Ontario

INVENTORY OF MOE CERTIFIED WASTE DISPOSAL SITES
(active and closed)

Site Identification:

Number: 321603 Name: Coboconk Site

Applicant:

Individual/Business Name: Township of Somerville

Address: P.O. Box 59, Kilmount, Ontario

Telephone: 1-705-488-2571

Type of Applicant:

Private ☐

Industrial ☐

Municipality ☒

Type of Ownership:

☐ Proprietorship
Name if different than applicant:

☐ Partnership - Name all partners:

☐ Corporation: President's Name -

Land Owner: (If not applicant)

Name:

Site Location:

Descriptive Location

City ☐

Town ☐

Village ☐

Township ☐

Other ☐

Name: Somerville

Concession: Front Range

Lot Number: 35 and 36

Part of Lot:

Municipality:

Street Address:

Prepared and return location and site plan if not on your record. Note: Include all uses of all adjoining properties.

County Victoria

Electoral District Code 86

MOE Region C

MOE District Peterborough

Has the certificate been registered on title

Yes

☐

No

☐

5. Type of Site:

Organic Soil Conditioning ☐

Transfer ☐

Landfilling ☒ Dump

Describe operations and process to be carried out on site:

..... Site closed - August 20th, 1974

6. Site Characteristics:

Planning

a) Present land use Bush

b) Present official plan designation of site Rural

c) Present zoning category Rural

d) Present land use of all adjoining properties to be provided on location map....
..... Agricultural

e) Distance from any well water supply 750 feet

f) Nearest water course: a) Name Gull River b) Distance 1 mile

Physical Description

g) Rate at which site receives waste in (tons/cubic meters) per day..... Site closed

h) Life expectancy in years based on rate established in (g) N/A

i) Population served 1,000

j) Total area of site (hectares) 3.6

k) Total area approved to be filled (hectares)..... N/A completed O not completed

o) Estimated capacity of site in tons or cubic meters N/A

Hydrogeology

p) Is there a hydrogeologic report available? Yes _____ No X

Author:

Client:

Date:

Location of report:

q) Based on a hydrogeologic appraisal by the Ground Water Evaluator

i) problems with contaminant discharge are likely _____ not likely _____

ii) problems with contaminant discharge are a reasonable possibility.

Yes _____ No _____

iii) there are insufficient data to form a reasonable opinion regarding

i) and ii) above X.

iv) priority for further investigation: high _____ low X

reasons: _____

r) Are the wastes adjacent or near to gravels _____, sands _____, or
bedrock X ?

- s) Is the site in an upland X , or a lowland area?
- t) Is there a ground and/or surface water monitoring program for this site?
Yes No X
- u) Have there been any problems with ground and/or surface water contamination?
Yes No X
- v) Is the nearby ground or surface water presently being used?
Yes 750' Well No
- w) What is the potential use of nearby ground and surface water?
Recreational and Domestic Wells
- x) Has leachate discharge been discussed No ? or calculated No ?

7. Eligible waste categories to be allowed at the site in percent of rate established in 6(g) above:

Domestic

 6 0

Industrial

 3 *

Hazardous

 2 *

Others

 1 0

Commercial

 2 5

Limited to the
class number

101 ☐	203 ☐	302 ☐
102 ☐	204 ☐	303 ☐
103 ☐	205 ☐	304 ☐
104 ☐	206 ☐	190 ☒
105 ☐	207 ☐	290 ☐
106 ☐	208 ☐	401 ☐
201 ☐	209 ☐	402 ☐
202 ☐	301 ☐	

601 ☐
602 ☐
603 ☐
604 ☐
605 ☐
606 ☐
607 ☐

Describe

 Agricultural

.....

.....

.....

.....

.....

.....

.....

dry construction material

8. Control System:

Is there any - Gas control system Yes ☐ No ☒

If yes, please describe

- Gas recovery system Yes ☐ No ☒

If yes, please describe

- Leachate on site treatment Yes ☐ No ☒

If yes, please describe

- Leachate off site treatment Yes ☐ No ☒

If yes, please describe

9. Recommendations for Certification:

Conditions:.....
Site is closed and should not be reopened nor certified
.....

Reasons.....

10.Environmental Officer: Name:.....

Signature: Paul Chester

Date this form was completed:..October.19th.,.1979.

To be completed by the Environmental Approvals Branch.

11. Examined By:.....Certified correct:.....

Date:

TWSP. OF SOMERVILLE
COBOCONK SITE, L. 35+36, F.R.



BUSH

BUSH

RAVINE


BUSH

BUSH

BUSH

TWSP. ROAD

SCR LAND



① ~~B. B. B.~~
② Jacques Paul ~~K~~ an
③ File - Bexley Tap? ~~File~~

WM-08-03

May 6, 1986

Township of Bexley
Coboconk, Ontario
KOM 1K0

Attention: Helen Russell
Clerk-Treasurer

Dear Mrs. Russell:

Re: Proposed Sale of Former Landfill Site
Parts of Lots 35 and 36, Front Range
Township of Somerville

In response to your letter of April 25th, 1986, regarding the
aforementioned subject, please be advised that:

(1) our files indicate that the subject property was used as a
landfill site from March 17, 1971, to August 20, 1974.

(2) under Section 45 of the Environmental Protection Act, "No use
shall be made of land or land covered by water which has been
used for the disposal of waste within a period of twenty-five
years from the year in which such land ceased to be used unless
the approval of the Minister for the proposed use has been given.
R.S.O. 1980, c. 141, s. 45, and

(3) it is our feeling that the owner(s) of the subject property
have a moral obligation to inform the prospective buyer of the
previous use of the property, the liabilities, and of the
restrictions for its future use.

It is our understanding that the prospective buyer is Mr. Guy
Mitchell, who plans to use this property to redirect runoff away
from his present property and dwelling. As noted in the
foregoing, any use of the subject property must receive approval
from this Ministry.


Continued.../2

Helen Russell -2-

With respect to the question of putting the property up for Tender, we suggest that reference be made to the Municipal Act and/or your solicitor.

Should you have any questions regarding this matter, please contact me at this office.

Yours truly,



Clare Muisiner
Environmental Officer
Abatement East Section

CRM:bh

cc: Mr. M.J. McBride





Ministry
of the
Environment

COMPUTER INVENTORY
OF

WASTE DISPOSAL SITES (LANDFILL)

Application/Certificate No.

321603

☐ 1 - Delete
☐ 2 - Add or New
☐ 3 - Change

If this inventory is for Notification of Changes fill in only the data which is being revised.

1. Site Disposition: Active () Closed (x) Not Approved ()

2. Applicants:

Municipal (x) Provincial () Other ()

Name: Cobocoonk Site

Address: P.O. Box 59 Postal Code

City/Prov.: Kinmount, Ontario Telephone: 705-488-2571

If Applicant not Municipal or Provincial complete the following:

() Proprietorship
Name, if different than applicant: () Corporation: President's Name:

() Partnership - Name all partners:
(i) (ii)

3. Land Owner: (if not applicant)

Name:

Address:

4. Lessee (if applicable)

Name:

Address:

5. Site Operator

Name: Jacob Gill Title:

Address: R.R. #1, Kirkfield, Ontario

6. Site Location:

Municipality Name: Somerville Township Municipal Code 85

From Plan of Survey:

Mun. Name: Somerville Township Municipal Code 85

Concession: Front Range

Lot No: 35 and 36 Part of Lot: 35 and 36

Street Address:

7. Geocode

Zone _____ Easting _____ Northing _____

8. Site Characteristics and Waste Category

A. Rate at which site can receive waste per day.

Domestic 60% ☐ Tonnes ☐ Cu. Metres Commercial 25% ☐ Tonnes ☐ Cu. Metres

Liquid Industrial 0 ☐ Tonnes ☐ Cu. Metres Hazardous 0 ☐ Tonnes ☐ Cu. Metres
☐ Litres ☐ Litres

Non Hazardous Solid Industrial 3% ☐ Tonnes ☐ Cu. Metres Other 10% ☐ Tonnes ☐ Cu. Metres

For each Category of Waste List the Class Number as per MOE Classification Guidelines.

190

B. Number of days/year the site is open 20 hrs./month

C. Population served 1,000

D. Names of all municipalities/major industries intended to be served by the site

1) Cobocank 4) _____
2) Sommerville Township 5) _____
3) _____

E. Total area of site 3.6 Hectares

F. Total area to be filled n/a Hectares

G. Estimated capacity of the site n/a Tonnes or _____ Cu. Meters

9. Control System

a. Monitoring for - Gas ☐ Yes ☐ No - Ground Water ☐ Yes ☒ No - Surface Water ☐ Yes ☒ No

b. Control system for - Gas ☐ Yes ☒ No - Gas utilization ☐ Yes ☐ No - Leachate ☐ Yes ☐ No

10. Hydrology

Author: _____

Date: _____

b. Hydrogeologic Appraisal by the Ground Water Evaluator:

Author: _____

Date: _____

11. A. Conditions for Certification Yes (x) No ()
B. Has the certificate been registered on title Yes () No (x)
C. Was there a Hearing Held Yes () No (x)
D. Certificate issued by MOE Region () Head Office (x)
12. A. Date Application was completed or changed November 18, 1970
B. Date Original Certificate was issued March 17, 1971
C. Date Waste Site Closed August 20, 1974

This inventory form was completed by:

Paul Clatter

Approved by Environment Approval Branch for Computer Inventory

Signed _____



Ministry
of the
Environment

Ministère
de
l'Environnement

Central
Region

Région du
Centre

January 14, 1987

To: Brian

From: Paul C.

Re: Closed Landfill Site - Coboconk - 321603
Somerville Township

I spoke with Mike McBride about this site. He didn't have much knowledge about it. However, he informed me the land had been sold to an adjacent landowner, Gilbert Mitchell, in 1986. Mr. Mitchell is aware of the closed site and of the 25 year rule. He uses the land for the storage of wood.

I spoke with Reeve Maurice Watson who reiterated the above. This site was used in conjunction with Bexley Township. This included the plywood company Vic-Ply. As far as the Reeve is aware there was no hazardous waste deposited at this site.

On the original application, dated March 3, 1971, "wastes to be disposed of comprise" should have read Industrial Waste - 5% instead of 3% and 2% hazardous waste.

Due to the nature of the land (lack of adequate soil material), proximity of new homes in the area and the importation of cover material, it is my estimation that a survey of the groundwater be conducted by this office, not W.M.B. I further suggest Derek and Ross be involved with this.

Paul Cleator

Environmental Officer
Abatement East Section

PDC:bh

cc: D. Smith/R. Hodgins

Aug 31/81
WMB want to study
this site
for Ennis inc. *John*
James

139 George Street North
Peterborough Ontario
K9J 3G6
705/743-2972

139 nord, rue George
Peterborough (Ontario)
K9J 3G6
705/743-2972

If in agreement
I will arrange
with Tech Support
agreed
JB

File
401-08 05



Municipality of the
Township of Somerville


CHAS. O. HODGSON, Reeve
Burnt River

C. P. BROHM, Assessor
Coboconk

A. A. WILLIAMSON, Clerk
Treasurer and Tax Collector
Kinmount

DR. H. E. GOOD, M.O.H.
Haliburton

Kinmount, Ontario Lot 37



APPENDIX II

- **MOE COMPUTERIZED WATER WELL RECORDS**
- **MOE ORIGINAL WATER WELL RECORDS**
- **GLL WATER WELL RECONNAISSANCE SURVEY FORMS**

VICTORIA COUNTY 64

MUNICIPALITY CONCESSION ETC	LOT	WELL NO	UTM EASTING NORTHING	ELEV FEET	DATE	DRILLER	CSG DIA INS	KIND OF WATER	WATER FOUND FEET	STAT PUMP FEET	PUMP RATE GPM	TEST TIME MIN	WATER USE GAL	DEPTHS IN FEET TO WHICH FORMATIONS EXTEND	OWNER/LOG/SCREEN
(CONTINUED....)															
RFC	28	647 5281	673887 4944663	850	07/73	2517	6		54	25	50	5	4/20 D0		CRUICKSHANKS I BLACK TPSL 0002 GREY CLAY BLDR 0039 GREY LMSN 0054
RFC	28	647 4412	673910 4944680	850	04/71	2517	6	FR	41	20	20	7	1/00 D0		LAFFY S BRWN CLAY MSND BLDM 0016 BRWN FSHD STNS 0041 GREY LMSN 0049
IC	29	647 5973	673921 4944775	850	05/74	2517	6	FR	52	20	50	7	2/00 D0		KINSMAN ROBERT BLACK TPSL 0002 GREY LMSN BLDR CLAY 0040 GREY LMSN 0052
RFC	29	647 7441	673930 4944740	850	09/75	1312	5	FR	20 38	8	22	30	2/00 D0		CARITARI MARCEL BRWN CLAY STNS HPAN 0020 BRWN STNS SAND 0038
RFC	29	647 5807	674000 4944861	850	06/74	2515	6	FR	45	34	34	8	2/00 D0		CRUICKSHANKS I GREY CLAY STNS 0043 GREY LMSN 0052
RFC	29	647 5797	674026 4944917	850	08/74	2515	6	FR	30	22	36	5	2/00 D0		BIRNO A BRWN CLAY STNS 0027 WHIT LMSN SHLE 0032 WHIT LMSN 0039
RFC	29	647 4577	674050 4944780	850	10/71	2517	6	FR	33	13	35	5	2/00 D0		GORDON T BLDR 0004 CLAY GMYL 0030 LMSN 0040
RFC	30	647 6479	674080 4945043	850	05/77	2515	6	FR	18	2	18	2	2/00 D0		HOGAN JIM BRWN CLAY STNS 0017 GREY LMSN HAKD 0029
RFC	30	647 5972	674081 4945081	850	10/74	2517	6	FR	26	6	28	4	2/00 D0		LEADREATER MAHOLU BRWN CLAY BLDR 0019 GREY LMSN 0030
RFC	30	647 2873	674150 4945200	875	09/63	1312	6	FR	51	10	25	15	1/00 D0		THOMPSON G W BLUE CLAY MSND HPAN 0051 LMSN SHLE 0052
RFC	30	647 3545	674190 4945170	865	05/68	2548	6	FR	36	10	16	4	2/00 D0		KIRWAN G CLAY STNS 0030 LMSN 0036
RFC	31	647 2875	674043 4945508	850	08/63	1312	6	FR	15	7	12	10	1/00 MU		LINCOLN LUD HPAN BLDR 0015 GREY SHLE 0018
RFC	31	647 5811	674084 4945274	850	05/74	2515	6	FR	18	3	3	5	2/00 D0		MUCALUK FRED BRWN CLAY STNS GMYL 0016 GREY LMSN 0023
RFC	31	647 7009	674120 4945350	850	05/77	2517	6	FR	22	3	25	5	2/00 D0		SHICHTER JOHN BRWN TPSL 0001 GREY SHLE 0022 GREY LMSN 0028 LMSN 0021
RFC	31	647 4709	674120 4945440	875	08/71	1312	6	FR	25	14	25	10	1/00 D0		MACEACHERN S GREY CLAY BLDR 0015 GREY LMSN 0030
RFC	31	647 2876	674163 4945389	900	08/67	2516	6	FR	27	16	30	3	2/00 D0		ALCOCK J B BLDR 0006 SHUS 0026 LMSN 0040
RFC	31	647 3543	674200 4945350	900	06/68	2517	6	FR	46	11	44	4	2/00 D0		STETON J A GREY CLAY STNS 0020 BLUE CLAY MSND 0045 LMSN 0054
RFC	31	647 2874	674282 4945543	900	05/62	1312	6	FR	19	4	5	10	1/30 D0		OAKES J H TPSL 0001 CLAY STNS 0019
RFC	32	647 4121	674160 4945650	848	05/70	2517	6	FR	46	44	50	5	2/00 D0		BARTULZ J CLAY MSND 0015 CLAY 0040 SHLE 0045 LMSN 0052
RFC	32	647 2879	674174 4945609	850	08/63	1312	6	FR	15	7	12	10	2/00 D0		DUNLOM HOLDINGS CLAY HPAN BLDR 0015 GREY LMSN SHLE 0018
RFC	32	647 2880	674185 4945654	850	07/65	1312	6	FR	16	11	15	7	1/00 D0		DORLAND S BRWN HPAN BLDM 0016 GREY LMSN SHLE 0019

RFC	32	2078	4973	207	850	08/62	1312	6	FR	14	4	10	10	1/30	00	LUDMA E	CLAY BLDR 0014	GREY	LMSN	0024	
RFC	32	2077	4972	206	850	05/62	1312	6	FR	25	10	20	10	1/00	00	GREY	CLAY HOLDINGS	0017	GREY	LMSN	0027
RFC	33	2076	4971	205	850	09/70	2517	6	FR	30	6	6	5	2/00	00	GREY	CLAY STNS	0024	GREY	LMSN	0027
RFC	34	2075	4970	204	900	01/58	1344	6	FR	30	15	20	5	1/00	00	GREY	CLAY STNS	0024	GREY	LMSN	0031
RFC	35	2074	4969	203	900	07/76	4512	5	FR	30	40	80	2	1/30	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	35	2073	4968	202	900	07/76	4512	6	FR	98	55	65	20	1/30	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2072	4967	201	850	01/64	2516	6	FR	115	40	50	12	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2071	4966	200	900	07/81	5415	6	FR	48	15	30	5	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2070	4965	199	900	03/66	2516	6	FR	40	4	40	4	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2069	4964	198	900	08/72	3324	6	FR	36	10	59	4	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2068	4963	197	900	11/56	5423	6	FR	98	25	25	4	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2067	4962	196	900	08/72	5415	6	FR	21	10	15	6	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	36	2066	4961	195	850	05/50	5423	5	FR	91	20	52	3	3/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2065	4960	194	900	07/66	2516	6	FR	17	9	52	3	3/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2064	4959	193	850	10/50	4223	6	FR	27	9	52	3	3/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2063	4958	192	850	11/50	4223	5	FR	30	8	52	3	3/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2062	4957	191	850	11/60	1312	6	FR	25	8	15	5	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2061	4956	190	850	02/67	1312	6	FR	34	18	21	25	14/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2060	4955	189	850	11/60	1312	6	FR	30	10	20	5	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2059	4954	188	850	05/65	1312	6	FR	24	6	35	3	1/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2058	4953	187	850	07/61	5423	6	FR	20	6	15	3	72/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2057	4952	186	855	01/74	5423	6	FR	29	15	25	10	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2056	4951	185	860	11/76	5415	6	FR	34	10	20	5	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2055	4950	184	870	11/79	5415	6	FR	22	5	7	20	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2054	4949	183	850	06/62	1312	6	FR	15	8	9	5	7/30	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2053	4948	182	850	05/60	5423	6	FR	40	3	40	5	4/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030
RFC	37	2052	4947	181	850	10/61	5415	6	FR	35	10	20	5	2/00	00	GREY	CLAY BLDR 0020	0020	GREY	LMSN	0030

12

MUNICIPALITY
CONFESSION

VICTORIA COUNTY 64

MUNICIPALITY CONFESSION	LUT	WELL NO	UTM EASTING NORTHING	ELEV FEET	DATE	DRILLER	CSG DIA INS	KIND OF WATER	WATER FOUND FEET	STAT LVL FEET	PUMP LVL FEET	TEST DATE GPM	TEST TIME MM/HH	WATER USE	OWNER/LOG/SCREEN DEPTHS IN FEET TO WHICH FORMATIONS EXTEND	
SOMERVILLE TOWNSHIP (CONTINUED...)																
RFC	37	64- 3450	674700 4947170	850	11/68	5415	6	FR	46	15	20	2	2/00	00	ANGERS PAT 0001 GREY CLAY BLDR 0030 LMSN 0050	
RFC	37	64- 2498	6747100 4947130	850	10/67	2516	6	FR	24	4	10	5	3/00	00	CLAY BLDR 0010 LMSN 0024	
RFC	37	64- 2498	6747130 4947160	900	11/82	5415	6	FR	22	10	15	5	2/00	00	HENDERSON M 0005 SHLE 0010 LMSN 0024	
RFC	37	9030	6747050 4947080	850	12/48	5423	5	FR	42	3				CO	BLACK TPLS 0001 CLAY BLDR 0015 LMSN 0022	
RFC	37	2887	6747050 4947080	850	06/67	5423	6	FR	24	6	16	2	2/00	00	BANK OF COMMERCE 0016 LMSN 0042	
RFC	37	2897	6747080 4947110	850	06/67	5423	6	FR	24	6	16	2	2/00	00	USATON 0016 LMSN 0042	
RFC	38	64- 9021	6747400 4947430	900	08/82	5415	6	FR	60	20	40	5	2/00	00	MCALL TPLS 0001 GREY LMSN 0025	
RFC	38	64- 7450	674700 4947300	850	05/76	1312	6	FR	38	9	28	10	1/00	00	BLACK TPLS 0001 CLAY BLDR 0033	
RFC	38	64- 2906	6747300 4947330	850	12/63	1312	6	FR	20	8	10	10	1/00	00	LOVEY CLAY BLDR 0020 GREY LMSN 0039	
RFC	38	64- 2910	6747330 4947360	850	03/65	1312	6	FR	50	26	40	5	1/00	00	HALL D TPLS 0001 GREY LMSN 0026	
RFC	38	64- 2908	6747360 4947390	850	03/65	2516	6	FR	54	29	32	3	3/00	00	BRNN HPAN 0010 GREY LMSN 0016 GREY LMSN	
RFC	38	64- 4402	6747390 4947420	850	05/71	1312	6	FR	50	25	47	10	1/00	00	LAKE S 0026 GREY CLAY HPAN 0045 SHLE LMSN	
RFC	38	64- 2903	6747510 4947540	850	07/54	2516	5	FR	44	17		2	1/00	00	PROG 0026 CLAY STNS GHVL 0040 LMSN 0054	
RFC	38	64- 2909	6747540 4947570	850	01/49	5423	5	FR	12	6				00	ANGELICAN CHURCH 0020 GREY HPAN 0042 GREY LMSN	
RFC	38	64- 2904	6747570 4947600	850	05/59	2516	6	FR	44	11	11	5	1/30	00	POVEY CLAY STNS 0027 LMSN 0046	
RFC	38	64- 2907	6747630 4947660	850	11/64	1312	6	FR	28	14	20	5	2/00	00	MAXBY G 0042 GHVL 0044	
RFC	38	64- 5636	6747660 4947690	870	04/74	5423	6	FR	52	10	15	5	2/00	00	BRNN CLAY BLDR 0016 GREY LMSN SHLE	
RFC	38	64- 5400	6747720 4947750	870	12/73	1312	6	FR	82	57	86	4	6/00	00	RUTER ARN 0001 GREY CLAY BLDR 0018 GREY	
RFC	38	64- 2902	6747600 4947630	850	11/53	5423	5	FR	66	48		3	72/00	00	BLACK TPLS 0001 GREY LMSN 0046	
RFC	38	64- 6406	6747630 4947660	900	01/76	5423	6	FR	85	30	30		1/00	00	REVER CLAY STNS 0006 GREY LMSN 0092	
RFC	38	64- 2901	6747660 4947690	900	11/52	2516	5	FR	90	60		1	1/00	00	GRANLEY MSH 0045 GHVL 0050 GREY LMSN 0066	
RFC	38	64- 5622	6747690 4947720	900	12/74	5423	6	FR	90	50	50	1	1/00	00	WELDER S 0010 GREY LMSN 0085	
RFC	38	64- 2909	6747720 4947750	900	02/66	1312	6	FR	80	54	74	5	1/00	00	LAKE S 0026 GREY CLAY HPAN 0045 SHLE LMSN	

6404313

COUNTY OR DISTRICT Victoria	TOWNSHIP, COUNCIL CITY, TOWN, OR VILLAGE Somerville	CON., SCHOOL TRACT, PARISH, ETC. Cal-Franlin-Tankver	LOT NO. 033
OWNER (SURNAMES FIRST) SCOTT, Russell	ADDRESS Box 151 Bowmanville, Ontario	DATE COMPLETED 02-09-70	

17 674250 4645780 462850 15 24

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)

[illegible][illegible]

411 WATER RECORD			
DATE FOUND AT - EAST		KIND OF WATER	
10-10	10-10	1 ☒ FRESH 2 ☐ SALTY	3 ☐ SULPHUR 4 ☐ MINERAL
10-10	10-10	1 ☐ FRESH 2 ☐ SALTY	3 ☐ SULPHUR 4 ☐ MINERAL
10-10	10-10	1 ☐ FRESH 2 ☐ SALTY	3 ☐ SULPHUR 4 ☐ MINERAL
10-10	10-10	1 ☐ FRESH 2 ☐ SALTY	3 ☐ SULPHUR 4 ☐ MINERAL
10-10	10-10	1 ☐ FRESH 2 ☐ SALTY	3 ☐ SULPHUR 4 ☐ MINERAL

51- CASING & OPEN HOLE RECORD				
INSIDE DIA. INCHES	MATERIAL	WALL THICKNESS INCHES	DEPTH - FEET	
			FROM	TO
6 3/4 06	STEEL ☐ GALVANIZED ☐ CONCRETE ☐ OPEN HOLE	.188	0	31 0031
	STEEL ☐ GALVANIZED ☐ CONCRETE ☐ OPEN HOLE			
	STEEL ☐ GALVANIZED ☐ CONCRETE ☐ OPEN HOLE			

NEW BAC UNIT	DATE(S) OF OPENING (LAST MO)	27-28	DIAMETER	20-26	DEPTH	1-2
	NATIONAL AND TYPE	INCHES		DEPTH TO TOP OF SCANNER	1-2	FEET

61: PLUGGING & SEALING RECORD			
DEPTH SET AT - FEET		MATERIAL AND TYPE	ELEMENT ABOUT LEAD PAGES, ETC.
FROM	TO		
10	10		
10	22.25		
	20.5		

PUMPING-TEST	PUMPING TEST METHOD		PUMPING RATE		DURATION OF PUMPING	
	☐ PUMP	☒ TRAILER	1005 GPM		02 HOURS 00 MIN	
	STATIC LEVEL	WATER LEVEL END OF PUMPING	WATER LEVELS DURING		PUMPING RECOVERY	
			15 MINUTES 30 MINUTES 45 MINUTES 60 MINUTES			
	006 FEET	006 FEET	06.1 FEET 06.6 FEET 06.6 FEET 06.6 FEET		06.6 FEET	
H. PLUMBING GIVE DATE	PUMP INTAKE SET AT		WATER AT END OF TEST			
	GPM	30 FEET		☒ CLEAR		☐ CLOUDY
RECOMMENDED PUMP TYPE	RECOMMENDED PUMP		RECOMMENDED PUMPING		IN G.S.	
☒ SHALLOW	☐ DEEP	JETTING		030 PART (DAYS)		000.5 GPM
NO. 1	0100		GPM / FT. SPECIFIC CAPACITY			

FINAL STATUS OF WELL	☒ WATER SUPPLY	☐ ABANDONED. INSUFFICIENT SUPPLY
	☐ OBSERVATION WELL	☐ ABANDONED. POOR QUALITY
	☐ TEST HOLE	☐ UNFINISHED
	☐ RECHARGE WELL	
WATER USE <i>21</i>	☒ DOMESTIC	☐ COMMERCIAL
	☐ STOCK	☐ MUNICIPAL
	☐ IRRIGATION	☐ PUBLIC SUPPLY
	☐ INDUSTRIAL	☐ COOLING OR AIR CONDITIONING
	☐ OTHER	☐ NOT USED
METHOD OF DRILLING	☒ CABLE TOOL	☐ BORING
	☐ ROTARY (CONVENTIONAL)	☐ DIAMOND
	☐ ROTARY (REVERSE)	☐ JETTING
	☐ ROTARY (AIR)	☐ DRILING
	☐ AIR PERCUSSION	

LOCATION OF WELL

IN DIAGRAM BELOW SHOW DISTANCES OF WELL FROM ROAD AND LOT LINE INDICATE NORTH BY ARROW

Gull River
 & 200'
 ← 25' →
 Fronting on River
 Lot 33
 Hwy. #259
 7

TRACTOR	NAME OF WELL CONTRACTOR	G. HART AND SONS	LEGISL. NUMBER
	Kenneth H. Hart		2517
	ADDRESS	R.R.1, Fenelon Falls, Ontario	

USE ONLY

DATE APR 12 1968	SYNOPSIS 3517	DATE APR 22 1968	03-00
DATE OF THIS APR 12 1968	ISSUED TO P/T. B.		

64 2881

#64 2881

Pipe and Casing Record

Pumping Test

Static level 15 ft
Pumping rate 300 gal per min
Pumping level 20 ft
Duration of test 1 hr

Well Log

Water Record

[illegible]

For what purpose(s) is the water to be used?

Is water clear or cloudy?.....clear

Is well on upland, in valley, or on hillside?.....

Drilling firm Wm. H. T. & Son

Address 15411 N. 1

Name of Driller S. J. B. B.

Address *London, U.K.*

Licence Number. 11 541


I certify that the foregoing statements of fact are true.

Date Mar 9/62 Easton, Illinois

Signature of Licensee _____

Location of Well

In diagram below show distances of well from road and lot line. Indicate north by arrow.



1640124 RFR

035

U7 67427P

494.550

5900

0444

...

— *Continued*

[illegible]

31

60402151

ESTD

17 0098211

總發行所 東京市丸の内區有樂町一丁目

1985

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

11

51 CASING & OPEN HOLE RECORD

WATER FOUND AT - FEET	KIND OF WATER
1-10	FRESH ☐ SULPHUR ☐ SALTY ☐ MINERAL ☐
10-20	FRESH ☐ SULPHUR ☐ SALTY ☐ MINERAL ☐
20-30	FRESH ☐ SULPHUR ☐ SALTY ☐ MINERAL ☐
30-40	FRESH ☐ SULPHUR ☐ SALTY ☐ MINERAL ☐
40-50	FRESH ☐ SULPHUR ☐ SALTY ☐ MINERAL ☐

[illegible]

SCREEN	SIZES: OF OPENING	21-32	PLATED	24-36	LAGGED	36-50
	MATERIAL AND TYPE		TOUGH		PROOF	UPST
	DEPTH TO TOP OF SCREEN					

61' ~~WELL~~ PLUGGING & SEALING RECORD

DISPATCH AREA		DATE		TIME		PAGE	
FROM	TO	DATE	TIME	DATE	TIME	DATE	TIME
10:00	10:05	10:00	10:05	10:00	10:05	10:00	10:05
10:05	10:10	10:05	10:10	10:05	10:10	10:05	10:10
10:10	10:15	10:10	10:15	10:10	10:15	10:10	10:15
10:15	10:20	10:15	10:20	10:15	10:20	10:15	10:20
10:20	10:25	10:20	10:25	10:20	10:25	10:20	10:25
10:25	10:30	10:25	10:30	10:25	10:30	10:25	10:30
10:30	10:35	10:30	10:35	10:30	10:35	10:30	10:35
10:35	10:40	10:35	10:40	10:35	10:40	10:35	10:40
10:40	10:45	10:40	10:45	10:40	10:45	10:40	10:45
10:45	10:50	10:45	10:50	10:45	10:50	10:45	10:50
10:50	10:55	10:50	10:55	10:50	10:55	10:50	10:55
10:55	11:00	10:55	11:00	10:55	11:00	10:55	11:00
11:00	11:05	11:00	11:05	11:00	11:05	11:00	11:05
11:05	11:10	11:05	11:10	11:05	11:10	11:05	11:10
11:10	11:15	11:10	11:15	11:10	11:15	11:10	11:15
11:15	11:20	11:15	11:20	11:15	11:20	11:15	11:20
11:20	11:25	11:20	11:25	11:20	11:25	11:20	11:25
11:25	11:30	11:25	11:30	11:25	11:30	11:25	11:30
11:30	11:35	11:30	11:35	11:30	11:35	11:30	11:35
11:35	11:40	11:35	11:40	11:35	11:40	11:35	11:40
11:40	11:45	11:40	11:45	11:40	11:45	11:40	11:45
11:45	11:50	11:45	11:50	11:45	11:50	11:45	11:50
11:50	11:55	11:50	11:55	11:50	11:55	11:50	11:55
11:55	12:00	11:55	12:00	11:55	12:00	11:55	12:00
12:00	12:05	12:00	12:05	12:00	12:05	12:00	12:05
12:05	12:10	12:05	12:10	12:05	12:10	12:05	12:10
12:10	12:15	12:10	12:15	12:10	12:15	12:10	12:15
12:15	12:20	12:15	12:20	12:15	12:20	12:15	12:20
12:20	12:25	12:20	12:25	12:20	12:25	12:20	12:25
12:25	12:30	12:25	12:30	12:25	12:30	12:25	12:30
12:30	12:35	12:30	12:35	12:30	12:35	12:30	12:35
12:35	12:40	12:35	12:40	12:35	12:40	12:35	12:40
12:40	12:45	12:40	12:45	12:40	12:45	12:40	12:45
12:45	12:50	12:45	12:50	12:45	12:50	12:45	12:50
12:50	12:55	12:50	12:55	12:50	12:55	12:50	12:55
12:55	13:00	12:55	13:00	12:55	13:00	12:55	13:00
13:00	13:05	13:00	13:05	13:00	13:05	13:00	13:05
13:05	13:10	13:05	13:10	13:05	13:10	13:05	13:10
13:10	13:15	13:10	13:15	13:10	13:15	13:10	13:15
13:15	13:20	13:15	13:20	13:15	13:20	13:15	13:20
13:20	13:25	13:20	13:25	13:20	13:25	13:20	13:25
13:25	13:30	13:25	13:30	13:25	13:30	13	

70 **REPAIRING**

STATIC LEVEL	WATER LEVEL AND OF PUMPING	WATER LEVELS DURING		☐ PUMPING ☐ RECOVERY
055	065	15 MINUTES	30 MINUTES	45 MINUTES
55	65	055	055	055
FEET	FEET	FEET	FEET	FEET
IS FLOWING	PUMP INITIAL SET AT	WATER AT END OF TEST		
DATE	90	CLEAR		☐ CLOUDY
RECOMMENDED PUMP TYPE	RECOMMENDED PUMP	RECOMMENDED	RECOMMENDED	
☐ SMALLLOW	☐ SLIP	SET	PSY	
60-61	60-61	60-61	60-61	
GPM, FFS, SPECIFIC CAPACITY				

LOCATION OF WELL

[illegible]

WELL NO.	WELL TYPE	WELL STATUS	WELL DEPTH	WELL DRAINAGE AREA	WELL LOCATION	WELL OWNER	WELL STATUS	WELL DEPTH	WELL DRAINAGE AREA	WELL LOCATION	WELL OWNER
1	1	1	1	1	1	1	1	1	1	1	1
2	2	2	2	2	2	2	2	2	2	2	2
3	3	3	3	3	3	3	3	3	3	3	3
4	4	4	4	4	4	4	4	4	4	4	4
5	5	5	5	5	5	5	5	5	5	5	5
6	6	6	6	6	6	6	6	6	6	6	6
7	7	7	7	7	7	7	7	7	7	7	7
8	8	8	8	8	8	8	8	8	8	8	8
9	9	9	9	9	9	9	9	9	9	9	9
10	10	10	10	10	10	10	10	10	10	10	10
11	11	11	11	11	11	11	11	11	11	11	11
12	12	12	12	12	12	12	12	12	12	12	12
13	13	13	13	13	13	13	13	13	13	13	13
14	14	14	14	14	14	14	14	14	14	14	14
15	15	15	15	15	15	15	15	15	15	15	15
16	16	16	16	16	16	16	16	16	16	16	16
17	17	17	17	17	17	17	17	17	17	17	17
18	18	18	18	18	18	18	18	18	18	18	18
19	19	19	19	19	19	19	19	19	19	19	19
20	20	20	20	20	20	20	20	20	20	20	20
21	21	21	21	21	21	21	21	21	21	21	21
22	22	22	22	22	22	22	22	22	22	22	22
23	23	23	23	23	23	23	23	23	23	23	23
24	24	24	24	24	24	24	24	24	24	24	24
25	25	25	25	25	25	25	25	25	25	25	25
26	26	26	26	26	26	26	26	26	26	26	26
27	27	27	27	27	27	27	27	27	27	27	27
28	28	28	28	28	28	28	28	28	28	28	28
29	29	29	29	29	29	29	29	29	29	29	29
30	30	30	30	30	30	30	30	30	30	30	30
31	31	31	31	31	31	31	31	31	31	31	31
32	32	32	32	32	32	32	32	32	32	32	32
33	33	33	33	33	33	33	33	33	33	33	33
34	34	34	34	34	34	34	34	34	34	34	34
35	35	35	35	35	35	35	35	35	35	35	35
36	36	36	36	36	36	36	36	36	36	36	36
37	37	37	37	37	37	37	37	37	37	37	37
38	38	38	38	38	38	38	38	38	38	38	38
39	39	39	39	39	39	39	39	39	39	39	39
40	40	40	40	40	40</						

WATER USE 01

☒ DOMESTIC	☐ COMMERCIAL
☐ STOCK	☐ MUNICIPAL
☐ IRRIGATION	☐ PUBLIC SUPPLY
☐ INDUSTRIAL	☐ COOLING OR AIR CONDITIONING
☐ OTHER	☐ NOT USED

METHOD OF DRILLING

NAME OF WELL CONNECTION: **HENRIK POWOY** *Henry* **4512**
 ADDRESS: **REH**

SE ONLY

DATE	DO	DESCRIPTION	DO-44	AMOUNT RECEIVED	DO-44	DO
10/2/52		4512		050477		
DATE OF next	DO	DESCRIPTION				

Ontario

1. POINT OF SALE
2. CHECK
3. CHECK
4. CHECK
5. CHECK
6. CHECK
7. CHECK
8. CHECK
9. CHECK
10. CHECK
11. CHECK
12. CHECK
13. CHECK
14. CHECK
15. CHECK
16. CHECK
17. CHECK
18. CHECK
19. CHECK
20. CHECK
21. CHECK
22. CHECK
23. CHECK
24. CHECK
25. CHECK
26. CHECK
27. CHECK
28. CHECK
29. CHECK
30. CHECK
31. CHECK
32. CHECK
33. CHECK
34. CHECK
35. CHECK
36. CHECK
37. CHECK
38. CHECK
39. CHECK
40. CHECK
41. CHECK
42. CHECK
43. CHECK
44. CHECK
45. CHECK
46. CHECK
47. CHECK
48. CHECK
49. CHECK
50. CHECK
51. CHECK
52. CHECK
53. CHECK
54. CHECK
55. CHECK
56. CHECK
57. CHECK
58. CHECK
59. CHECK
60. CHECK
61. CHECK
62. CHECK
63. CHECK
64. CHECK
65. CHECK
66. CHECK
67. CHECK
68. CHECK
69. CHECK
70. CHECK
71. CHECK
72. CHECK
73. CHECK
74. CHECK
75. CHECK
76. CHECK
77. CHECK
78. CHECK
79. CHECK
80. CHECK
81. CHECK
82. CHECK
83. CHECK
84. CHECK
85. CHECK
86. CHECK
87. CHECK
88. CHECK
89. CHECK
90. CHECK
91. CHECK
92. CHECK
93. CHECK
94. CHECK
95. CHECK
96. CHECK
97. CHECK
98. CHECK
99. CHECK
100. CHECK

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)				
GENERAL COLOUR	MOISTURE CONTENT	OTHER MATERIAL	GENERAL DESCRIPTION	DEPTH - FEET FROM
Grey	Shale	Limestone		0
Grey	Shale	Limestone		1
Grey	Shale	Limestone		2
Grey	Shale	Limestone		3
Grey	Shale	Limestone		4
Grey	Shale	Limestone		5
Grey	Shale	Limestone		6
Grey	Shale	Limestone		7
Grey	Shale	Limestone		8
Grey	Shale	Limestone		9
Grey	Shale	Limestone		10
Grey	Shale	Limestone		11
Grey	Shale	Limestone		12
Grey	Shale	Limestone		13
Grey	Shale	Limestone		14
Grey	Shale	Limestone		15
Grey	Shale	Limestone		16
Grey	Shale	Limestone		17
Grey	Shale	Limestone		18
Grey	Shale	Limestone		19
Grey	Shale	Limestone		20
Grey	Shale	Limestone		21
Grey	Shale	Limestone		22
Grey	Shale	Limestone		23
Grey	Shale	Limestone		24
Grey	Shale	Limestone		25
Grey	Shale	Limestone		26
Grey	Shale	Limestone		27
Grey	Shale	Limestone		28
Grey	Shale	Limestone		29
Grey	Shale	Limestone		30
Grey	Shale	Limestone		31
Grey	Shale	Limestone		32
Grey	Shale	Limestone		33
Grey	Shale	Limestone		34
Grey	Shale	Limestone		35
Grey	Shale	Limestone		36
Grey	Shale	Limestone		37
Grey	Shale	Limestone		38
Grey	Shale	Limestone		39
Grey	Shale	Limestone		40
Grey	Shale	Limestone		41
Grey	Shale	Limestone		42
Grey	Shale	Limestone		43
Grey	Shale	Limestone		44
Grey	Shale	Limestone		45
Grey	Shale	Limestone		46
Grey	Shale	Limestone		47
Grey	Shale	Limestone		48
Grey	Shale	Limestone		49
Grey	Shale	Limestone		50
Grey	Shale	Limestone		51
Grey	Shale	Limestone		52
Grey	Shale	Limestone		53
Grey	Shale	Limestone		54
Grey	Shale	Limestone		55
Grey	Shale	Limestone		56
Grey	Shale	Limestone		57
Grey	Shale	Limestone		58
Grey	Shale	Limestone		59
Grey	Shale	Limestone		60
Grey	Shale	Limestone		61
Grey	Shale	Limestone		62
Grey	Shale	Limestone		63
Grey	Shale	Limestone		64
Grey	Shale	Limestone		65
Grey	Shale	Limestone		66
Grey	Shale	Limestone		67
Grey	Shale	Limestone		68
Grey	Shale	Limestone		69
Grey	Shale	Limestone		70
Grey	Shale	Limestone		71
Grey	Shale	Limestone		72
Grey	Shale	Limestone		73
Grey	Shale	Limestone		74
Grey	Shale	Limestone		75
Grey	Shale	Limestone		76
Grey	Shale	Limestone		77
Grey	Shale	Limestone		78
Grey	Shale	Limestone		79
Grey	Shale	Limestone		80
Grey	Shale	Limestone		81
Grey	Shale	Limestone		82
Grey	Shale	Limestone		83
Grey	Shale	Limestone		84
Grey	Shale	Limestone		85
Grey	Shale	Limestone		86
Grey	Shale	Limestone		87
Grey	Shale	Limestone		88
Grey	Shale	Limestone		89
Grey	Shale	Limestone		90
Grey	Shale	Limestone		91
Grey	Shale	Limestone		92
Grey	Shale	Limestone		93
Grey	Shale	Limestone		94
Grey	Shale	Limestone		95
Grey	Shale	Limestone		96
Grey	Shale	Limestone		97
Grey	Shale	Limestone		98
Grey	Shale	Limestone		99
Grey	Shale	Limestone		100

31. 0006211715 0040215 0060615 0083215 0106415 0129615 0152815 0176015 0199215 0222415 0245615 0268815 0292015 0315215 0338415 0361615 0384815 0408015 0431215 0454415 0477615 0500815 0524015 0547215 0570415 0593615 0616815 0640015 0663215 0686415 0709615 0732815 0756015 0779215 0802415 0825615 0848815 0872015 0895215 0918415 0941615 0964815 0988015 1011215 1034415 1057615 1080815 1104015 1127215 1150415 1173615 1196815 1220015 1243215 1266415 1289615 1312815 1336015 1359215 1382415 1405615 1428815 1452015 1475215 1498415 1521615 1544815 1568015 1591215 1614415 1637615 1660815 1684015 1707215 1730415 1753615 1776815 1800015 1823215 1846415 1869615 1892815 1916015 1939215 1962415 1985615 2008815 2032015 2055215 2078415 2101615 2124815 2148015 2171215 2194415 2217615 2240815 2264015 2287215 2310415 2333615 2356815 2380015 2403215 2426415 2449615 2472815 2496015 2519215 2542415 2565615 2588815 2612015 2635215 2658415 2681615 2704815 2728015 2751215 2774415 2797615 2820815 2844015 2867215 2890415 2913615 2936815 2960015 2983215 3006415 3029615 3052815 3076015 3099215 3122415 3145615 3168815 3192015 3215215 3238415 3261615 3284815 3308015 3331215 3354415 3377615 3400815 3424015 3447215 3470415 3493615 3516815 3540015 3563215 3586415 3609615 3632815 3656015 3679215 3702415 3725615 3748815 3772015 3795215 3818415 3841615 3864815 3888015 3911215 3934415 3957615 3980815 4004015 4027215 4050415 4073615 4096815 4120015 4143215 4166415 4189615 4212815 4236015 4259215 4282415 4305615 4328815 4352015 4375215 4398415 4421615 4444815 4468015 4491215 4514415 4537615 4560815 4584015 4607215 4630415 4653615 4676815 4700015 4723215 4746415 4769615 4792815 4816015 4839215 4862415 4885615 4908815 4932015 4955215 4978415 5001615 5024815 5048015 5071215 5094415 5117615 5140815 5164015 5187215 5210415 5233615 5256815 5280015 5303215 5326415 5349615 5372815 5396015 5419215 5442415 5465615 5488815 5512015 5535215 5558415 5581615 5604815 5628015 5651215 5674415 5697615 5720815 5744015 5767215 5790415 5813615 5836815 5860015 5883215 5906415 5929615 5952815 5976015 5999215 6022415 6045615 6068815 6092015 6115215 6138415 6161615 6184815 6208015 6231215 6254415 6277615 6300815 6324015 6347215 6370415 6393615 6416815 6440015 6463215 6486415 6509615 6532815 6556015 6579215 6602415 6625615 6648815 6672015 6695215 6718415 6741615 6764815 6788015 6811215 6834415 6857615 6880815 6904015 6927215 6950415 6973615 6996815 7020015 7043215 7066415 7089615 7112815 7136015 7159215 7182415 7205615 7228815 7252015 7275215 7298415 7321615 7344815 7368015 7391215 7414415 7437615 7460815 7484015 7507215 7530415 7553615 7576815 7600015 7623215 7646415 7669615 7692815 7716015 7739215 7762415 7785615 7808815 7832015 7855215 7878415 7901615 7924815 7948015 7971215 7994415 8017615 8040815 8064015 8087215 8110415 8133615 8156815 8180015 8203215 8226415 8249615 8272815 8296015 8319215 8342415 8365615 8388815 8412015 8435215 8458415 8481615 8504815 8528015 8551215 8574415 8597615 8620815 8644015 8667215 8690415 8713615 8736815 8760015 8783215 8806415 8829615 8852815 8876015 8899215 8922415 8945615 8968815 8992015 9015215 9038415 9061615 9084815 9108015 9131215 9154415 9177615 9200815 9224015 9247215 9270415 9293615 9316815 9340015 9363215 9386415 9409615 9432815 9456015 9479215 9502415 9525615 9548815 9572015 9595215 9618415 9641615 9664815 9688015 9711215 9734415 9757615 9780815 9804015 9827215 9850415 9873615 9896815 9920015 9943215 9966415 9989615 10012815 10036015 10059215 10082415 10105615 10128815 10152015 10175215 10198415 10221615 10244815 10268015 10291215 10314415 10337615 10360815 10384015 10407215 10430415 10453615 10476815 10500015 10523215 10546415 10569615 10592815 10616015 10639215 10662415 10685615 10708815 10732015 10755215 10778415 10801615 10824815 10848015 10871215 10894415 10917615 10940815 10964015 10987215 11010415 11033615 11056815 11080015 11103215 11126415 11149615 11172815 11196015 11219215 11242415 11265615 11288815 11312015 11335215 11358415 11381615 11404815 11428015 11451215 11474415 11497615 11520815 11544015 11567215 11590415 11613615 11636815 11660015 11683215 11706415 11729615 11752815 11776015 11799215 11822415 11845615 11868815 11892015 11915215 11938415 11961615 11984815 12008015 12031215 12054415 12077615 12100815 12124015 12147215 12170415 12193615 12216815 12240015 12263215 12286415 12309615 12332815 12356015 12379215 12402415 12425615 12448815 12472015 12495215 12518415 12541615 12564815 12588015 12611215 12634415 12657615 12680815 12704015 12727215 12750415 12773615 12796815 12820015 12843215 12866415 12889615 12912815 12936015 12959215 12982415 13005615 13028815 13052015 13075215 13098415 13121615 13144815 13168015 13191215 13214415 13237615 13260815 13284015 13307215 13330415 13353615 13376815 13400015 13423215 13446415 13469615 13492815 13516015 13539215 13562415 13585615 13608815 13632015 13655215 13678415 13701615 13724815 13748015 13771215 13794415 13817615 13840815 13864015 13887215 13910415 13933615 13956815 13980015 14003215 14026415 14049615 14072815 14096015 14119215 14142415 14165615 14188815 14212015 14235215 14258415 14281615 14304815 14328015 14351215 14374415 14397615 14420815 14444015 14467215 14490415 14513615 14536815 14560015 14583215 14606415 14629615 14652815 14676015 14699215 14722415 14745615 14768815 14792015 14815215 14838415 14861615 14884815 14908015 14931215 14954415 14977615 15000815 15024015 15047215 15070415 15093615 15116815 15140015 15163215 15186415 15209615 15232815 15256015 15279215 15302415 15325615 15348815 15372015 15395215 15418415 15441615 15464815 15488015 15511215 15534415 15557615 15580815 15604015 15627215 15650415 15673615 15696815 15720015 15743215 15766415 15789615 15812815 15836015 15859215 15882415 15905615 15928815 15952015 15975215 15998415 16021615 16044815 16068015 16091215 16114415 16137615 16160815 16184015 16207215 16230415 16253615 16276815 16300015 16323215 16346415 16369615 16392815 16416015 16439215 16462415 16485615 16508815 16532015 16555215 16578415 16601615 16624815 16648015 16671215 16694415 16717615 16740815 16764015 16787215 16810415 16833615 16856815 16880015 16903215 16926415 16949615 16972815 16996015 17019215 17042415 17065615 17088815 17112015 17135215 17158415 17181615 17204815 17228015 17251215 17274415 17297615 17320815 17344015 17367215 17390415 17413615 17436815 17460015 17483215 17506415 17529615 17552815 17576015 17599215 17622415 17645615 17668815 17692015 17715215 17738415 17761615 17784815 17808015 17831215 17854415 17877615 17900815 17924015 17947215 17970415 17993615 18016815 18040015 18063215 18086415 18109615 18132815 18156015 18179215 18202415 18225615 18248815 18272015 18295215 18318415 18341615 18364815 18388015 18411215 18434415 18457615 18480815 18504015 18527215 18550415 18573615 18596815 18620015 18643215 18666415 18689615 18712815 18736015 18759215 18782415 18805615 18828815 18852015 18875215 18898415 18921615 18944815 18968015 18991215 19014415 19037615 19060815 19084015 19107215 19130415 19153615 19176815 19200015 19223215 19246415 19269615 19292815 19316015 19339215 19362415 19385615 19408815 19432015 19455215 19478415 19501615 19524815 19548015 19571215 19594415 19617615 19640815 19664015 19687215 19710415 19733615 19756815 19780015 19803215 19826415 19849615 19872815 19896015 19919215 19942415 19965615 19988815 20012015 20035215 20058415 20081615 20104815 20128015 20151215 20174415 20197615 20220815 20244015 20267215 20290415 20313615 20336815 20360015 20383215 20406415 20429615 20452815 20476015 20499215 20522415 20545615 20568815 20592015 20615215 20638415 20661615 20684815 20708015 20731215 20754415 20777615 20800815 20824015 20847215 20870415 20893615 20916815 20940015 20963215 20986415 21009615 21032815 21056015 21079215 21102415 21125615 21148815 21172015 21195215 21218415 21241615 21264815 21288015 21311215 21334415 21357615 21380815 21404015 21427215 21450415 21473615 2149681



of the
Environment,
Ontario

17/80

THE ONTARIO WATER RESOURCES ACT

WATER WELL RECORD

1. POINT ONLY IN SPACES PROVIDED
2. CHECK ☒ CORRECT; ☐ WHERE APPLICABLE

11

6411200

64012

CON.

NAME OF DISTRICT *West* TOWN *Somerville* CON. BLOCK, TRACT, SHED, ETC. *Front Range* LOT *35*
OWNER (PERSON OR FIRM) *Mitchell, L.* ADDRESS *Cobourg* DATE *17-5-88*
WELL NO. *21*

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)

GENERAL COLOUR	MOST COMMON MATERIAL	OTHER MATERIALS	GENERAL DESCRIPTION	DEPTH - FEET	
				FROM	TO
	<i>Topsoil</i>			0	1
	<i>Clay</i>			1	4
	<i>Limestone</i>			4	92

31
32

41 WATER RECORD

WATER FOUND AT FEET	KIND OF WATER
90	☒ FRESH ☐ SALTY
	☐ SULPHUR ☐ MINERALS ☐ GAS
	☐ FRESH ☐ SALTY
	☐ SULPHUR ☐ MINERALS ☐ GAS
	☐ FRESH ☐ SALTY
	☐ SULPHUR ☐ MINERALS ☐ GAS
	☐ FRESH ☐ SALTY
	☐ SULPHUR ☐ MINERALS ☐ GAS

51 CASING & OPEN HOLE RECORD

1-24 IN. FEET	MATERIAL	24-30 IN. FEET	DEPTH - FEET
64	☒ STEEL ☐ GALVANIZED ☐ CONCRETE ☐ OPEN HOLE ☐ PLASTIC	188	0.21

SCREEN

SIZE OF OPENING (SLOT NO.)	31-32	33-34	35-36	37-38	39-40
MATERIAL AND TYPE					
DEPTH TO TOP OF SCREEN					
FEET					

61 PLUGGING & SEALING RECORD

DEPTH SET AT - FEET	MATERIAL AND TYPE	CEMENT GROUT
FROM	TO	LOAD PNEUMATIC ETC.
00-01	01-02	
02-03	03-04	
04-05	05-06	

71 PUMPING TEST

PUMPING TEST METHOD	NO. 1 PUMP NO. 2 SAILER	NO. 3 PUMPING RATE	NO. 4 DURATION OF PUMPING
		20	1
STATIC LEVEL	WATER LEVEL	WATER LEVEL DURING	WATER LEVEL DURING
31	60	15 MINUTES	30 MINUTES
		45 MINUTES	60 MINUTES
		75 MINUTES	90 MINUTES
		105 MINUTES	120 MINUTES
		135 MINUTES	150 MINUTES
		165 MINUTES	180 MINUTES
		195 MINUTES	210 MINUTES
		225 MINUTES	240 MINUTES
		255 MINUTES	270 MINUTES
		285 MINUTES	300 MINUTES
		315 MINUTES	330 MINUTES
		345 MINUTES	360 MINUTES
		375 MINUTES	390 MINUTES
		405 MINUTES	420 MINUTES
		435 MINUTES	450 MINUTES
		465 MINUTES	480 MINUTES
		495 MINUTES	510 MINUTES
		525 MINUTES	540 MINUTES
		555 MINUTES	570 MINUTES
		585 MINUTES	600 MINUTES
		615 MINUTES	630 MINUTES
		645 MINUTES	660 MINUTES
		675 MINUTES	690 MINUTES
		705 MINUTES	720 MINUTES
		735 MINUTES	750 MINUTES
		765 MINUTES	780 MINUTES
		795 MINUTES	810 MINUTES
		825 MINUTES	840 MINUTES
		855 MINUTES	870 MINUTES
		885 MINUTES	900 MINUTES
		915 MINUTES	930 MINUTES
		945 MINUTES	960 MINUTES
		975 MINUTES	990 MINUTES
		1005 MINUTES	1020 MINUTES
		1035 MINUTES	1050 MINUTES
		1065 MINUTES	1080 MINUTES
		1095 MINUTES	1110 MINUTES
		1125 MINUTES	1140 MINUTES
		1155 MINUTES	1170 MINUTES
		1185 MINUTES	1200 MINUTES
		1215 MINUTES	1230 MINUTES
		1245 MINUTES	1260 MINUTES
		1275 MINUTES	1290 MINUTES
		1305 MINUTES	1320 MINUTES
		1335 MINUTES	1350 MINUTES
		1365 MINUTES	1380 MINUTES
		1395 MINUTES	1410 MINUTES
		1425 MINUTES	1440 MINUTES
		1455 MINUTES	1470 MINUTES
		1485 MINUTES	1500 MINUTES
		1515 MINUTES	1530 MINUTES
		1545 MINUTES	1560 MINUTES
		1575 MINUTES	1590 MINUTES
		1605 MINUTES	1620 MINUTES
		1635 MINUTES	1650 MINUTES
		1665 MINUTES	1680 MINUTES
		1695 MINUTES	1710 MINUTES
		1725 MINUTES	1740 MINUTES
		1755 MINUTES	1770 MINUTES
		1785 MINUTES	1800 MINUTES
		1815 MINUTES	1830 MINUTES
		1845 MINUTES	1860 MINUTES
		1875 MINUTES	1890 MINUTES
		1905 MINUTES	1920 MINUTES
		1935 MINUTES	1950 MINUTES
		1965 MINUTES	1980 MINUTES
		1995 MINUTES	2010 MINUTES
		2025 MINUTES	2040 MINUTES
		2055 MINUTES	2070 MINUTES
		2085 MINUTES	2100 MINUTES
		2115 MINUTES	2130 MINUTES
		2145 MINUTES	2160 MINUTES
		2175 MINUTES	2190 MINUTES
		2205 MINUTES	2220 MINUTES
		2235 MINUTES	2250 MINUTES
		2265 MINUTES	2280 MINUTES
		2295 MINUTES	2310 MINUTES
		2325 MINUTES	2340 MINUTES
		2355 MINUTES	2370 MINUTES
		2385 MINUTES	2400 MINUTES
		2415 MINUTES	2430 MINUTES
		2445 MINUTES	2460 MINUTES
		2475 MINUTES	2490 MINUTES
		2505 MINUTES	2520 MINUTES
		2535 MINUTES	2550 MINUTES
		2565 MINUTES	2580 MINUTES
		2595 MINUTES	2610 MINUTES
		2625 MINUTES	2640 MINUTES
		2655 MINUTES	2670 MINUTES
		2685 MINUTES	2700 MINUTES
		2715 MINUTES	2730 MINUTES
		2745 MINUTES	2760 MINUTES
		2775 MINUTES	2790 MINUTES
		2805 MINUTES	2820 MINUTES
		2835 MINUTES	2850 MINUTES
		2865 MINUTES	2880 MINUTES
		2895 MINUTES	2910 MINUTES
		2925 MINUTES	2940 MINUTES
		2955 MINUTES	2970 MINUTES
		2985 MINUTES	3000 MINUTES
		3015 MINUTES	3030 MINUTES
		3045 MINUTES	3060 MINUTES
		3075 MINUTES	3090 MINUTES
		3105 MINUTES	3120 MINUTES
		3135 MINUTES	3150 MINUTES
		3165 MINUTES	3180 MINUTES
		3195 MINUTES	3210 MINUTES
		3225 MINUTES	3240 MINUTES
		3255 MINUTES	3270 MINUTES
		3285 MINUTES	3300 MINUTES
		3315 MINUTES	3330 MINUTES
		3345 MINUTES	3360 MINUTES
		3375 MINUTES	3390 MINUTES
		3405 MINUTES	3420 MINUTES
		3435 MINUTES	3450 MINUTES
		3465 MINUTES	3480 MINUTES
		3495 MINUTES	3510 MINUTES
		3525 MINUTES	3540 MINUTES
		3555 MINUTES	3570 MINUTES
		3585 MINUTES	3600 MINUTES
		3615 MINUTES	3630 MINUTES
		3645 MINUTES	3660 MINUTES
		3675 MINUTES	3690 MINUTES
		3705 MINUTES	3720 MINUTES
		3735 MINUTES	3750 MINUTES
		3765 MINUTES	3780 MINUTES
		3795 MINUTES	3810 MINUTES
		3825 MINUTES	3840 MINUTES
		3855 MINUTES	3870 MINUTES
		3885 MINUTES	3900 MINUTES
		3915 MINUTES	3930 MINUTES
		3945 MINUTES	3960 MINUTES
		3975 MINUTES	3990 MINUTES
		4005 MINUTES	4020 MINUTES
		4035 MINUTES	4050 MINUTES
		4065 MINUTES	4080 MINUTES
		4095 MINUTES	4110 MINUTES
		4125 MINUTES	4140 MINUTES
		4155 MINUTES	4170 MINUTES
		4185 MINUTES	4200 MINUTES
		4215 MINUTES	4230 MINUTES
		4245 MINUTES	4260 MINUTES
		4275 MINUTES	4290 MINUTES
		4305 MINUTES	4320 MINUTES
		4335 MINUTES	4350 MINUTES
		4365 MINUTES	4380 MINUTES
		4395 MINUTES	4410 MINUTES
		4425 MINUTES	4440 MINUTES
		4455 MINUTES	4470 MINUTES
		4485 MINUTES	4500 MINUTES
		4515 MINUTES	4530 MINUTES
		4545 MINUTES	4560 MINUTES
		4575 MINUTES	4590 MINUTES
		4605 MINUTES	4620 MINUTES
		4635 MINUTES	4650 MINUTES
		4665 MINUTES	4680 MINUTES
		4695 MINUTES	4710 MINUTES
		4725 MINUTES	4740 MINUTES
		4755 MINUTES	4770 MINUTES
		4785 MINUTES	4800 MINUTES
		4815 MINUTES	4830 MINUTES
		4845 MINUTES	4860 MINUTES
		4875 MINUTES	4890 MINUTES
		4905 MINUTES	4920 MINUTES
		4935 MINUTES	4950 MINUTES
		4965 MINUTES	4980 MINUTES
		4995 MINUTES	5010 MINUTES
		5025 MINUTES	5040 MINUTES
		5055 MINUTES	5070 MINUTES
		5085 MINUTES	5100 MINUTES
		5115 MINUTES	5130 MINUTES
		5145 MINUTES	5160 MINUTES
		5175 MINUTES	5190 MINUTES
		5205 MINUTES	5220 MINUTES
		5235 MINUTES	5250 MINUTES
		5265 MINUTES	5280 MINUTES
		5295 MINUTES	5310 MINUTES
		5325 MINUTES	5340 MINUTES
		5355 MINUTES	5370 MINUTES
		5385 MINUTES	5400 MINUTES
		5415 MINUTES	5430 MINUTES
		5445 MINUTES	5460 MINUTES
		5475 MINUTES	5490 MINUTES
		5505 MINUTES	5520 MINUTES
		5535 MINUTES	5550 MINUTES
		5565 MINUTES	5580 MINUTES
		5595 MINUTES	5610 MINUTES
		5625 MINUTES	5640 MINUTES
		5655 MINUTES	5670 MINUTES
		5685 MINUTES	5700 MINUTES
		5715 MINUTES	5730 MINUTES
		5745 MINUTES	5760 MINUTES
		5775 MINUTES	5790 MINUTES
		5805 MINUTES	5820 MINUTES
		5835 MINUTES	5850 MINUTES
		5865 MINUTES	5880 MINUTES
		5895 MINUTES	5910 MINUTES
		5925 MINUTES	5940 MINUTES
		5955 MINUTES	5970 MINUTES
		5985 MINUTES	6000 MINUTES
		6015 MINUTES	6030 MINUTES
		6045 MINUTES	6060 MINUTES
		6075 MINUTES	6090 MINUTES
		6105 MINUTES	6120 MINUTES
		6135 MINUTES	6150 MINUTES
		6165 MINUTES	6180 MINUTES
		6195 MINUTES	6210 MINUTES
		6225 MINUTES	6240 MINUTES
		6255 MINUTES	6270 MINUTES
		6285 MINUTES	6300 MINUTES
		6315 MINUTES	6330 MINUTES
		6345 MINUTES	6360 MINUTES
		6375 MINUTES	6390 MINUTES
		6405 MINUTES	6420 MINUTES
		6435 MINUTES	6450 MINUTES
		6465 MINUTES	6480 MINUTES
		6495 MINUTES	6510 MINUTES
		6525 MINUTES	6540 MINUTES
		6555 MINUTES	6570 MINUTES
		6585 MINUTES	6600 MINUTES
		6615 MINUTES	6630 MINUTES
		6645 MINUTES	6660 MINUTES
		6675 MINUTES	6690 MINUTES
		6705 MINUTES	6720 MINUTES
		6735 MINUTES	6750 MINUTES
		6765 MINUTES	6780 MINUTES
		6795 MINUTES	6810 MINUTES
		6825 MINUTES	6840 MINUTES
		6855 MINUTES	6870 MINUTES
		6885 MINUTES	6900 MINUTES
		6915 MINUTES	6930 MINUTES
		6945 MINUTES	6960 MINUTES
		6975 MINUTES	6990 MINUTES
		7005 MINUTES	7020 MINUTES
		7035 MINUTES	7050 MINUTES
		7065 MINUTES	7080 MINUTES
		7095 MINUTES	7110 MINUTES
		7125 MINUTES	7140 MINUTES
		7155 MINUTES	7170 MINUTES
		7185 MINUTES	7200 MINUTES
		7215 MINUTES	7230 MINUTES
		7245 MINUTES	7260 MINUTES
		7275 MINUTES	7290 MINUTES
		7305 MINUTES	7320 MINUTES
		7335 MINUTES	7350 MINUTES
		7365 MINUTES	7380 MINUTES
		7395 MINUTES	7410 MINUTES
		7425 MINUTES	7440 MINUTES
		7455 MINUTES	7470 MINUTES
		7485 MINUTES	7500 MINUTES
		7515 MINUTES	7530 MINUTES
		7545 MINUTES	7560 MINUTES
		7575 MINUTES	7590 MINUTES
		7605 MINUTES	7620 MINUTES
		7635 MINUTES	7650 MINUTES
		7665 MINUTES	7680 MINUTES
		7695 MINUTES	7710 MINUTES
		7725 MINUTES	7740 MINUTES
		7755 MINUTES	7770 MINUTES
		7785 MINUTES	7800 MINUTES
		7815 MINUTES	7830 MINUTES
		7845 MINUTES	7860 MINUTES
		7875 MINUTES	7890 MINUTES
		7905 MINUTES	7920 MINUTES
		7935 MINUTES	7950 MINUTES
		7965 MINUTES	7980 MINUTES
		7995 MINUTES	8010 MINUTES
		8025 MINUTES	8040 MINUTES
		8055 MINUTES	8070 MINUTES
		8085 MINUTES	8100 MINUTES
		8115 MINUTES	8130 MINUTES
		8145 MINUTES	8160 MINUTES
		8175 MINUTES	8190 MINUTES
		8205 MINUTES	8220 MINUTES
		8235 MINUTES	8250 MINUTES
		8265 MINUTES	8280 MINUTES
		8295 MINUTES	8310 MINUTES
		8325 MINUTES	8340 MINUTES
		8355 MINUTES	8370 MINUTES
		8385 MINUTES	8400 MINUTES
		8415 MINUTES	8430 MINUTES
		8445 MINUTES	8460 MINUTES
		8475 MINUTES	8490 MINUTES
		8505 MINUTES	8520 MINUTES
		8535 MINUTES	8550 MINUTES
		8565 MINUTES	8580 MINUTES
		8595 MINUTES	8610 MINUTES
		8625 MINUTES	8640 MINUTES
		8655 MINUTES	8670 MINUTES
		8685 MINUTES	8700 MINUTES
		8715 MINUTES	8730 MINUTES
		8745 MINUTES	8760 MINUTES
		8775 MINUTES	8790 MINUTES
		8805 MINUTES	8820 MINUTES
		8835 MINUTES	8850 MINUTES
		8865 MINUTES	8880 MINUTES
		8895 MINUTES	8910 MINUTES
		8925 MINUTES	8940 MINUTES
		8955 MINUTES	8970 MINUTES
		8985 MINUTES	9000 MINUTES
		9015 MINUTES	9030 MINUTES
		9045 MINUTES	9060 MINUTES
		9075 MINUTES	9090 MINUTES
		9105 MINUTES	9120 MINUTES
		9135 MINUTES	9150 MINUTES
		9165 MINUTES	9180 MINUTES
		9195 MINUTES	9210 MINUTES
		9225 MINUTES	9240 MINUTES



The Ontario Water Resources Commission Act

WATER WELL RECORD



County or District FRANKLIN Township, Village, Town or City SCARBOROUGH
Date completed 10 month JAN year 1964
Owner H. OLSEN Address Cabot Park
(print in block letters)

Casing and Screen Record	Pumping Test
Inside diameter of casing <u>6 1/2"</u>	Static level <u>40 ft</u>
Total length of casing <u>96 ft</u>	Test-pumping rate <u>12</u> G.P.M.
Type of screen	Pumping level <u>50 ft</u>
Length of screen	Duration of test pumping <u>20 HRS.</u>
Depth to top of screen	Water clear or cloudy at end of test <u>CLEAR</u>
Diameter of finished hole <u>6 1/2"</u>	Recommended pumping rate <u>12</u> G.P.M.
	with pump setting of <u>90</u> feet below ground surface

Well Log		Water Record		
Overburden and Bedrock Record		From ft.	To ft.	Depth(s) at which water(s) found
SHALE Rock		0	3	
LIMESTONE Rock		3	96	
RED GRANITE		96	115	

For what purpose(s) is the water to be used? HOUSE & GARAGE
Is well on upland, in valley, or on hillside? UPLAND
Drilling or Boring Firm C. HART & SON
Address R. R. #1
FENELTON FALLS
Licence Number 818
Name of Driller or Borer CON HART
Address SAME AS ABOVE
Date JAN 14 1964
D. C. Hart
(Signature of Licensed Drilling or Boring Contractor)

Location of Well
In diagram below show distances of well from road and lot line. Indicate north by arrow.

Owner DEPT OF HIGHWAYS Shed Address #2883
Date completed 1 NOV 56
(day) (month) (year)

Pipe and Casing Record

Pumping Test

Casing diameter(s) 3.5

Length(s) 75

Type of screen 2.5

Length of screen 249

Static level 25

Pumping rate 250 GPH

Pumping level 25

Duration of test 249

Well Log

Water Record

Overburden and Bedrock Record

From
ft.

To
ft.

Depth (s)
at which
water (s)
found

No. of feet
water rises

Kind of water
(fresh, salty
or sulphur)

CRAY-LINE STONE

0

102

98

77

FRESH

For what purpose(s) is the water to be used?

HOUSEHOLD

Is water clear or cloudy? CLEAR

Is well on upland, in valley, or on hillside? UPLAND

Drilling firm

Address

Name of Driller P. D. WENDEL

Address CRAY-LINE STONE

Licence Number 27


I certify that the foregoing
statements of fact are true.

Date Nov 21 1957

Signature of Licensee

Location of Well

In diagram below show distances of well from
road and lot line. Indicate north by arrow.



Water Well Record

Pipe and Casing Record

Pumping Test

Date _____
Developed Capacity _____
Duration of Test _____
Pumping Rate _____
Drawdown _____
Static level of completed well _____
Is well a gravel-wall type? _____

Water Record

Enclose a copy of any mineral analysis that has been made of water. *None*

[illegible]

Well Log

[illegible]

Location of Well

In diagram below show distances of well from road and lot line

Cobocenk. - 17

Cobocenk.

Highway 35

Situation: Is well on upland, in valley, or on hillside? . . . upland

Drilling Firm *L. F. Means*

15/92

The Ontario Water Resources Act

511/0

WATER WELL RECORD

6408778

64012 REC

con
REC

DATE OF DISCHARGE

1985-86 Budget Call for Action

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

WILMS, JOHN
John Wilms

Cabovank

ETC *Q36*
FRC
DATE COMPLETED *80-51*
DAY *20* MONTH *07* YEAR *81*

DATE	READING	ODMETER	BC	ELEVATION	DC	MARK CODE	DI	DI1	DI2
1/7	6749.00	49468.50	5	09.00	6	24			

WILMS, rohn

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)

[illegible]

MOE
VF-18

41 WATER RECORD

AIES FOUND AT 1915		SIDE OF ROAD		
10-12	1	1	1	1
10-13	1	1	1	1
10-14	1	1	1	1
10-15	1	1	1	1
10-16	1	1	1	1
10-17	1	1	1	1
10-18	1	1	1	1
10-19	1	1	1	1
10-20	1	1	1	1
10-21	1	1	1	1
10-22	1	1	1	1
10-23	1	1	1	1
10-24	1	1	1	1
10-25	1	1	1	1
10-26	1	1	1	1
10-27	1	1	1	1
10-28	1	1	1	1
10-29	1	1	1	1
10-30	1	1	1	1

CASING & OPEN HOLE RECORD

collegi book	DATE	NO.	NAME	NO.
100	1	100	100	100
100	2	100	100	100
100	3	100	100	100
100	4	100	100	100
100	5	100	100	100
100	6	100	100	100
100	7	100	100	100
100	8	100	100	100
100	9	100	100	100
100	10	100	100	100
100	11	100	100	100
100	12	100	100	100
100	13	100	100	100
100	14	100	100	100
100	15	100	100	100
100	16	100	100	100
100	17	100	100	100
100	18	100	100	100
100	19	100	100	100
100	20	100	100	100
100	21	100	100	100
100	22	100	100	100
100	23	100	100	100
100	24	100	100	100
100	25	100	100	100
100	26	100	100	100
100	27	100	100	100
100	28	100	100	100
100	29	100	100	100
100	30	100	100	100
100	31	100	100	100
100	32	100	100	100
100	33	100	100	100
100	34	100	100	100
100	35	100	100	100
100	36	100	100	100
100	37	100	100	100
100	38	100	100	100
100	39	100	100	100
100	40	100	100	100
100	41	100	100	100
100	42	100	100	100
100	43	100	100	100
100	44	100	100	100
100	45	100	100	100
100	46	100	100	100
100	47	100	100	100
100	48	100	100	100
100	49	100	100	100
100	50	100	100	100
100	51	100	100	100
100	52	100	100	100
100	53	100	100	100
100	54	100	100	100
100	55	100	100	100
100	56	100	100	100
100	57	100	100	100
100	58	100	100	100
100	59	100	100	100
100	60	100	100	100
100	61	100	100	100
100	62	100	100	100
100	63	100	100	100
100	64	100	100	100
100	65	100	100	100
100	66	100	100	100
100	67	100	100	100
100	68	100	100	100
100	69	100	100	100
100	70	100	100	100
100	71	100	100	100
100	72	100	100	100
100	73	100	100	100
100	74	100	100	100
100	75	100	100	100
100	76	100	100	100
100	77	100	100	100
100	78	100	100	100
100	79	100	100	100
100	80	1		

SCREEN	SIZE - 5" x 30" 10000000	30-30	30-30	30-30	30-30
	MATERIAL AND TYPE		30-30	30-30	30-30

61		PLUGGING & SEALING RECORD	
DEPTH SET AT	FEET	MATERIAL AND TYPE	STAMP NO.
10-00	TO		100-100-100-100
10-02	10-07		
10-08	10-10		
10-12	10-15		

PUMPING TEST DATA SHEET		NO. 10		PUMPING SET		NO. 10		LOCATION OF PUMPING	
1. PUMP NO. 001		0005		1000		24		00	
2. DATE		01-01		00-00		00-00		00-00	
3. TIME		00-00		00-00		00-00		00-00	
4. PUMPING SET		00-00		00-00		00-00		00-00	
5. PUMPING SET		00-00		00-00		00-00		00-00	
6. PUMPING SET		00-00		00-00		00-00		00-00	
7. PUMPING SET		00-00		00-00		00-00		00-00	
8. PUMPING SET		00-00		00-00		00-00		00-00	
9. PUMPING SET		00-00		00-00		00-00		00-00	
10. PUMPING SET		00-00		00-00		00-00		00-00	
11. PUMPING SET		00-00		00-00		00-00		00-00	
12. PUMPING SET		00-00		00-00		00-00		00-00	
13. PUMPING SET		00-00		00-00		00-00		00-00	
14. PUMPING SET		00-00		00-00		00-00		00-00	
15. PUMPING SET		00-00		00-00		00-00		00-00	
16. PUMPING SET		00-00		00-00		00-00		00-00	
17. PUMPING SET		00-00		00-00		00-00		00-00	
18. PUMPING SET		00-00		00-00		00-00		00-00	
19. PUMPING SET		00-00		00-00		00-00		00-00	
20. PUMPING SET		00-00		00-00		00-00		00-00	
21. PUMPING SET		00-00		00-00		00-00		00-00	
22. PUMPING SET		00-00		00-00		00-00		00-00	
23. PUMPING SET		00-00		00-00		00-00		00-00	
24. PUMPING SET		00-00		00-00		00-00		00-00	
25. PUMPING SET		00-00		00-00		00-00		00-00	
26. PUMPING SET		00-00		00-00		00-00		00-00	
27. PUMPING SET		00-00		00-00		00-00		00-00	
28. PUMPING SET		00-00		00-00		00-00		00-00	
29. PUMPING SET		00-00		00-00		00-00		00-00	
30. PUMPING SET		00-00		00-00		00-00		00-00	
31. PUMPING SET		00-00		00-00		00-00		00-00	
32. PUMPING SET		00-00		00-00		00-00		00-00	
33. PUMPING SET		00-00		00-00		00-00		00-00	
34. PUMPING SET		00-00		00-00		00-00		00-00	
35. PUMPING SET		00-00		00-00		00-00		00-00	
36. PUMPING SET		00-00		00-00		00-00		00-00	
37. PUMPING SET		00-00		00-00		00-00		00-00	
38. PUMPING SET		00-00		00-00		00-00		00-00	
39. PUMPING SET		00-00		00-00		00-00		00-00	
40. PUMPING SET		00-00		00-00		00-00		00-00	
41. PUMPING SET		00-00		00-00		00-00		00-00	
42. PUMPING SET		00-00		00-00		00-00		00-00	
43. PUMPING SET		00-00		00-00		00-00		00-00	
44. PUMPING SET		00-00		00-00		00-00		00-00	
45. PUMPING SET		00-00		00-00		00-00		00-00	
46. PUMPING SET		00-00		00-00		00-00		00-00	
47. PUMPING SET		00-00		00-00		00-00		00-00	
48. PUMPING SET		00-00		00-00		00-00		00-00	
49. PUMPING SET		00-00		00-00		00-00		00-00	
50. PUMPING SET		00-00		00-00		00-00		00-00	
51. PUMPING SET		00-00		00-00		00-00		00-00	

LOCATION OF WELL

IN DIAGRAM BELOW SHOW DISTANCES OF WELL FROM ROAD AND LOT LINE INDICATE NORTH BY ARROW

A hand-drawn map showing the intersection of Groll River, Coboc, Moose Line Rd, and 6 Con well.

5367.

OFFICE USE ONLY	DATA SOURCE	NO	CONTRACT NO	DO-02	DATE RECEIVED	1988
	1		5415		29 01 82	
	DATE OF INSPECTION		INSPECTION			
COMMENTS						

CONTRACTOR

NAME OF WELL CONTRACTOR		SEALING NUMBER
Jordan Weaver		5415
ADDRESS		
Calabow		
NAME OF DEALER OR OWNER		SEALING NUMBER
Weaver and Willey		5415
SIGNATURE OF CONTRACTOR		EXPIRATION DATE
Jordan Weaver		Oct 13 1981



64 No

2886

The Ontario Water Resources Commission Act

WATER WELL RECORD

Basin
County or District

VICTORIA

Township, Village, Town or City SOMERVILLE

Con.

T. RANGE

Lot 36

Date completed

14

JULY

1966

Owner

MR. TIM BRADDOCK

(print in block letters)

Address

R. R. #1, FENELON FALLS

Casing and Screen Record

Pumping Test

Inside diameter of casing

6 1/4"

Total length of casing

9'

Type of screen

Length of screen

Depth to top of screen

Diameter of finished hole

6 1/4"

Static level

9'

Test-pumping rate

3

G.P.M.

Pumping level

empty

Duration of test pumping

3 hrs.

Water clear or cloudy at end of test

clear

Recommended pumping rate

2

G.P.M.

with pump setting of

50'

feet below ground surface

Well Log

Water Record

Overburden and Bedrock Record

From ft.

To ft.

Depth(s) at which water(s) found

Kind of water (fresh, salty, sulphur)

TOP SOIL

0

1

17

FRESH

LIMESTONE ROCK

1

52

For what purpose(s) is the water to be used?

HOUSE

UPLAND

Is well on upland, in valley, or on hillside?

Drilling or Boring Firm

G. HART & SONS

Address

R. R. #1, FENELON FALLS

Licence Number

2242

Name of Driller or Borer

DONALD HART

Address

R. R. #1, FENELON FALLS


Date

JULY 14, 1966

(Signature of Licensed Drilling or Boring Contractor)

Location of Well

In diagram below show distances of well from road and lot line. Indicate north by arrow.



Form 7 15M-60-4138

O.W.R.C. COPY



1st RANGE

The Ontario Water Resources Commission Act

WATER RESOURCES DIVISION

230900

WATER WELL RECORD

1966

City or District *Victoria*

Township, Village, Town or City *Seaton*

Con. *7*

Lot *36 Range*

Date completed *25 March 1966*

Owner *Gilbert Mitchell*

Address *P.O. Box 1, Cobocant, Ont.*

Casing and Screen Record

Pumping Test

Inside diameter of casing *5 3/8"*

Total length of casing

Type of screen

Length of screen

Depth to top of screen

Diameter of finished hole

5 inches

Static level *4 ft*

Test-pumping rate *4 G.P.M.*

Pumping level *40 ft*

Duration of test pumping *1 hr*

Water clear or cloudy at end of test *Clear*

Recommended pumping rate *4 G.P.M.*

with pump setting of *50*

feet below ground surface

Well Log

Water Record

DRILLED
Deepened to 51 ft and Bedrock Record
limestone rock

From ft

To ft

Depth(s) at which water(s) found

Kind of water (fresh, salty, sulphur)

22

51

40'

fresh

For what purpose(s) is the water to be used?

house

Is well on upland, in valley, or on hillside?

upland

Drilling or Boring Firm

George Hart & Sons

Address

R.R. # 3, Fenelon Falls, Ont.

License Number

1965

Name of Driller or Borer

GEORGE HART

Address

Same as above

Date

March 25/66

G. Hart


(Signature of Licensed Drilling or Boring Contractor)

(Per m. H.)

Form 1531-60-1138

Location of Well

In diagram below show distances of well from road and lot line. Indicate north by arrow.



OWRC COPY

401



DATE COMPLETED 05-08-77
BY NO 1TH

LOG OF OVERBURDEN AND BEDROCK MATERIALS (SEE INSTRUCTIONS)

[illegible]

2

51) CASING & OPEN HOLE RECORD

INCHES DOWN	MATERIAL	SMALL DIMENSIONS INCHES	DEPTH - FEET	
			FROM	TO
00 1/4	1 STEEL 2 GALVANIZED 3 CONCRETE 4 OPEN HOLE	188	0	000 X
06 1/4	1 STEEL 2 GALVANIZED 3 CONCRETE 4 OPEN HOLE		0	X 000?
24 1/4	1 STEEL 2 GALVANIZED 3 CONCRETE 4 OPEN HOLE		16	

61 PLUGGING & SEALING RECORD 1

PUMPING-TEST	PUMPING TEST (if lost)		PUMPING RATE		NO. OF PUMPS		NO. OF PUMPS	
	1 ☐ PUMP 2 ☒ SALES		0006		01		60	
PUMPING-TEST	DATE SERIAL		NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS	
	010 015		010 010		010 010		010 010	
DATE		DATE		DATE		DATE		
NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS		
GATE DATE		GATE DATE		GATE DATE		GATE DATE		
RECOMMENDED PUMP TYPE		NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS		
1 ☒ BALL VALVE 2 ☐ GATE		019		0005		0005		
NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS		NO. OF PUMPS		

IN DIAGRAM BELOW IN A DISTANCES OF WELL FROM ROAD AND
LOT LINE INDICATE NUMBER BY ARROW

CONCRETE FR. HWY. #35

ON RIVER

12m

LOT 37

2.5 mi

LOT 36

N

24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200
 201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300
 301
 302
 303
 304
 305
 306
 307
 308
 309
 310
 311
 312
 313
 314
 315
 316
 317
 318
 319
 320
 321
 322
 323
 324
 325
 326
 327
 328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348
 349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364
 365
 366
 367
 368
 369
 370
 371
 372
 373
 374
 375
 376
 377
 378
 379
 380
 381
 382
 383
 384
 385
 386
 387
 388
 389
 390
 391
 392
 393
 394
 395
 396
 397
 398
 399
 400
 401
 402
 403
 404
 405
 406
 407
 408
 409
 410
 411
 412
 413
 414
 415
 416
 417
 418
 419
 420
 421
 422
 423
 424
 425
 426
 427
 428
 429
 430
 431
 432
 433
 434
 435
 436
 437
 438
 439
 440
 441
 442
 443
 444
 445
 446
 447
 448
 449
 450
 451
 452
 453
 454
 455
 456
 457
 458
 459
 460
 461
 462
 463
 464
 465
 466
 467
 468
 469
 470
 471
 472
 473
 474
 475
 476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505
 506
 507
 508
 509
 510
 511
 512
 513
 514
 515
 516
 517
 518
 519
 520
 521
 522
 523
 524
 525
 526
 527
 528
 529
 530
 531
 532
 533
 534
 535
 536
 537
 538
 539
 540
 541
 542
 543
 544

FORM 100-1 (Rev. 1-25-60)

NAME (Last, first, middle initial) G. Weaver	DATE 1/1/61	TO (Contract or order number) 5415	BY (Date received) 121272
--	----------------	--	-------------------------------------

1471 167495.9 4946520 01900 24115

FREE INSTRUCTIONS

0059-15

CASING & OPEN HOLE RECORD

SCREEN	TELETYPE UNIT	REPORT	DATE
	MATERIAL AND TYPE	DEPTH TO TOP OF SCREEN	FOOT

PLUGGING & SEALING RECORD

[illegible]

LOCATION OF WELL

LOCATION OF WELL

IN DIAGRAM BELOW SHOW DISTANCES OF WELL FROM ROAD AND LOT LINE. INDICATE NORTH BY ARROW.

RIVER

CONC - FA. ON.

POW. #35

LOT 37_{300'}

← 0.73 Mi →

LOT 36

0.50 ↓

DILLED HENNA

FINAL STATUS OF WELL	☒ 1 WATER SUPPLY ☒ 2 UNDERSTATION WELL ☐ 3 TEST HOLE ☐ 4 RECHARGE WELL	☐ 5 ABANDONED INSUFFICIENT SUPPLY ☐ 6 ABANDONED POOR QUALITY ☐ 7 UNFINISHED
WATER USE 01	☒ 1 DOMESTIC ☐ 2 STOCK ☐ 3 IRRIGATION ☐ 4 INDUSTRIAL ☐ 5 OTHER	☐ 6 COMMERCIAL ☐ 7 MUNICIPAL ☐ 8 PUBLIC SUPPLY ☐ 9 COOLING OR AIR CONDITIONING ☐ 10 NOT USED
METHOD OF DRILLING	☒ 1 TABLE MOUNTED ☐ 2 ROTARY - CONVENTIONAL ☐ 3 GRAB REVERSE ☐ 4 MOUNTED A.M. ☐ 5 A.M. PL. MOUNTED	☐ 6 BUREAU ☐ 7 HAND ☐ 8 CASTING ☐ 9 CRANK

NAME OF WELL CONTAINER
C. WEAVER
ADDRESS
Cobocank Ontario

WELL NUMBER
3324

1 3324 121272

WATER WELL RECONNAISSANCE SURVEY Sheet ____ of ____

PROJECT NAME <u>Coboconk</u>	PROJECT NO <u>88-237</u>
PERSON INTERVIEWED <u>Gene Suggitt</u>	RESIDENCE <u>Texaco</u>
DATE <u>August 24/88</u> TIME <u>9:50</u>	INTERVIEWED BY <u>PW</u>

OWNER OF WELL:

Name:.....Jim Hannivan.....Telephone (Bus.)..454-3962..
 Address:..Rox. 84, Coboconk.....(incl. Area Code) (Home)..454-3346

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:....Mrs. Hannivan (owner's mother).....Telephone (Bus.).....
 Address:..Directly Beside (north) of Texaco Station.....(incl. Area Code) (Home).....

WELL LOCATION: Lot.....Concession.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed.....Use.....Contractor.....
 Type (drilled or dug).....Diameter.....Well Depth.....
 Is well accessible for direct sampling.....or buried.....
 Well completed into Bedrock.....m. Overburden.....m
 Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)

Original water level depth.....m.

Subsequent water level measurements (give depths in m and dates).....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity....Age...

How is your pump lubricated?.....

Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s

Storage tank: Type..... Capacity.....

Do you have a:

Chlorinator.....Water Softener.....Water Filter.....Filter Type.....

Water use: Domestic No...Yes... No. of persons using water from well

Livestock No...Yes... No. of livestock watered from well

Lawn watering No...Yes... Other..... Amount.....

Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.).....

Private waste and water disposal: Type (septic tank, etc.).....

Distance to well

Well is (1) Uphill..... (2) Downhill..... (3) Same Grade

(continued on reverse..)

PROJECT NAME Coboconk PROJECT NO 88-237
PERSON INTERVIEWED Mary Spry RESIDENCE X
DATE August 24/88 TIME 12:00 INTERVIEWED BY PW

OWNER OF WELL:

Name: Mary Spry Telephone (Bus.)

Address:.....(incl. Area Code) (Home) 454-3982

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:.....Mary Spry.....Telephone (Bus.).....

Address:.....(incl. Area Code) (Home) 454-3982.

WELL LOCATION: Lot.....Part 55.....Concession.....Front.....Township.....
Range.....

WELL CONSTRUCTION DETAILS:

WELL CONSTRUCTION DETAILS:

Date constructed.....	20 years	Use.....	Domestic	Contractor.....	Weaver Well Drilling
-----------------------	----------	----------	----------	-----------------	----------------------

Type (drilled or dug)....drilled.....Diameter.....Well Depth.....60 ft

Is well accessible for direct sampling.....or buried.....

Well completed into Bedrock...Yes.....m. Overburden.....m

Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)

Original water level depth.....m.

Subsequent water level measurements (give depths in m and dates).....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age...

How is your pump lubricated?.....

Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s

Storage tank: Type..... Capacity.....

Do you have a:

Chlorinator.....No.....Water Softener.....Yes.....Water Filter.....No.....Filter Type.....

Water use: Domestic No...Yes.X No. of persons using water from well 3.....

Livestock No. X Yes... No. of livestock watered from well

Lawn watering No...Yes...^X Other..... Amount.....

Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.)...washer,.....

dishwasher, shower

Private waste and water disposal: Type (septic tank, etc.)...Septic.....

Distance to well 50 ft.....

Well is (1) Uphill.....slightly (2) Downhill..... (3) Same Grade

(continued on reverse..)

WATER WELL RECONNAISSANCE SURVEY Sheet ___ of ___

PROJECT NAME Cobocank PROJECT NO 88-237
PERSON INTERVIEWED Mary Spry/Mrs. Mitchell RESIDENCE X
DATE August 24/88 TIME 12:20 INTERVIEWED BY PW

OWNER OF WELL:

Name: Mrs. Mitchell Telephone (Bus.)

Address:.....(incl. Area Code) (Home).....

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:.....Mrs..Mitchell.....Telephone (Bus.).....

Address:.....(incl. Area Code) (Home).....

WELL LOCATION: Lot.....Part 35.....Concession.....Front
Range.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed... May 17/88 Use... X Contractor... Weaver

Type (drilled or dug).....drilled.....Diameter.....6 1/4 in.....Well Depth.....92 ft.....

Is well accessible for direct sampling.....or buried.....

Well completed into Bedrock....Yes.....m. Overburden. 1-4 ft. of clay....m

Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing) Pumping rate: 20 GPM

Original water level depth.....90.ft.....m. Duration of pumping: 1 hr

Static level: 31 ft

Subsequent water level measurements (give depths in m and dates).....
Water level end of pumping: 60 ft

Pump intake set at 85 ft

PUMPING EQUIPMENT:

PUMPING EQUIPMENT: NOTE: clear water, rotary method of construction
 Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age...

How is your pump lubricated?.....

Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s

Storage tank: Type..... Capacity.....

Do you have a:

Chlorinator. NO..Water Softener. NO....Water Filter. NO....Filter Type.....

Water use: Domestic No...Yes. 8. No. of persons using water from well 1.....

Livestock No: ^X Yes... No. of livestock watered from well

Lawn watering No...Yes^X Other..... Amount.....

Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.)...shower, washer.

Private waste and water disposal: Type (septic tank, etc.) Septic.....

Distance to well 45 ft..

Well is (1) Uphill..... (2) Downhill Slightly (3) Same Grade

(continued on reverse..)

Sample Number H4, Assumed MOE Water Well Record Number - No Number
WATER WELL RECONNAISSANCE SURVEY Sheet of

PROJECT NAME <u>Coboconk</u>	PROJECT NO <u>88-237</u>
PERSON INTERVIEWED <u>Colleen Liscombe</u>	RESIDENCE <u>Store</u>
DATE <u>August 24/88</u> TIME <u>10:20</u>	INTERVIEWED BY <u>PW</u>

OWNER OF WELL:

Name:.....Pam Wilcox.....Telephone (Bus.).....454-1401
Address:.....The Millworks Store.....(incl. Area Code) (Home).....454-8879

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:.....Telephone (Bus.).....
Address:.....(incl. Area Code) (Home).....

WELL LOCATION: Lot.....Concession.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed.....Use.....Contractor.....
Type (drilled or dug).....Diameter.....Well Depth.....
Is well accessible for direct sampling.....or buried.....
Well completed into Bedrock.....m. Overburden.....m
Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)
Original water level depth.....m.
Subsequent water level measurements (give depths in m and dates).....
.....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age...
How is your pump lubricated?.....
Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s
Storage tank: Type..... Capacity.....
Do you have a:
Chlorinator.....Water Softener.....Water Filter.....Filter Type.....
Water use: Domestic No...Yes... No. of persons using water from well
Livestock No...Yes... No. of livestock watered from well
Lawn watering No...Yes... Other..... Amount.....
Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.).....
.....
Private waste and water disposal: Type (septic tank, etc.).....
Distance to well
Well is (1) Uphill..... (2) Downhill..... (3) Same Grade

(continued on reverse..)

WATER WELL RECONNAISSANCE SURVEY Sheet of

PROJECT NAME <u>Coboconk</u>	PROJECT NO <u>88-237</u>
PERSON INTERVIEWED <u>Leslie Frances</u>	RESIDENCE <u>X</u>
DATE <u>August 24/88</u> TIME <u>10:40</u>	INTERVIEWED BY <u>PW</u>

OWNER OF WELL:

Name:.....Leslie Frances.....Telephone (Bus.).....
 Address:.....(incl. Area Code) (Home).....454-1262

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:.....Leslie Frances.....Telephone (Bus.).....
 Address:.....(incl. Area Code) (Home).....

WELL LOCATION: Lot.....Part Lot 36.....Concession.....7.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed.....Use.....Contractor.....
 Type (drilled or dug).....Diameter.....Well Depth.....
 Is well accessible for direct sampling.....or buried.....
 Well completed into Bedrock.....m. Overburden.....m.
 Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)
 Original water level depth.....m.
 Subsequent water level measurements (give depths in m and dates).....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age...
 How is your pump lubricated?.....
 Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s
 Storage tank: Type..... Capacity.....
 Do you have a:
 Chlorinator.....Water Softener.....Water Filter.....Filter Type.....
 Water use: Domestic No...Yes...X No. of persons using water from well 1.....
 Livestock No...XYes... No. of livestock watered from well
 Lawn watering No...XYes... Other..... Amount.....
 Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.)...shower.....
,.....
 Private waste and water disposal: Type (septic tank, etc.)...Septic.....
 Distance to well 37 ft.....
 Well is (1) Uphill..... (2) Downhill..... (3) Same Grade X.....

(continued on reverse..)

PROJECT NAME Coboconk PROJECT NO 88-237
PERSON INTERVIEWED Gayle Webster RESIDENCE X
DATE August 24/88 TIME 1:30 INTERVIEWED BY PW

OWNER OF WELL:

Name: Earl Hughes Telephone (Bus.)
Address: (incl. Area Code) (Home) (705) 454-3944

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name:.....Earl Hughes.....Telephone (Bus.).....
Address:.....(incl. Area Code) (Home).....

WELL LOCATION: Lot.....Concession.....Township.....

WELL CONSTRUCTION DETAILS:

WELL CONSTRUCTION DETAILS: Lenridge Well
Drilling
Date constructed. 14 years.... Use..... Contractor.....
Type (drilled or dug)... drilled..... Diameter..... Well Depth... 100. ft
Is well accessible for direct sampling. concrete cover or buried.....
Well completed into Bedrock... Yes..... m. Overburden..... m
Screen: Yes.... No.... If yes, length..... m. Depth to top of screen..... m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)
Original water level depth.....m.
Subsequent water level measurements (give depths in m and dates).....
.....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence.X..Pumping capacity....Age...
How is your pump lubricated?.....
Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s
Storage tank: Type..... Capacity.....
Do you have a:
Chlorinator...No...Water Softener...X....Water Filter...X....Filter Type.....
Water use: Domestic No...Yes.X No. of persons using water from well 2.....
Livestock No:X...Yes... No. of livestock watered from well
Lawn watering No...Yes.X Other..... Amount.....
Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.).....
.....
Private waste and water disposal: Type (septic tank, etc.)...Septic.....
Distance to well 45 ft.....
Well is (1) Uphill..... (2) Downhill..... (3) Same Grade...X.....

(continued on reverse...)

WATER WELL RECONNAISSANCE SURVEY Sheet ___ of ___

PROJECT NAME	Coboconk	PROJECT NO	88-237
PERSON INTERVIEWED	Wilma Baker	RESIDENCE	X
DATE	August 24/88	TIME	11:10
		INTERVIEWED BY	PW

OWNER OF WELL:

Name: Ray & Wilma Baker Telephone (Bus.)
Address: (incl. Area Code) (Home) 454-1263.

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name: Ray & Wilma Baker.....Telephone (Bus.).....
Address:.....(incl. Area Code) (Home).....

WELL LOCATION: Lot..Part.36.....Concession.....7.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed.....14 years.....Use.....Contractor.....Gordy Weaver.....
Type (drilled or dug).....drilled.....Diameter.....Well Depth.....57 ft
Is well accessible for direct sampling.....concrete covered.....or buried.....
Well completed into Bedrock.....Yes.....m.....Overburden.....m
Screen: Yes.... No.... If yes, length.....m.....Depth to top of screen.....m

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)

Original water level depth.....m.

Subsequent water level measurements (give depths in m and dates).....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age 2 months

How is your pump lubricated?.....

Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s

Storage tank: Type..... Capacity.....

Do you have a:

Clear 'n' Fresh
Envirogard Products

Chlorinator.....No.....Water Softener.....No.....Water Filter.....X.....Filter Type.....Ltd.....

Water use: Domestic No...Yes...^X No. of persons using water from well ...³.....

Livestock No. ^X Yes... No. of livestock watered from well

Lawn watering No. X Yes... Other..... Amount.....

Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.)..shower.....

Private waste and water disposal: Type (septic tank, etc.)...Septic.....

Distance to well 52 ft.

Well is (1) Uphill..... (2) Downhill..... (3) Same Grade^X

(continued on reverse) 1

WATER WELL RECONNAISSANCE SURVEY Sheet ___ of ___

PROJECT NAME	Coboconk	PROJECT NO	88-237
PERSON INTERVIEWED	John Wilms	RESIDENCE	X
DATE	August 24/88	TIME	11:30
		INTERVIEWED BY	PW

OWNER OF WELL:

Name:.....John Wilms.....Telephone (Bus.).....
Address:.....(Incl. Area Code) (Home) 454-8112.

OCCUPANT OF HOUSE SERVED BY WELL (if other than owner):

Name: John Wilson Telephone (Bus.)
Address: (incl. Area Code) (Home)

WELL LOCATION: Lot...Part 36.....Concession.....7.....Township.....

WELL CONSTRUCTION DETAILS:

Date constructed.....8 years.....Use.....X.....Contractor.....Gordy Weaver.....

Type (drilled or dug)...drilled.....Diameter...6-8 inch...Well Depth...48 ft.....

Is well accessible for direct sampling....No.....or buried.....

Well completed into Bedrock....Yes.....m.....Overburden.....m.....

Screen: Yes.... No.... If yes, length.....m. Depth to top of screen.....m.....

WELL WATER LEVELS:

(Indicate whether measured from ground level, or from top of casing)
Original water level depth...15 ft. from ground...m.
surface when drilled
Subsequent water level measurements (give depths in m and dates)...No.....
.....

PUMPING EQUIPMENT:

Pump Type: Suction-lift....or Positive-submergence....Pumping capacity.....Age 8 years

How is your pump lubricated?....sealed bearings.....

Depth of intake setting.....m (Original).....m (present) Pumping rate....L/s

Storage tank: Type.....No..... Capacity.....

Do you have a:

Chlorinator...No...Water Softener...No...Water Filter.No....Filter Type.....

Water use: Domestic No...Yes X. No. of persons using water from well ...5.....

Livestock No...Yes X. No. of livestock watered from well 1.....

Lawn watering No X.Yes... Other..... Amount.....

Equipment: Indoor plumbing (e.g. shower, automatic washer, etc.)..washer, bathtub-
no shower, dishwasher

Private waste and water disposal: Type (septic tank, etc.)...Septic.....

Distance to well 44 ft.....

Well is (1) Uphill..... (2) Downhill..... (3) Same Grade ...X.....

APPENDIX III

- **BOREHOLE LOGS**
- **HAND AUGER BOREHOLE LOGS**
- **MONITOR DETAIL^c SUMMARY**
- **SLUG TEST ANALYSIS PLOTS**



BOREHOLE LOG	PROJECT NO. <u>88-237</u>	BOREHOLE NO. <u>1</u>
PROJECT NAME <u>Coboconk Waste Disposal Site</u>		DATE <u>17 August 1988</u>
<u>Coboconk, Ontario</u>		GEOLOGIST <u>PW</u>
CLIENT <u>Ministry of the Environment</u>		ELEVATION <u>280.79 masl</u>

DEPTH (m)	STRATIGRAPHY	STRATIGRAPHIC DESCRIPTION	MONITOR DETAILS & NUMBER I II	INTERVAL	SAMPLE					Penetration Resistance N VALUE (Blows/0.3m)				Water Content (%) w _c ☐				
					NO.	TYPE	N 1/VALUE	%RECOVERY	%WATER	%RQD	10	20	30	40	10	20	30	
1		LIMESTONE (Gull River Formation) Grey-Brown, fractured with sand, shale and clay seams			1	NQ		80		4								
2.1																		
2		Grey, fractured with clay seams and horizontal shaley partings, some vertical fractures with well developed crystals on fracture faces, fine to medium grained, laminated, fossiliferous			2	NQ		90		0								
3					3	NQ		90		0								
4					4	NQ		100		53								
5					5	NQ		100		48								
6					6	NQ		100		60								
7					7	NQ		100		86								
8																		
9																		
10																		
10.7		NQ corehole terminated at 10.7 m in fractured limestone.																

P-Piezometer S-Standpipe G-Gas Monitor

 Gartner Lee Limited

BOREHOLE LOG	PROJECT NO. <u>88-237</u>	BOREHOLE NO. <u>2</u>
PROJECT NAME <u>Coboconk Waste Disposal Site</u>	DATE <u>18 August 1988</u>	
<u>Coboconk, Ontario</u>	GEOLOGIST <u>PW</u>	
CLIENT <u>Ministry of the Environment</u>	ELEVATION <u>276.98 masl</u>	

DEPTH (m)	STRATIGRAPHY	STRATIGRAPHIC DESCRIPTION	SAMPLE						Penetration Resistance N VALUE (Blows/0.3m)				Water Content (%)		
			MONITOR DETAILS & NUMBER	INTERVAL	NO.	TYPE	N VALUE	%RECOVERY	%WATER	%RQD					w ☐
											10	20	30	40	
1		LIMESTONE (Gull River Formation) Grey, fractured with shaley parting and vuggy sections, fine to medium grained, laminated, fossiliferous	I		1	NQ	100			19					
			II		2	NQ	100			31					
2					3	NQ	100			50					
3					4	NQ	100			75					
4															
5					5	NQ	100			80					
6					6	NQ	100			88					
7															
8					7	NQ	100			79					
9.1 9		NQ Corehole terminated at 9.1 m in fractured limestone.													

P-Piezometer S-Standpipe G-Gas Monitor

 Gartner Lee Limited

BOREHOLE LOG	PROJECT NO. <u>88-237</u>	BOREHOLE NO. <u>3</u>
PROJECT NAME <u>Coboconk Waste Disposal Site</u>		DATE <u>18 August 1988</u>
<u>Coboconk, Ontario</u>		GEOLOGIST <u>PW</u>
CLIENT <u>Ministry of the Environment</u>		ELEVATION <u>276.94 masl</u>

DEPTH (m)	STRATIGRAPHY	STRATIGRAPHIC DESCRIPTION	MONITOR DETAILS & NUMBER I II	SAMPLE					Penetration Resistance N VALUE (Blows/0.3m)				Water Content (%) w _c ☐		
				NO.	TYPE	N VALUE	%RECOVERY	%WATER	XRQD	10	20	30	10	20	30
0.3		SANDY SILT TOPSOIL		1	NQ	95			0						
1		LIMESTONE (Gull River Formation) Grey, fractured with shaley partings and mud seams, fine to medium grained, laminated, fossiliferous		2	NQ	90			0						
2				3	NQ	80			47						
3				4	NQ	100			48						
4				5	NQ	100			71						
5				6	NQ	100			74						
6				7	NQ	100			80						
7															
8															
9.1		NQ Corehole terminated at 9.1 m in fractured limestone.													

P-Piezometer S-Standpipe G-Gas Monitor

 Gartner Lee Limited

BOREHOLE LOG	PROJECT NO. <u>88-237</u>	BOREHOLE NO. <u>4</u>
PROJECT NAME <u>Coboconk Waste Disposal Site</u>	DATE <u>19 August 1988</u>	
<u>Coboconk, Ontario</u>	GEOLOGIST <u>PW</u>	
CLIENT <u>Ministry of the Environment</u>	ELEVATION <u>280.30 masl</u>	

DEPTH (m)	STRATIGRAPHY	STRATIGRAPHIC DESCRIPTION	MONITOR DETAILS & NUMBER INTERVAL	SAMPLE						Penetration Resistance N VALUE (Blows/0.3m)				Water Content (%) w _c ☐		
				NO.	TYPE	N VALUE	%RECOVERY	%WATER	%RQD							
0.2		<u>ORGANIC/SANDY TOPSOIL</u>														
1		<u>FILL</u> Tan-Brown to Brown, sand, gravel, silt, glass, rubble, garbage														
2																
3				1	SS	60									> 2	
3.5				2	NQ	90			54							
4		<u>LIMESTONE</u> (Gull River Formation) Grey, fractured with shaley partings and vuggy sections, fine to medium grained, laminated, fossiliferous		3	NQ	100			56							
5				4	NQ	100			67							
6				5	NQ	100			74							
7																
8																
9.1 9		NQ Corehole terminated at 9.1 m in fractured limestone.														

P-Piezometer S-Standpipe G-Gas Monitor

 Gartner Lee Limited

TABLE 1: HAND AUGER HOLES
Coboconk Waste Disposal Site (88-237)

AH-1

0 - 0.15m Dark brown, clayey silt till with organic
 matter
 Gas reading = 0

AH-2

0 - 0.25m Brown, silty sand fill (roots, refuse -
 glass)
0.25 - 0.41m Brown, sandy silt/silty sand fill (refuse -
 glass, brick)
 Gas reading = 0

AH-3

0 - 0.15m Brown, silty sand fill
0.15 - 0.25m Brown, sandy silt fill (refuse - glass)
 Gas reading = 0

AH-4

0 - 0.25m Silty sand fill (refuse - burnt garbage and
 glass)
0.25 - 0.30m Tan-brown, fine to medium sand
 Gas reading = 0

AH-5

0 - 0.30m Brown, silty sand (refuse - glass)
 Gas reading = 0

AH-6

0 - 0.15m Black, organic, sandy topsoil
 Gas reading = 0

PROJECT NO: 88-237

MONITOR DETAILS SUMMARY

BOREHOLE		MONITOR						SCREENED INTERVAL		FILTER PACK		SEAL		BACKFILL	
NO.	DIAMETER (mm)	NO.	TYPE	DIAMETER (mm)	STICK-UP (m)	ELEVATION (t.o.p.m.)		(m)	(m)	(m)	(m)	(m)	(m)	(m)	(m)
1	76	I	PVC	51	0.32	281.114		9.8	- 8.3	9.8	- 8.0	8.0	- 7.4	7.4	- 0
1	76	II	PVC	51	0.04	280.916		6.1	- 3.1	6.1	- 3.0	3.0	- 2.4	2.4	- 0
2	76	I	PVC	51	0.22	277.194		9.0	- 7.5	9.0	- 7.0	7.0	- 6.4	6.4	- 0
2	76	II	PVC	51	0.08	277.087		4.6	- 1.6	4.6	- 1.0	1.0	- 0.4	0.4	- 0
3	76	I	PVC	51	0.37	277.305		8.7	- 7.2	8.7	- 7.0	7.0	- 6.4	6.4	- 0
3	76	II	PVC	51	0.31	277.315		4.3	- 1.3	4.3	- 1.0	1.0	- 0.4	0.4	- 0
4	76	I	PVC	51	0.09	280.388		8.8	- 5.8	8.8	- 5.5	5.5	- 4.9	4.9	- 0

NOTE: t.o.p.m. - TOP OF PIPE IN METRES


PROJECT NO: 88-237 COBOCONK LANDFILL

WATER LEVEL DATA

B.H. GROUND NO. ELEV.	MONITOR		18-AUG-88	19-AUG-88	23-AUG-88	24-AUG-88	25-AUG-88	11-NOV-88								
	NO.	TOP OF MONITOR ELEV.	DEPTH BELOW T.O.P. (m)	DEPTH BELOW T.O.P. (m)	DEPTH BELOW T.O.P. (m)	DEPTH BELOW T.O.P. (m)	DEPTH BELOW T.O.P. (m)	DEPTH BELOW T.O.P. (m)								
1	280.79	I	281.11	P	2.41	278.70	2.46	278.65	2.65	278.46	2.75	278.36	2.57	278.54	1.74	279.37
1	280.87	II	280.92	S	1.99	278.93	2.15	278.77	2.33	278.59	2.31	278.61	2.22	278.70	1.43	279.49
2	276.98	I	277.19	P	-	-	3.86	273.33	-	-	5.10	272.09	5.12	272.07	0.29	276.90
2	277.00	II	277.09	S	4.14	272.95	4.09	273.00	4.20	272.89	4.24	272.85	4.24	272.85	0.13	276.96
3	276.94	I	277.31	P	-	-	-	-	5.68	271.63	6.21	271.10	6.28	271.03	0.78	276.53
3	277.01	II	277.32	S	-	-	3.48	273.84	-	-	DRY	-	DRY	-	0.71	276.61
4	280.30	I	280.39	P	-	-	-	-	6.49	273.90	6.97	273.42	6.96	273.43	3.34	277.05


NOTE: S - STANDPIPE
P - PIEZOMETER
T.O.P. - TOP OF PIPE

SLUG TEST ANALYSIS - HVORSLEV'S METHOD



PROJECT NAME: COBOCONK PROJECT NUMBER: 88-237


SLUG TEST ANALYSIS - HVORSLEV'S METHOD



ELAPSED TIME(hours)

PROJECT NAME: COBOCONK PROJECT NUMBER: 88-237

SLUG TEST ANALYSIS - HVORSLEV'S METHOD



PROJECT NAME: COBOCONK LANDFILL SITE PROJECT NUMBER: 87-237

SLUG TEST ANALYSIS - HVORSLEV'S METHOD

Least Squares Regression Analysis


INSTALLATION ID: BH 2 II

$$K = d^2 \ln \left[\frac{mL/D + (1 + (mL/D)^2)^{1/2}}{8LT_0} \right]$$

8LT₀

d = 51 mm
D = 76 mm
L = 3000 mm
T₀ = 5.588E+04 s
m = 1.00
K = 8.5E-09 m/s

$$\frac{H-h}{H-H_0}$$



Note: '+' indicates data point not used in analysis

ELAPSED TIME(hours)

PROJECT NAME: COBOCONK PROJECT NUMBER: 88237


SLUG TEST ANALYSIS - HVORSLEV'S METHOD

Least Squares Regression Analysis

INSTALLATION ID: 3 -I

$$K = \frac{d^2 \ln \left[\frac{mL}{D} + \left(1 + \left(\frac{mL}{D} \right)^2 \right)^{1/2} \right]}{8LT_0}$$

$d = 51$ mm
 $D = 76$ mm
 $L = 1500$ mm
 $T_0 = 5.791E+04$ s
 $m = 1.00$
 $K = 1.4E-08$ m/s



ELAPSED TIME(hours)

PROJECT NAME: COBOCONK PROJECT NUMBER: 88-237

SLUG TEST ANALYSIS - HVORSLEV'S METHOD

Least Squares Regression Analysis


INSTALLATION ID: 3 II

$$K = \frac{d^2 \ln \left[\frac{mL}{D + (1 + (mL/D)^2)^{1/2}} \right]}{8LT_0}$$

8LT₀

d = 51 mm
D = 76 mm
L = 3000 mm
T₀ = 2.595E+03 s
m = 1.00
K = 1.8E-07 m/s


$$\frac{H-h}{H-H_0}$$



ELAPSED TIME(minutes)

PROJECT NAME: COBOCONK LANDFILL SITE PROJECT NUMBER: 88237


SLUG TEST ANALYSIS - HVORSLEV'S METHOD



PROJECT NAME: COBOCONK PROJECT NUMBER: 88-237

APPENDIX IV

- **ROUTINE WATER CHEMISTRY ANALYSIS - AUGUST
SAMPLES**
- **ROUTINE WATER CHEMISTRY ANALYSES - NOVEMBER
SAMPLES**
- **VOLATILE ORGANIC ANALYSES OF LEACHATE
(MONITOR 4-I)**
- **HEAVY METAL ANALYSES OF LEACHATE
(MONITOR 4-I)**





MANN TESTING LABORATORIES LTD.
5550 BRADAM ROAD, MISSISSAUGA, ONTARIO L4Z 1P1
PHONE: 890-2555 • TELEX: 06-960496 • FAX: (416) 890-0370

CUSTOMER: Gartner Lee Limited
140 Renfrew Drive
Markham, Ontario
L3R 6B3

RECEIVED
OCT 13 1988
GARTNER LEE

REPORT #: 882315

CUSTOMER REF.# 88-237

ATTN: Mr. Rob Dickin

DATE SUBMITTED: Aug. 25, 1988

----- CERTIFICATE OF ANALYSIS -----

Sample Description: WATER

Preparation: Samples were prepared as recommended in APHA Standard methods for the examination of water and wastewater, 16th Edition, 1985 or MOE Handbook of analytical methods for environmental samples, 1983.

Note: Additional Information is available on request.


Methodology:

Metals - flame, atomic absorption,
Inductivity coupled Plasma Atomic
Emission.

Conventionals - potentiometric, spectrophotometric
and other wet chemical techniques.

Chemical Results: See Tables 1 and 2.

DATE: Oct. 6/88


CERTIFIED BY:
Jim Forrester,
Manager, Inorganic Dept.

REPORT TO: GAKTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1A

RCAP CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#H1	#H2		
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	120		7.3	
Potassium	0.1 mg/L	5.0		1.9	
Calcium	0.005 mg/L	138		88	
Magnesium	0.001 mg/L	24		11	
Hardness (as CaCO ₃)	0.05 mg/L	443		265	
Alkalinity (as CaCO ₃)	1.0 mg/L	210		240	
Sulphate	1.0 mg/L	400		33	
Chloride	1.0 mg/L	54		8	
Silica	0.5 mg/L	10		6.1	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	<0.05		0.13	
Ammonia (as N)	0.05 mg/L	0.35		<0.05	
Iron	0.02 mg/L	0.23	0.31	0.02	0.05
Manganese	0.01 mg/L	0.04	0.05	<0.01	0.01
Copper	0.01 mg/L	<0.01	<0.01	0.11	0.11
Zinc	0.01 mg/L	0.27	0.30	0.01	0.01
Colour (true)	0.5 T.C.U.	6		6	
Turbidity	0.1 N.T.U.	2.5		0.6	
Conductivity (25°C)	0.1 umho/cm	1480		593	
pH	0.01	7.6		7.5	
Total Organic Carbon	0.5 mg/L	1.7		2.6	
Cation Sum	0.01 meq/L	14.27		5.68	
Anion Sum	0.01 meq/L	14.05		5.72	
Ion Ratio	0.01	1.02		0.99	
% Difference	0.1 %	0.8		0.4	
TDS (ion sum, calc)	0.1 mg/L	877		300	
Conductivity (calc, 25°C)	0.1 umho/cm	1632		568	
Saturation pH (4°C)	0.01	7.34		7.43	
Langelier Index (4°C)	0.01	0.26		0.07	
Bicarbonate(as CaCO ₃)	1.0 mg/L	209		239	
Carbonate(as CaCO ₃)	1.0 mg/L	0.8		0.7	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1B

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#H3		#H4	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	84		58	
Potassium	0.1 mg/L	3.4		1.9	
Calcium	0.005 mg/L	129		134	
Magnesium	0.001 mg/L	13		8.3	
Hardness (as CaCO ₃)	0.05 mg/L	376		369	
Alkalinity (as CaCO ₃)	1.0 mg/L	280		230	
Sulphate	1.0 mg/L	49		140	
Chloride	1.0 mg/L	140		95	
Silica	0.5 mg/L	7.1		5.2	
o-Phosphate (as P)	0.01 mg/L	0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	2.9		2.2	
Ammonia (as N)	0.05 mg/L	<0.05		<0.05	
Iron	0.02 mg/L	0.08	0.19	0.01	0.03
Manganese	0.01 mg/L	0.15	0.16	0.02	0.01
Copper	0.01 mg/L	0.01	0.01	0.88	0.91
Zinc	0.01 mg/L	1.1	1.1	0.41	0.40
Colour (true)	0.5 T.C.U.	<3		6	
Turbidity	0.1 N.T.U.	1.1		0.5	
Conductivity (25°C)	0.1 umho/cm	1240		1128	
pH	0.01	7.4		7.5	
Total Organic Carbon	0.5 mg/L	3.9		2.8	
Cation Sum	0.01 meq/L	11.27		9.96	
Anion Sum	0.01 meq/L	10.77		10.35	
Ion Ratio	0.01	1.05		0.96	
% Difference	0.1 %	2.3		1.9	
TDS (ion sum, calc)	0.1 mg/L	606		590	
Conductivity (calc, 25°C)	0.1 umho/cm	1205		1138	
Saturation pH (4°C)	0.01	7.23		7.29	
Langelier Index (4°C)	0.01	0.17		0.21	
Bicarbonate(as CaCO ₃)	1.0 mg/L	279		229	
Carbonate(as CaCO ₃)	1.0 mg/L	0.7		0.7	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1C

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#H5		#H6	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	14		170	
Potassium	0.1 mg/L	4.1		3.7	
Calcium	0.005 mg/L	94		200	
Magnesium	0.001 mg/L	20		9.8	
Hardness (as CaCO ₃)	0.05 mg/L	317		540	
Alkalinity (as CaCO ₃)	1.0 mg/L	250		350	
Sulphate	1.0 mg/L	67		35	
Chloride	1.0 mg/L	22		360	
Silica	0.5 mg/L	7.9		6.2	
o-Phosphate (as P)	0.01 mg/L	<0.01		0.04	
Nitrate + Nitrite (as N)	0.05 mg/L	0.17		0.69	
Ammonia (as N)	0.05 mg/L	0.19		0.93	
Iron	0.02 mg/L	0.10	0.36	0.09	0.64
Manganese	0.01 mg/L	0.04	0.05	0.35	0.46
Copper	0.01 mg/L	0.28	0.29	0.15	0.17
Zinc	0.01 mg/L	1.1	1.10	0.03	0.03
Colour (true)	0.5 T.C.U.	11		12	
Turbidity	0.1 N.T.U.	4.4		3.1	
Conductivity (25°C)	0.1 umho/cm	760		1960	
pH	0.01	7.5		7.2	
Total Organic Carbon	0.5 mg/L	4.1		4.5	
Cation Sum	0.01 meq/L	7.09		18.37	
Anion Sum	0.01 meq/L	7.03		17.92	
Ion Ratio	0.01	1.01		1.03	
% Difference	0.1 %	0.4		1.2	
TDS (ion sum, calc)	0.1 mg/L	380		999	
Conductivity (calc, 25°C)	0.1 umho/cm	729		2064	
Saturation pH (4°C)	0.01	7.39		6.97	
Langelier Index (4°C)	0.01	0.11		0.23	
Bicarbonate(as CaCO ₃)	1.0 mg/L	249		350	
Carbonate(as CaCO ₃)	1.0 mg/L	0.7		0.5	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1D

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#H7	#H8		
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	22		16	
Potassium	0.1 mg/L	3.0		2.4	
Calcium	0.005 mg/L	112		111	
Magnesium	0.001 mg/L	13		6.6	
Hardness (as CaCO ₃)	0.05 mg/L	333		304	
Alkalinity (as CaCO ₃)	1.0 mg/L	250		230	
Sulphate	1.0 mg/L	75		65	
Chloride	1.0 mg/L	41		20	
Silica	0.5 mg/L	5.6		5.0	
o-Phosphate (as P)	0.01 mg/L	<0.01		0.02	
Nitrate + Nitrite (as N)	0.05 mg/L	<0.05		5.2	
Ammonia (as N)	0.05 mg/L	0.14		<0.05	
Iron	0.02 mg/L	0.40	1.0	0.02	0.03
Manganese	0.01 mg/L	0.06	0.11	0.02	0.01
Copper	0.01 mg/L	0.01	0.02	0.01	0.01
Zinc	0.01 mg/L	0.60	0.74	0.06	0.06
Colour (true)	0.5 T.C.U.	22		10	
Turbidity	0.1 N.T.U.	3.2		0.6	
Conductivity (25°C)	0.1 umho/cm	770		760	
pH	0.01	7.4		7.6	
Total Organic Carbon	0.5 mg/L	5.9		3.3	
Cation Sum	0.01 meq/L	7.73		6.86	
Anion Sum	0.01 meq/L	7.72		6.89	
Ion Ratio	0.01	1.00		1.00	
% Difference	0.1 %	0.1		0.2	
TDS (ion sum, calc)	0.1 mg/L	422		387	
Conductivity (calc, 25°C)	0.1 umho/cm	816		723	
Saturation pH (4°C)	0.01	7.32		7.36	
Langelier Index (4°C)	0.01	0.08		0.24	
Bicarbonate(as CaCO ₃)	1.0 mg/L	249		229	
Carbonate(as CaCO ₃)	1.0 mg/L	0.6		0.9	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1E

1-I

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#H9	#BH 1-D		
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	160		0.9	
Potassium	0.1 mg/L	3.7		0.6	
Calcium	0.005 mg/L	197		113	
Magnesium	0.001 mg/L	9.7		3.8	
Hardness (as CaCO ₃)	0.05 mg/L	532		298	
Alkalinity (as CaCO ₃)	1.0 mg/L	350		290	
Sulphate	1.0 mg/L	34		15	
Chloride	1.0 mg/L	360		2	
Silica	0.5 mg/L	6.2		4.8	
o-Phosphate (as P)	0.01 mg/L	0.04		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	0.73		<0.05	
Ammonia (as N)	0.05 mg/L	0.95		<0.05	
Iron	0.02 mg/L	0.07	0.64	0.07	0.95
Manganese	0.01 mg/L	0.34	0.45	0.06	0.15
Copper	0.01 mg/L	0.16	0.19	<0.01	<0.01
Zinc	0.01 mg/L	0.03	0.03	0.01	0.01
Colour (true)	0.5 T.C.U.	12		10	
Turbidity	0.1 N.T.U.	2.8		180	
Conductivity (25°C)	0.1 umho/cm	1990		625	
pH	0.01	7.3		7.5	
Total Organic Carbon	0.5 mg/L	4.5		4.1	
Cation Sum	0.01 meq/L	17.78		6.02	
Anion Sum	0.01 meq/L	17.90		6.17	
Ion Ratio	0.01	0.99		0.98	
% Difference	0.1 %	0.3		1.2	
TDS (ion sum, calc)	0.1 mg/L	985		314	
Conductivity (calc, 25°C)	0.1 umho/cm	2034		592	
Saturation pH (4°C)	0.01	6.97		7.24	
Langelier Index (4°C)	0.01	0.33		0.26	
Bicarbonate(as CaCO ₃)	1.0 mg/L	349		289	
Carbonate(as CaCO ₃)	1.0 mg/L	0.7		0.9	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1F

RCAP CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	1-II		2-I	
		#BH 1-S	'Total' Metals	#BH 2-D	'Total' Metals
		Water Soluble		Water Soluble	
Sodium	0.5 mg/L	0.9		20	
Potassium	0.1 mg/L	3.5		3.7	
Calcium	0.005 mg/L	99		64	
Magnesium	0.001 mg/L	7.8		14	
Hardness (as CaCO ₃)	0.05 mg/L	279		218	
Alkalinity (as CaCO ₃)	1.0 mg/L	250		175	
Sulphate	1.0 mg/L	21		70	
Chloride	1.0 mg/L	3		11	
Silica	0.5 mg/L	5.3		4.7	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	<0.05		0.86	
Ammonia (as N)	0.05 mg/L	<0.05		0.4	
Iron	0.02 mg/L	0.02	0.23	0.03	0.61
Manganese	0.01 mg/L	0.04	0.05	0.04	0.11
Copper	0.01 mg/L	0.01	0.01	0.01	0.02
Zinc	0.01 mg/L	0.02	0.02	0.01	0.03
Colour (true)	0.5 T.C.U.	11		4	
Turbidity	0.1 N.T.U.	52		100	
Conductivity (25°C)	0.1 umho/cm	575		560	
pH	0.01	7.6		7.7	
Total Organic Carbon	0.5 mg/L	2.9		4.1	
Cation Sum	0.01 meq/L	5.73		5.36	
Anion Sum	0.01 meq/L	5.51		5.33	
Ion Ratio	0.01	1.04		1.01	
% Difference	0.1 %	2.0		0.3	
TDS (ion sum, calc)	0.1 mg/L	290		297	
Conductivity (calc, 25°C)	0.1 umho/cm	552		558	
Saturation pH (4°C)	0.01	7.36		7.70	
Langelier Index (4°C)	0.01	0.24		0.00	
Bicarbonate(as CaCO ₃)	1.0 mg/L	249		174	
Carbonate(as CaCO ₃)	1.0 mg/L	0.9		0.8	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1G

3-I

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#BH 3-D	#BH 4		
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	7.6		4	
Potassium	0.1 mg/L	6.3		3.4	
Calcium	0.005 mg/L	86		88	
Magnesium	0.001 mg/L	12		21	
Hardness (as CaCO ₃)	0.05 mg/L	264		306	
Alkalinity (as CaCO ₃)	1.0 mg/L	190		280	
Sulphate	1.0 mg/L	70		26	
Chloride	1.0 mg/L	11		4	
Silica	0.5 mg/L	5.0		8.3	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	0.56		0.11	
Ammonia (as N)	0.05 mg/L	0.25		0.23	
Iron	0.02 mg/L	0.06	2.0	0.05	1.6
Manganese	0.01 mg/L	0.03	0.50	0.04	0.14
Copper	0.01 mg/L	<0.01	0.02	<0.01	0.01
Zinc	0.01 mg/L	0.01	0.04	0.01	0.04
Colour (true)	0.5 T.C.U.	4		5	
Turbidity	0.1 N.T.U.	>1000		99	
Conductivity (25°C)	0.1 umho/cm	660		640	
pH	0.01	7.5		7.5	
Total Organic Carbon	0.5 mg/L	5.4		2.6	
Cation Sum	0.01 meq/L	5.81		6.43	
Anion Sum	0.01 meq/L	5.61		6.25	
Ion Ratio	0.01	1.04		1.03	
% Difference	0.1 %	1.8		1.4	
TDS (ion sum, calc)	0.1 mg/L	315		323	
Conductivity (calc, 25°C)	0.1 umho/cm	598		618	
Saturation pH (4°C)	0.01	7.54		7.36	
Langelier Index (4°C)	0.01	-0.04		0.14	
Bicarbonate(as CaCO ₃)	1.0 mg/L	189		279	
Carbonate(as CaCO ₃)	1.0 mg/L	0.6		0.8	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB. #:882315
 TABLE #1H

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#BH 5		#BH 6	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	8.8		0.6	
Potassium	0.1 mg/L	1.2		0.4	
Calcium	0.005 mg/L	36		75	
Magnesium	0.001 mg/L	8.3		3.6	
Hardness (as CaCO ₃)	0.05 mg/L	124		202	
Alkalinity (as CaCO ₃)	1.0 mg/L	85		195	
Sulphate	1.0 mg/L	26		11	
Chloride	1.0 mg/L	25		2	
Silica	0.5 mg/L	0.8		4.8	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	0.24		<0.05	
Ammonia (as N)	0.05 mg/L	0.19		<0.05	
Iron	0.02 mg/L	0.02	0.03	0.04	1.7
Manganese	0.01 mg/L	0.01	<0.01	0.06	0.25
Copper	0.01 mg/L	0.01	0.01	<0.01	<0.01
Zinc	0.01 mg/L	0.01	<0.01	<0.01	0.01
Colour (true)	0.5 T.C.U.	<3		18	
Turbidity	0.1 N.T.U.	15		290	
Conductivity (25°C)	0.1 umho/cm	300		430	
pH	0.01	7.6		7.3	
Total Organic Carbon	0.5 mg/L	2.6		3.5	
Cation Sum	0.01 meq/L	2.92		4.09	
Anion Sum	0.01 meq/L	2.96		4.19	
Ion Ratio	0.01	0.99		0.98	
% Difference	0.1 %	0.7		1.2	
TTS (ion sum, calc)	0.1 mg/L	158		215	
Conductivity (calc, 25°C)	0.1 umho/cm	316		402	
Saturation pH (4°C)	0.01	8.25		7.58	
Langelier Index (4°C)	0.01	-0.65		-0.28	
Bicarbonate(as CaCO ₃)	1.0 mg/L	85		195	
Carbonate(as CaCO ₃)	1.0 mg/L	0.3		0.4	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB. #:882315
 TABLE #11

RCAP CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#Q 1		#R 2	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	15		1.5	
Potassium	0.1 mg/L	3.7		0.7	
Calcium	0.005 mg/L	82		9	
Magnesium	0.001 mg/L	18		1.8	
Hardness (as CaCO ₃)	0.05 mg/L	279		29	
Alkalinity (as CaCO ₃)	1.0 mg/L	140		19	
Sulphate	1.0 mg/L	150		11	
Chloride	1.0 mg/L	19		3	
Silica	0.5 mg/L	1.5		1.4	
o-Phosphate (as P)	0.01 mg/L	0.07		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	2.5		<0.05	
Ammonia (as N)	0.05 mg/L	0.10		0.05	
Iron	0.02 mg/L	0.05	0.07	0.04	0.07
Manganese	0.01 mg/L	0.02	0.01	0.01	0.02
Copper	0.01 mg/L	<0.01	<0.01	0.01	0.01
Zinc	0.01 mg/L	0.01	0.01	0.01	0.01
Colour (true)	0.5 T.C.U.	<3		11	
Turbidity	0.1 N.T.U.	2.4		1.1	
Conductivity (25°C)	0.1 umho/cm	740		73	
pH	0.01	8.0		7.5	
Total Organic Carbon	0.5 mg/L	4.7		4.6	
Cation Sum	0.01 meq/L	6.35		0.67	
Anion Sum	0.01 meq/L	6.64		0.69	
Ion Ratio	0.01	0.96		0.97	
% Difference	0.1 %	2.2		1.5	
TDS (ion sum, calc)	0.1 mg/L	384		40	
Conductivity (calc, 25°C)	0.1 umho/cm	729		74	
Saturation pH (4°C)	0.01	7.70		9.49	
Langelier Index (4°C)	0.01	0.30		-1.99	
Bicarbonate(as CaCO ₃)	1.0 mg/L	139		19	
Carbonate(as CaCO ₃)	1.0 mg/L	1.3		0.1	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB.#:882315
 TABLE #1J

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	#R 3		#R 4	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	1.8		1.3	
Potassium	0.1 mg/L	0.6		0.5	
Calcium	0.005 mg/L	9		8	
Magnesium	0.001 mg/L	1.7		1.7	
Hardness (as CaCO ₃)	0.05 mg/L	30		26	
Alkalinity (as CaCO ₃)	1.0 mg/L	21		16	
Sulphate	1.0 mg/L	10		10	
Chloride	1.0 mg/L	3		3	
Silica	0.5 mg/L	1.4		1.4	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	<0.05		<0.05	
Ammonia (as N)	0.05 mg/L	<0.05		<0.05	
Iron	0.02 mg/L	0.04	0.30	0.03	0.04
Manganese	0.01 mg/L	0.01	0.05	0.01	0.01
Copper	0.01 mg/L	<0.01	<0.01	<0.01	<0.01
Zinc	0.01 mg/L	<0.01	<0.01	<0.01	<0.01
Colour (true)	0.5 T.C.U.	12		11	
Turbidity	0.1 N.T.U.	4		0.6	
Conductivity (25°C)	0.1 umho/cm	76		65	
pH	0.01	7.9		7.4	
Total Organic Carbon	0.5 mg/L	4.2		4.1	
Cation Sum	0.01 meq/L	0.70		0.59	
Anion Sum	0.01 meq/L	0.71		0.60	
Ion Ratio	0.01	0.99		0.98	
% Difference	0.1 %	0.7		0.8	
TDS (ion sum, calc)	0.1 mg/L	40		35	
Conductivity (calc, 25°C)	0.1 umho/cm	75		65	
Saturation pH (4°C)	0.01	9.42		9.62	
Langelier Index (4°C)	0.01	-1.52		-2.22	
Bicarbonate(as CaCO ₃)	1.0 mg/L	21		16	
Carbonate(as CaCO ₃)	1.0 mg/L	0.2		0.0	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

GEN-V

CLIENT: GARTNER & LEE ASSOCIATES

REF. NO.: 882315

TABLE: 2

CHEMICAL PARAMETERS - GENERAL

SAMPLE IDENTIFICATION	PHENOLS mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L
H1	<0.002							
H2	<0.002							
H3	0.006							
H4	<0.002							
H5	0.003							
H6	0.003							
H7	0.003							
H8	<0.002							
H9	<0.002							
BH1-D 1-I	<0.002							
BH1-S 1-II	<0.002							
BH2-D 2-I	0.006							
BH3-D 3-II	0.003							
BH4	0.003							
BH5	0.003							
BH6	<0.002							
Q1	<0.002							
R2	<0.002							
R3	<0.002							
R4	<0.002							

QA/QC PROTOCOL

0.0288	0.0275							
TRUE VALUE								
TRUE VALUE								
TRUE VALUE								
MDL								

MDL = INSTRUMENT/METHOD DETECTION LIMIT

NS = NON SUFFICIENT SAMPLE

-- = NO ANALYSIS REQUIRED

MANN TESTING LABORATORIES LTD.



MANN AQUA LABORATORIES LTD.
5550 McADAM ROAD, MISSISSAUGA, ONTARIO L4Z 1P1
PHONE: (416) 890-2555 · TELEX: 06-960496 · FAX: (416) 890-0370

NEW ADDRESS:
UNIT #6
400 MATHESON BLVD. EAST
MISSISSAUGA, ONT. L4Z 1N8

CLIENT: Gartner Lee Limited
140 Renfrew Drive
Markham, Ontario
L3R 8B6

REPORT #: MA01902-1905

CUSTOMER REF.#88-237

ATTN: Mr. Rob Dickin

DATE SUBMITTED: Nov 15/88

-----CERTIFICATE OF ANALYSIS-----

Sample Description: WATER

Preparation: Samples were prepared as recommended in APHA
Standard Methods for the Examination of Water
and Wastewater, 16th Edition, 1985 unless
otherwise noted.

Methodology: Rapid Chemical Analysis program (RCAP)

Chemical Results: See Tables 1A and 1B

Note: If you require further information, please
contact Nora Macnee at (416) 890-2555.

DATE: January 23, 1989

J. Dale

CERTIFIED BY:
Jim Dale, M.Sc.
Manager, RCAP

REPORT TO: GARTNER LEE LIMITED
 PROJECT #:88-237
 LAB. #:MA01902-1903
 TABLE #1A

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	SAMPLE #BH 2-II		SAMPLE #BH 3-II	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	25		25	
Potassium	0.1 mg/L	2.1		23	
Calcium	0.005 mg/L	64		137	
Magnesium	0.001 mg/L	5.7		14	
Hardness (as CaCO ₃)	0.05 mg/L	185		404	
Alkalinity (as CaCO ₃)	1.0 mg/L	199		294	
Sulphate	1.0 mg/L	49		176	
Chloride	1.0 mg/L	3.0		10	
Silica	0.5 mg/L	4.2		5.6	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	0.22		4.6	
Ammonia (as N)	0.05 mg/L	<0.05		<0.05	
Iron	0.02 mg/L	0.03	0.09	0.03	0.97
Manganese	0.01 mg/L	0.03	0.03	0.04	0.13
Copper	0.01 mg/L	0.01	0.01	0.01	0.01
Zinc	0.01 mg/L	0.01	0.01	0.03	0.04
Colour (true)	0.5 T.C.U.	5		<3	
Turbidity	0.1 N.T.U.	13		17	
Conductivity (25°C)	0.1 umho/cm	522		1098	
pH	0.01	8.0		7.6	
Total Organic Carbon	0.5 mg/L	2.0		5.6	
Cation Sum	0.01 meq/L	4.86		9.76	
Anion Sum	0.01 meq/L	5.09		10.12	
Ion Ratio	0.01	0.95		0.97	
% Difference	0.1 %	2.4		1.8	
TDS (ion sum, calc)	0.1 mg/L	396		769	
Conductivity (calc, 25°C)	0.1 umho/cm	505		1080	
Saturation pH (4°C)	0.01	7.77		7.31	
Langelier Index (4°C)	0.01	0.23		0.29	
Bicarbonate(as CaCO ₃)	1.0 mg/L	197		292	
Carbonate(as CaCO ₃)	1.0 mg/L	1.9		1.1	

NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
 EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
 COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
 IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).

REPORT TO: GARINER LEE LIMITED
PROJECT #:88-237
LAB. #:MA01904-1905
TABLE #1B

RCap CHEMICAL PARAMETERS	METHOD DETECTION LIMIT	SAMPLE #BH 4		SAMPLE #SW A	
		Water Soluble	'Total' Metals	Water Soluble	'Total' Metals
Sodium	0.5 mg/L	3.3		10	
Potassium	0.1 mg/L	11		4.0	
Calcium	0.005 mg/L	117		104	
Magnesium	0.001 mg/L	10		3.0	
Hardness (as CaCO ₃)	0.05 mg/L	334		273	
Alkalinity (as CaCO ₃)	1.0 mg/L	321		294	
Sulphate	1.0 mg/L	33		18	
Chloride	1.0 mg/L	1.0		<1.0	
Silica	0.5 mg/L	6.5		4.0	
o-Phosphate (as P)	0.01 mg/L	<0.01		<0.01	
Nitrate + Nitrite (as N)	0.05 mg/L	0.74		<0.05	
Ammonia (as N)	0.05 mg/L	0.09		<0.05	
Iron	0.02 mg/L	0.02	3.20	0.02	0.03
Manganese	0.01 mg/L	0.06	0.28	0.04	0.04
Copper	0.01 mg/L	0.01	0.07	0.01	0.01
Zinc	0.01 mg/L	0.08	0.16	0.01	0.01
Colour (true)	0.5 T.C.U.	<3		5	
Turbidity	0.1 N.T.U.	72		0.6	
Conductivity (25°C)	0.1 umho/cm	766		570	
pH	0.01	7.6		7.7	
Total Organic Carbon	0.5 mg/L	2.0		3.7	
Cation Sum	0.01 meq/L	7.12		5.99	
Anion Sum	0.01 meq/L	7.19		6.24	
Ion Ratio	0.01	0.99		0.96	
% Difference	0.1 %	0.5		2.1	
TDS (ion sum, calc)	0.1 mg/L	576		500	
Conductivity (calc, 25°C)	0.1 umho/cm	708		595	
Saturation pH (4°C)	0.01	7.32		7.41	
Langelier Index (4°C)	0.01	0.28		0.29	
Bicarbonate(as CaCO ₃)	1.0 mg/L	320		292	
Carbonate(as CaCO ₃)	1.0 mg/L	1.2		1.4	


NOTE: ALL RESULTS BASED ON SAMPLE CENTRIFUGED AT 2000 RPM FOR 30 MINUTES
EXCEPT pH, TURBIDITY, CONDUCTIVITY AND 'TOTAL METALS' (IRON, MANGANESE,
COPPER AND ZINC)

ALL RESULTS BASED ON UNPRESERVED SAMPLE AS SUBMITTED EXCEPT FOR
IRON, MANGANESE, COPPER AND ZINC (NITRIC ACID TO pH <2).



MANN TESTING LABORATORIES LTD.

5550 McADAM ROAD, MISSISSAUGA, ONTARIO L4Z 1P1-6827
PHONE: 890-2555 • TELEX: 06-960496 • FAX: (416) 890-0370



CUSTOMER: Gartner Lee Limited
140 Renfrew Drive
Suite 102
Markham, Ontario
L3R 8B6

REPORT #: 883893

CUSTOMER REF. # 88-237

ATTN: Mr. Rob Dickin

DATE SUBMITTED: Nov. 17, 1988

----- CERTIFICATE OF ANALYSIS -----

Sample Description: WATER

Preparation: Samples were prepared as recommended in APHA Standard methods for the examination of water and wastewater, 16th Edition, 1985 or MOE Handbook of analytical methods for environmental samples, 1983.

Note: Additional information is available on request.

Methodology:

Conventionals - wet chemical techniques.

Chemical Results: See Table 1.

DATE: Dec. 21, 1988


CERTIFIED BY:
Jim Forrester,
Manager, Inorganic Dept.

TABLE: 1

CHEMICAL ANALYSIS - GENERAL

CONC = mg/L UNLESS OTHERWISE NOTED

CHEMICAL PARAMETERS	MDL	QA/QC	TRUE	BH2-11	BH3-11	BH4
	(mg/L)	(mg/L)				
	EXP'T					
Phenol	0.002	0.028	0.029(e)	<0.002	<0.002	<0.002

MDL = INSTRUMENT/METHOD DETECTION LIMIT

NS = NON SUFFICIENT SAMPLE

-- = NO ANALYSIS REQUIRED

8- EPA WP 1083

b6 EPA WP 386

c= NBS 1643b

d= EPA WP 1185+WS 378

e= OTHER

ICAP 19/7

TRACE METALS - 1

TRACE ELEMENTS IN WATER

MINERALS +NO3/F-6




MANN TESTING LABORATORIES LTD.

5550 McADAM ROAD, MISSISSAUGA, ONTARIO L4Z 1P1
PHONE: 890-2555 • TELEX: 06-960496 • FAX: (416) 890-0370

CUSTOMER: Gartner Lee Limited
140 Renfrew Drive
Suite 102
Markham, Ontario
L3R 6B3

ENV-003



ATTN: Mr. Rob Dicken

REPORT #: 882319

CUSTOMER REF. #

DATE SUBMITTED: Aug. 25, 1988

DATE REPORTED: Sept. 28/88

----- **CERTIFICATE OF ANALYSIS** -----

Sample Description: WATER

Analysis Performed: VOLATILE ORGANIC ANALYSIS

Protocol based upon U.S. EPA Method #624.
Samples are fortified with isotopically labelled
internal standards and analyzed by purge and trap
gas chromatography/mass spectrometry (PT-GC/MS).

Note: Additional information is available on request.

Instrumentation:

- Envirochem 810 purge and trap concentrator.
- Finnigan 3200 GC/MS-DS.


Chemical Results: See Table V-1.

Nellie Sio

CERTIFIED BY:
Nellie Sio, B. Tech
Project Leader-Volatile Organics

Tim Munshaw

WITNESSED BY:
Tim Munshaw, M.Sc. C. Chem.
Manager, Environmental



* Refer inquiries to.

2319-V-1

VOLATILE ORGANICS

Conc. = (ppb)

GARTNER LEE LIMITED

W.O. #882319

VOLATILE COMPOUNDS	MDL (ppb)	TRAVELLING BLANK	BH-4		
DICHLORODIFLUOROMETHANE	2.0	--	--	--	--
CHLOROMETHANE	2.0	--	--	--	--
VINYL CHLORIDE	2.0	--	--	--	--
BROMOMETHANE	2.0	--	--	--	--
CHLOROETHANE	2.0	--	--	--	--
TRICHLOROFLUOROMETHANE	2.0	--	--	--	--
1,1-DICHLOROETHYLENE	1.0	--	--	--	--
DICHLOROMETHANE	1.0	4.24	--	--	--
1,1,2-DICHLOROETHYLENE	1.0	--	--	--	--
1,1-DICHLOROETHANE	1.0	--	--	--	--
CHLOROFORM	1.0	TR	--	--	--
1,2-DICHLOROETHANE	1.0	--	--	--	--
1,1,1-TRICHLOROETHANE	1.0	--	--	--	--
BENZENE	0.5	TR	TR	--	--
CARBON TETRACHLORIDE	1.0	--	--	--	--
1,2-DICHLOROPROPANE	1.0	--	--	--	--
BROMODICHLOROMETHANE	1.0	--	--	--	--
TRICHLOROETHYLENE	1.0	--	--	--	--
1,3-DICHLOROPROPENE(2)	1.0	--	--	--	--
1,3-DICHLOROPROPENE(E)	1.0	--	--	--	--
1,1,2-TRICHLOROETHANE	1.0	--	--	--	--
TOLUENE	0.5	--	--	--	--
DIBROMOCHLOROMETHANE	1.0	--	--	--	--
TETRACHLOROETHYLENE	1.0	--	--	--	--
CHLOROBENZENE	0.5	--	--	--	--
ETHYL BENZENE	0.5	--	--	--	--
P & M XYLENE	0.5	--	--	--	--
BROMOFORM	1.0	--	--	--	--
O-XYLENE	0.5	--	--	--	--
1,1,2,2-TETRACHLOROETHANE	1.0	--	--	--	--
1,3-DICHLOROBENZENE	1.0	--	--	--	--
1,4-DICHLOROBENZENE	1.0	--	TR	--	--
1,2-DICHLOROBENZENE	1.0	--	--	--	--
CIS-1,2-DICHLOROETHYLENE	1.0	--	--	--	--
SURROGATE % RECOVERY					
4-BROMOFLUOROBENZENE		119.12%	80.81%		

TR = TRACE AMOUNT DETECTED

-- = NONE DETECTED

MDL = METHOD DETECTION LIMIT

ANALYST

W. L. S. O. 1, Sept 28/88

FILE: TR_4653
DATE: 01/12/88
MATRIX: AQUEOUS

GARTNER-LEE LTD (ROB DICKIN)

PKOJ:88-237

UN NO: 88-4653

PAGE: 1

[illegible]